


MODULE - I

DC - MOTORS

DC - motor :-



Principle :- DC motor

- * whenever a current carrying conductor / coil is placed in a magnetic field, it experiences a mechanical force.

* The magnitude of force experienced is given by

$$F = B I l \text{ Newtons}$$

where B = Magnetic flux density - Wb/m^2

I = current flowing through coil/conductor - Amps


l = Active length of conductor


* Significance of back emf (motor)

- : rotation - DC
flinging left hand rule
- : rotation
flinging right hand
generators

Fleming's ~~right~~ ^{left} hand rule -

It is applicable for DC motors





field

\otimes → Current flow Inwards

\emptyset → Current flow Outwards

Motoring action - Interaction of 2 fluxes -
field and armature fluxes lead to

\Rightarrow Significance of back emf (E_b):-

- * In every DC motor, there exists a generating action after the motoring action. Due to this generating action, an emf gets induced in the armature winding / conductor.
- * This induced emf opposes the supply voltage V . due to Lenz's law and is known as the back emf E_b

* Magnitude of E_b is given by

$$E_b = \frac{P \Phi N Z}{60 A}$$

Induced emf in
motor due to
generating action

Φ = flux in Webers


P = No: of poles

(3) N = Speed in revs per armature in rpm

Z = Number of armature conductors

A = No: of parallel paths

⇒ Symbolic representation of a DC-motor :-




Classification of DC-motors:-


↳ 1) DC - shunt motor

↳ 2) DC - series motor

↳ 3) DC - compound motors



↳ 1) DC - shunt motor:-



→ Current relationship

$$I_L = I_a + I_{sh}$$

$$I_L = I_a = I$$

$$I_{sh} = \frac{V}{R_{sh}}$$

$$\phi = I_a \times R_s$$

→ Voltage equation

$$\rightarrow V = E_b + I_a R_a + V_{brush}$$


Generally V_{brush} is neglected

$$V = E_b + I_a R_a$$

→ relation of flux and shunt current

$$\phi \propto I_{sh}$$

↳ 2) DC - series motor



- In DC-series motor field winding has less no. of turns
- In DC-shunt motor field winding has more no. of turns

→ current relationship

$$I_L = I_{se} = I_a$$

→ relation of flux and series current and line current

$$\phi \propto I_{se} \propto I_L \propto I_a$$

→ Voltage equation

$$\rightarrow V = E_b + I_a R_a + I_{se} R_{se} + V_{bush}$$

$$V = E_b + I_a (R_a + R_{se}) \quad \text{neglecting } V_{bush}$$

R_{sh} should be high value

R_{se} should be low value

Voltage drop across Armature should be high & in series

R_a → low value

R_{se} → low value

R_{sh} → high value

$$R \propto \frac{l}{a} \Rightarrow R \propto l \quad ; \quad R \propto \frac{1}{a}$$

∴ R_{sh} - more no. of turns \Rightarrow higher value with thin cross-section (area)

R_{se} - less no. of turns \Rightarrow lower value with thick value (area)


3) Compound motor



(iii) Long Shunt DC compound motor :-

Types of winding

- 1) Armature
- 2) shunt field winding
- 3) series field winding



→ current relationship

$$I_L = I_{se} + I_{sn}$$

$$I_{se} = I_a$$


$$(or) I_L = I_a + I_{sn}$$

→ voltage equation

$$\rightarrow V = E_b + I_a R_a + I_{se} R_{se} + V_{beam}$$

$$V = E_b + I_a (R_a + R_{se}) \quad \text{neglecting } V_{beam}$$

\rightarrow (iii) Show shunt DC compound motor



\rightarrow Current relationship

$$I_L = I_a + I_{sh}$$

$$I_L = I_{se}$$

$$I_{se} = I_a + I_{sh}$$

\rightarrow Voltage equation

$$V = E_b + I_{se} R_{se} + I_a R_a + V_{brush}$$

$$V = E_b + I_{se} R_{se} + I_a R_a \quad \text{neglecting } V_{brush}$$


\Rightarrow Shunt current equation

$$I_{sh} = \frac{V - I_{se} R_{se}}{R_{sh}} = \frac{E_b + I_a R_a}{R_{sh}}$$

$BB\phi - BB\phi$


L \rightarrow (ii) series brushless DC motor :-

Q1)



L \rightarrow (iii) Differential compound DC motors:-


Q2)



Q1) A 4 pole, 250V, DC supply motor has a wave connected armature with 200 conductors. A flux per pole is $\Phi = 25 \text{ mWb}$ when the motor is drawing 60 Amp from the supply.

The armature resistance is 0.15Ω . While the field winding resistance is 0.2Ω . Calculate the speed.

Soln



Given data:-

$$P = 4$$

$$\Phi = 25 \times 10^{-3} \text{ Wb}$$

$$Z = 200$$

$$Ra = 0.15 \Omega$$

$$Rse = 0.2 \Omega$$

$$I_L = 60 \text{ A}$$

$$V = 250 \text{ V}$$

$$A = 2$$

To find:-

$$N = ?$$

* Motor takes a current

(or)

Motor draws a current

\Rightarrow

means line

current I_L is not

I_a

Soh

$$\hookrightarrow E_b = \frac{P \Phi N Z}{60 A}$$

$$= 40 \times 25 \times 10^3$$

$$V = E_b + I_a R_a + I_a R_s$$

Given $V = 250 V$ & $I_a = 3 A$

$$250 = E_b + 3 \times 0.2 + 3 \times 0.15$$

$$E_b = 229 V$$


$$\hookrightarrow N = \frac{E_b \times 60 A}{P \Phi N Z}$$

$$= \frac{229 \times 60 \times 10^{-3}}{4 \times 25 \times 10^{-3} \times 200}$$

$$N = 1374 \text{ rpm}$$

- Q2) A 250V, DC shunt motor takes a line current of 20 Amps. The resistance of shunt field winding is 200Ω and resistance of armature is 0.3Ω. Find the armature current and back emf.

Soln :-



Given data :-

$$I_L = 20A$$

$$R_{sh} = 200\Omega$$

$$R_a = 0.3\Omega$$

$$V = 250V$$

To find :-

$$I_a = ?$$

$$E_b = ?$$

Soln :-

$$I_L = I_a + I_{sh} \Rightarrow I_a = I_L - I_{sh} \rightarrow ①$$

$$I_{sh} = I_L - I_a \rightarrow ②$$

$$V = I_{sh} R_{sh}$$

$$I_{sh} = \frac{V}{R_{sh}}$$

$$= \frac{250}{200}$$

$$\text{But } I_{sh} = 1.25 \text{ Amps} \rightarrow ③$$

Sub ③ in ①

$$I_a = I_L - I_{sh} = 20 - 1.25 = 18.75 \text{ Amps}$$

$$V = E_b + I_a R_a$$

$$E_b = 250 - 18.75 \times 0.3$$

$$E_b = 244.375 V$$

$$\text{II } (P_2 \text{ i/p - losses}) \text{ II } (i(P_2 \text{ o/p + losses})$$

→ Power equation of Dc motor :-

Consider a Dc shunt motor whose voltage equation is given by

$$V = E_b + I_a R_a$$

Multiply both sides by current I_a

$$V I_a = E_b I_a + I_a^2 R_a$$

Power eqn of Dc motor

where $V I_a$ = Power input to the armature in watts


$I_a^2 R_a$ = Power loss in armature in watts

$E_b I_a$ = Electrical equivalent of gross mechanical power developed
(power output)

→ Torque equation of a Dc motor :-

The turning and twisting movement of force about a particular axis is called torque.

Consider a wheel of radius 'R' rotated upon by a circumferential force 'F' newtons



Let the wheel rotate at 'N' rpm

ii) The angular speed is given by

$$\omega = \frac{2\pi N}{60} \text{ rad/sec}$$

Power developed

iii) Work done is given by

$w = \text{Force} * \text{distance travelled}$

$$= F * 2\pi R \text{ N-m}$$

iii) Power developed is given by -

$$P = \frac{\text{workdone}}{\text{Time taken (in sec)}}$$

$$P = \frac{F * 2\pi R}{\left(\frac{60}{N}\right)}$$

$$P = (F * R) \left(\frac{2\pi N}{60} \right)$$

$$P = (F \times R) \times w$$

$$\boxed{P = T \times w}$$

$$\text{when torque } T = F \times R$$

when the speed of armature is
 $'N'$ rpm

$E_b I_a$ = Electrical equivalent of mechanical power developed in armature.

but T_a = the torque developed in the armature

$$\therefore P = T_a \times w$$

$$E_b I_a = T_a \times \left(\frac{2\pi N}{60} \right)$$

Table

$$w \cdot k_t \quad E_b = \frac{P \Phi N Z}{60 A}$$


$$\frac{P \Phi N Z}{60 A} I_a = T_a \times \frac{2\pi N}{60}$$

$$T_a = \frac{1}{2\pi} \frac{\Phi P Z}{A} I_a = \underline{\underline{0.159 P \Phi Z I_a}} / A$$

$$\boxed{T_a = \frac{1}{2\pi} \frac{P \Phi Z I_a}{A}} \quad - \text{Nm}$$

→ Types of Torque in a DC motor :-

• mechanical torque goes with motor needs.




- The entire armature torque (T_a) developed in the armature is not transmitted to the load because there are some losses i.e., friction and windage losses at the shaft (coupling) known as lost torque - T_f
- The useful torque available to the mechanical load at the end of the end of the shaft is called shaft torque - T_{sh}

$$[T_{sh} < T_a] \rightarrow (\text{Due to loss})$$

- i) Armature torque
- ii) lost torque → Friction loss
- iii) shaft torque → windage loss
- iv) shaft torque

Q) A 200V, 4 pole, shunt wound DC T shunt motor has 800 armature conductors. $R_a = 0.5 \Omega$ and $R_m = 200 \Omega$. The motor takes a current of 21 Amps, the flux/pole is 30mWb. and rotates at 175 rpm. Find gross torque developed in the armature.

Soln



Given :-

$$\Phi = 30 \times 10^{-3} \text{ Wb}$$

$$N = 175 \text{ rpm}$$

$$\text{Lap} = A = P = 4$$

$$Z = 800$$

To find :- $T_a = ?$

$$T_a = \frac{P\phi Z I_a}{2\pi A}$$

$$I_L = I_a + I_{sh}$$

total current is sum of individual currents

$$\rightarrow I_{sh} = \frac{V}{R_{sh}}$$

shunt branch voltage is equal to source voltage

$$= \frac{200}{200}$$

shunt branch current is equal to source current

$$I_{sh} = 1 A$$

$$B = \frac{\mu_0 \cdot I}{2\pi r}$$

$$\rightarrow I_L = I_a + I_{sh}$$

$$I_a = 20 A$$

$$T_a = \frac{\mu_0 Z I_a}{4 \cdot 2\pi A}$$

torque formula for direct connection

$$= 4 \times 30 \times 10^{-3} \times 800 \times 20$$

torque formula in N-m

$$T_a = \underline{\underline{76.39 \text{ N-m}}}$$

torque unit is N-m

$$= \underline{\underline{76.39 \text{ N-m}}}$$

newton-meters

\Rightarrow Speed and Torque equations :-

W.K.T General torque expression is -

$$\rightarrow T_a = \frac{1}{2\pi A} * P \Phi Z I_a \text{ N-m}$$

$$T_a \propto \Phi I_a \rightarrow ①$$

because $\frac{1}{2\pi}, P, A, Z$ are all constant

For DC sh

1) \rightarrow For DC shunt motor:- (constant Φ flux machines)
as I_a is const $\rightarrow \Phi$ is also const

As long as the supply 'V' remains constant,

I_{sh} also remains constant and Φ value
remains constant ($\Phi \propto I_{sh}$)

Thus DC shunt motors are also called
constant flux machines

$$T_a \propto I_a$$

Application:-

\rightarrow Used for moderate starting torque applications

2) \Rightarrow For DC series motor : $\text{Torque} \propto I_a^2$ \leftarrow

WKT

$$I_r = I_{se} = I_a$$

Now

$$\phi \propto I_{se}$$

$$\Rightarrow \phi \propto I_a$$

$$T_a \propto \phi I_a$$

from eqn ①

$$T_a \propto I_a + I_a$$

$$T_a \propto I_a^2$$

\Rightarrow Speed equations :-

WKT

$$E_b = \frac{\phi P N Z}{60 A} \text{ Volts}$$

$$E_b \propto \phi N$$

because $P, Z, 60, A$ are all constants

$\therefore \Rightarrow$

$$N \propto \frac{E_b}{\phi}$$

$\rightarrow ②$

\Rightarrow For DC shunt motors :- $\leftarrow (6)$

W.K.T ϕ remains constant

$$N \propto E_b$$

$$\left\{ \begin{array}{l} V = E_b + I_a R_a \\ \end{array} \right.$$

from voltage equations

$$N \propto (V - I_a R_a)$$

\Rightarrow For DC series motor :-

$$N \propto \frac{E_b}{I_a}$$

from eqn(2)

$$\phi \propto I_a$$

$$\left\{ \begin{array}{l} V = E_b + I_a (R_a + R_s) \\ \end{array} \right.$$

From voltage equations

$$N \propto \left\{ V - \frac{I_a R_a + I_{se} R_{se}}{I_a} \right\}$$

$$E_p \propto \phi$$

$$\left[\frac{\partial E_p}{\partial \phi} \propto N \right] \leftrightarrow \text{eqn 2}$$

-? Newer motors have large (←)

⇒ Characteristics of DC motors :-

(a) (b) (c)

- 1) Torque versus armature current (T_a vs I_a) :-
 - ↳ Electrical characteristic (also called)
- 2) Speed versus armature current (N vs I_a)
- 3) speed versus Torque (N vs T_a)
 - ↳ Mechanical characteristic (also called)

↳ Characteristics of DC shunt motors :-


1) Torque versus armature current :-

T_a vs I_a

W.O.K.T

$T_a \propto I_a$

Shunt motor can be started
on no load
• small motor requires
load to start



T_a - armature torque

T_{sh} - shaft torque

$T_{a0} \rightarrow$ No load armature torque


$I_{a0} \rightarrow$ No load armature current

\hookrightarrow Speed versus armature current :-

\therefore motor \propto Φ N (law) \leftarrow

(N vs I_a)

- $\frac{dN}{dT} \propto \text{constant}$ \therefore speed \propto current (c)



$$N \propto \frac{E_b}{\Phi} \quad \therefore \text{torque constant} \propto \frac{N}{\Phi} \quad \text{AT} \propto \frac{N}{\Phi}$$

$$N \propto V - I_a R_a$$

$R_a \rightarrow$ is very small (\propto) negligible

$\therefore I_a R_a$ is also negligible

$$N \propto \propto V$$

Since supply voltage V is constant,


N is also remains constant

$$N_o = N_o \text{ no load speed}$$

(AT)

motor load $\propto -\alpha T$

motor torque $\propto -T$




motor torque $\propto -T$

motor torque $\propto -kT$

\hookrightarrow Speed versus Torque :-

$$(N \propto T_a)$$




Since $T_a \propto I_a$

(Graph of N vs T_a is similar to N vs I_a)

\hookrightarrow Characteristics of DC series motors :-

\hookrightarrow 1) Torque versus armature current :-

$$(T \propto I_a)$$



W. K. T

$$Ta \propto Ia^2$$

After the point of saturation $T_a \propto I_a$
 i.e., It behaves as a shunt motor

T_f - lost torque

Ten - Shaff- Tolu


Ta - Alternaria foliae

Tao -

Iao -

↳) Speed versus armature current :-

(N VI Ia)



$$N \propto \frac{E_b}{\phi}$$

~~Now because ϕ is constant~~

$$N \propto \frac{V - I_a R_a - I_s e R_{se}}{I_a}$$

R_a & R_{se} are low values $\Rightarrow \frac{E_b}{\phi} \propto N$

$\therefore I_a R_a$ and $I_s e R_{se}$ are neglected

$$N \propto \frac{V}{I_a}$$

$V = \text{constant}$

$$N \propto \frac{1}{I_a} \quad \frac{V \times N}{\phi} \quad \frac{1 \times N}{\phi}$$

L3) Speed versus Torque :-

(N vs T_a)

N (rps)

$$J = I_a T_a$$



because J is very large, angular acc.
 (initially motor obtain its torque, but at
 after some time load also obtain torque $\propto T_a$ (N-m))

Work done per revolution $= T_a \times I_a^2$

$$\frac{1}{\phi} I_a \propto \sqrt{T_a}$$

$$\rightarrow N \propto \frac{1}{I_a} \Rightarrow N \propto \frac{1}{\sqrt{T_a}}$$

Representation

Series motor are always started with load

$$N \propto \frac{E_b}{\Phi} \rightarrow \text{general eqn}$$


$$N \propto \frac{V - I_a R_a - I_{se} R_{se}}{\Phi}$$

$I_a R_a$; $I_{se} R_{se} \rightarrow \text{negligible}$

$$N \propto \frac{V}{\Phi}$$

$\{V - \text{constant}\}$

$$N \propto \frac{1}{\Phi}$$



- * The minimum current which is required to just start the motor (start the motor) is called no load current which is very-very small

If I_{ao} - no load current is very small

speed is high $N \propto \frac{1}{\Phi} \propto \frac{1}{I_a}$ $I_a \downarrow \text{now}$

$I_o \downarrow, \Phi \downarrow \rightarrow N \uparrow$ (motor's speed)

If there is load \rightarrow current (~~no load~~)
(not-no-load)

Io decreased \therefore speed

current increase, flux also increases,
speed decreases

$$I^P; \Phi \uparrow; N \downarrow$$

DC series motor should never be

started on no-load.

\Rightarrow WKT

$$N \propto \frac{E_b}{\Phi}$$

$$N \propto \frac{(V - I_a R_a - I_{se} R_{se})}{\Phi}$$

$$N \propto \frac{V}{\Phi}$$

$$\therefore N \propto \frac{1}{\Phi}$$

(V is constant)

For DC series motor

l) On no-load $\rightarrow I_o$ is less, the flux Φ

is less, \rightarrow speed is high (dangerous high speed)

$$I_o \downarrow \rightarrow \Phi \downarrow \rightarrow N \uparrow$$

2) On load $\rightarrow I$ is greater, flux
increases and speed decreases

$$I \uparrow, \Phi \uparrow; N \downarrow$$

(book) truck \leftarrow load is 200 ft \Rightarrow
 (load - fan)

\Rightarrow Applications of DC-motors:-

Type of motor	Characteristics	Applications
DC shunt motor	- Speed is fairly constant and - Medium starting torque	Fans, blowers, centrifugal pumps, lathe machines, drilling machines, machine tools...etc
DC - series motor	- High starting torque, variable speed - No load condition is dangerous	Cranes, elevators, rollings, conveyor belts, marine locomotives and traction
cumulative compound motor	- High starting torque, - No load condition is allowed	Rolling mills, elevators, lifts...etc (For bidirectional application - lifts)
Differential compound motor	Speed increases as the load increases	Not suitable for any practical application

Differential compound motor

$$I_L = I_a + I_{sh}$$

$$\Phi_{sh} - \Phi_{se}$$

$$(\Phi_{sh} - \Phi_{se}) \downarrow$$

$$\uparrow N \propto \frac{E_b}{\Phi} \downarrow$$

In $\Phi_{se} \rightarrow$ I current is more \rightarrow Φ_{se} will be more
Due to more $\Phi_{se} \Rightarrow$ Difference of $(\Phi_{sh} - \Phi_{se})$

decreases

thus less

speed increases

→ Factors affecting speed of a DC motor:-

WKT

$$N \propto \frac{E_b}{\Phi}$$

Say

$$N \propto \frac{V - I_a R_a}{\Phi}$$

$$\therefore N \propto \frac{V}{\Phi}$$

as $E_b \approx V$ [approximately equal to V]

Factors affecting the speed are -

↳ (i) Flux (Φ)

↳ (ii) Voltage across the armature

↳ (iii) Supply voltage (V)

→ Depending on these factors, the various methods of speed control are -

↳ (i) Flux control method :-

By changing the flux Φ , by controlling the current through field winding


↳ (ii) Rheostatic control :- (or) Armature voltage control :-

changing the armature path resistance when we change the voltage across the armature.

↳ (iii) Voltage control method :- (or) Rheostatic load control method :-
changing the applied voltage

→ Speed control of DC shunt motors :-

↳ (i) Film control method :-



As disksta ↑

the longer
Rheostat

I_{sh} decreases

so Φ_{sh} decreases

$$\uparrow N \propto \frac{E_b}{\Phi}$$


∴ N increases

Disadvantages

Speed cannot
be decreased in
this type of control
method

[i.e., below the
rated speed]

↳ N Vs I_{sh} :-



$$I_{sh} \propto \frac{V}{R_{sh}}$$

as R_{sh} ↑ → I_{sh} ↓

as I_{sh} ↓ → Speed N ↑


→ Advantages :-

- Speed control above rated speed is possible.
- It provides smooth and easy control.
- As field current is low, the rheostat required is small.
Thus the power loss in the rheostat is also less.

→ Disadvantages :-

- Speed control below the normal rated speed is not possible.

Lⁱⁱⁱ) Rheostatic control (or) Armature voltage control :-




as $R_n \uparrow \rightarrow$, drop across $I_a R_x$ increases \uparrow

→ Due to $I_a R_a \rightarrow$ voltage drop decreases \downarrow

In this method voltage can only be decreased \rightarrow ~~Ammeter~~ Voltage across armature is reduced.

→ N vs Va




-? Motions A -




-? Motions D -

18/2/2017

→ (iii) → (i) Potential divider control :-



- basen avna speed control (iii)





→ Advantages:-

- Easy and smooth speed control below normal speed is possible

→ Disadvantages:-

- As the entire I_a passes through the internal resistance there is high power loss
- Rheostat required is of large size.
- Speed control above the rated speed is not possible

L iii) Supply / Applied voltage control method:-



Advantages

- Wide range of speed control by suitable arrangement in the field or armature circuit.

- Speed control in both directions can be achieved
- Uniform acceleration

Disadvantages

- This arrangement is expensive
- Overall efficiency is low

→ Steps to solve problems

$$1) T_a \propto \Phi I_a$$

$$2) N \propto \frac{E_b}{\Phi}$$

Problems

- Q1) A 230 volt, DC shunt motor with an armature resistance $R_a = 0.04 \Omega$, is excited to give constant field current. The motor runs at 500 rpm at full load and takes armature current of 30 Amps if an external resistance of 101.52Ω (R_x) is placed in the armature circuit. Find (i) full load torque (ii) full load speed

Soln :-

Given :-

$$V = 230 \text{ V}$$

$$R_a = 0.4 \Omega$$

$$R_{ba} = \dots$$

$$I_{a1} = 30 \text{ A}$$

$$R_x = 101 \Omega$$

$$N_1 = 500 \text{ rpm}$$

To find:- $N_2 = ?$ under full load torque condition

$$\underline{T_{a1}} = \underline{T_{a2}}$$

Then $T_a \propto \Phi I_a$ [constant general torque condition]

$T_a \propto I_a$ [shunt motor]

$\hookrightarrow T_{a1} \propto I_{a1}$ $\therefore I_{a1} = 30 \text{ A}$

$\hookrightarrow T_{a2} \propto I_{a2}$ $\therefore I_{a2} = ?$

$I_{a1} = I_{a2} = 30 \text{ A}$ [from above eqn]

$N \propto \frac{E_b}{\Phi}$ $\therefore N = ?$ [general eqn]

$N \propto E_b$ [$\Phi = \text{constant}$]

$$N_1 \propto E_{b1} \rightarrow ①$$

$$N_2 \propto E_{b2} \rightarrow ②$$

Taking ratio of ① and ②

$$\frac{N_1}{N_2} = \frac{E_{b1}}{E_{b2}}$$

* $\rightarrow E_{b1} = V - I_{a1} R_a$

* $\rightarrow E_{b2} = V - I_{a2} (R_a + R_x)$



* $\rightarrow E_{b1} = 230 - 30 * 0.04$
 $= 218 \text{ V}$

* $\rightarrow E_{b2} = 230 - 30 (0.04 + 1.0)$
 $= 185 \text{ V}$

$$\frac{N_1}{N_2} = \frac{E_{b1}}{E_{b2}}$$

$$N_2 = \frac{500 * 185}{218}$$

$$N_2 = 424 \text{ rpm}$$



Q) iii) Under 105 times full load torque

$$T_{a2} = 105 T_{a1}$$

$$\bar{T}_a \propto I_a$$

$$\rightarrow T_{a1} \propto I_{a1} \rightarrow ①$$

$$\rightarrow T_{a2} \propto I_{a2} \rightarrow ②$$

Takes from ① and ②

$$\frac{T_{a1}}{T_{a2}} = \frac{T_{a1}}{I_{a2}}$$

$$\frac{\bar{T}_a}{105 \bar{T}_{a1}} = \frac{\bar{T}_{a1}}{I_{a2}}$$

$$I_{a2} = 105 I_{a1}$$

$$= 105 \times 30$$

$$I_{a2} = 45 \text{ Amps}$$

$$\hookrightarrow E_{b1} = V - I_{a1} R_a$$

$$= 230 - (30 \times 0.04)$$

$$= 218$$

$$\hookrightarrow E_{b2} = V - I_{a2} (R_a + R_x)$$

$$= 230 - 45 (0.04 + 0.01)$$

$$= 162.5 V$$

$$\frac{N_1}{N_2} = \frac{E_{b1}}{E_{b2}}$$



$$\frac{500}{N_2} = \frac{218}{16205}$$

$$N_2 = \underline{\underline{372070 \text{ rev}}}$$

≈

$$N_2 = \underline{\underline{373 \text{ rpm}}}$$

Q2) A DC shunt motor runs at 1000 rpm on 200V supply, $R_a = 0.8 \Omega$ and the current taken is 40 Amps in addition to the field current. What resistance must be connected in series with armature to reduce the speed to 600 rpm, the armature torque remaining the same.



Given

$$V = 200 \text{ V} ; N_1 = 1000 \text{ rpm}$$

$$R_a = 0.8 \Omega ; N_2 = 600 \text{ rpm}$$

$$I_a1 = 40 \text{ A}$$

$$\parallel \quad T_{\alpha_1} = T_{\alpha_2}$$

To find :-

$$R_x = ?$$

\Rightarrow General torque van

$$T_a \propto \phi I_a$$

T_a & T_b

(De gheen motor
Q = constant)

$$^o \rightarrow T_{a_1} \times I_{a_1}$$

• $\hookrightarrow \text{Tag} \times \overline{\text{Tag}}$ mit den entsprechenden Aktionen A (§5)

$$\text{Btu} \cdot ^\circ\text{F} / \text{hr} = \frac{\text{Btu}}{\text{hr}} \cdot \text{Temp difference}$$

$$I_{A_1} = I_{A_2} = 10 \text{ Amps}$$

$N \propto \frac{E_\phi}{\Phi}$ where ϕ is constant

N. A. Ash

$$N \propto E_b$$

• $\hookrightarrow \text{Ni} \otimes \text{FeI}$

$\rightarrow N_2 \times E_{D2}$

To ① ÷ ② after finding A (e)

$$\frac{N_1}{N_2} = \frac{E_{b1}}{E_{b2}}$$

$$\rightarrow E_{b1} = V - I_{a1} R_a \text{ less with no feedback}$$

$$= 200 - (40 \times 0.8) \text{ more open loop gain}$$

$$= 168 \text{ V}$$

$A_{v1} = 0.8$ - less with no feedback

$$\rightarrow E_{b2} = V - I_{a2}(R_a + R_x)$$

$$= 200 - 168 = 32 \text{ V}$$

$$\hookrightarrow \frac{1000}{600} = \frac{168}{E_{b2}} \rightarrow E_{b2} = 100.8 \text{ V}$$

$$100.8 = 200 - 40(0.8) - 40 \times R_x$$


$$R_x = 200 - 40 \times 0.8 - 100.8$$

$$R_x = 16.8 \Omega$$

—

Q3) A 230V Dc shunt motor runs at 800 rpm and takes armature current of 50 Amps. Find the resistance to be added in the field circuit to increase the speed from 800 rpm to 1000 rpm, at an armature current of 80 Amps. Assume gear proportion to field current. $R_a = 0.15 \Omega$ and $R_{sh} = 250 \Omega$

Soln



Given

$$V = 230$$

$$R_a = 0.15 \Omega$$

$$\Phi_a \propto I_{sh} \propto I_f$$

$$R_{sh} = 250 \Omega$$

$$I_{a1} = 50A$$

$$I_{a2} = 80A$$

$$N_1 = 800 \text{ rpm}$$

$$N_2 = 1000 \text{ rpm}$$

To find: $R_x = ?$

→ Tharsh & Ia

→ VR.

$$\rightarrow I_{bh1} = \frac{V}{R_m}$$

$$I_{bh1} = \frac{250}{23\phi}$$

$$I_{bh1} = \underline{\underline{0.92A}}$$

$$\rightarrow E_{b1} = V - I_{a1} R_a$$

$$= 230 - 50 \times 0.15$$

$$E_{b1} = \underline{\underline{222.5 V}}$$

$$\rightarrow E_{b2} = V - I_{a2} R_a$$

$$E_{b2} = 230 - 80 \cancel{R_a} \times 0.15$$

$$E_{b2} = \underline{\underline{218 V}}$$

Note :-

As load condition is not given,
KVL equation cannot be used

$$\rightarrow N \propto \frac{E_b}{\phi}$$

given
 $\{\phi \propto I_{gh} \propto I_f\}$

$$\rightarrow N \propto \frac{E_b}{I_{gh}}$$

$$\bullet \rightarrow N_1 \propto \frac{E_{b1}}{I_{gh1}} \quad \text{①}$$

$$\bullet \rightarrow N_2 \propto \frac{E_{b2}}{I_{gh2}} \quad \text{②}$$

$$\text{①} \div \text{②}$$

$$\frac{N_1}{N_2} = \frac{E_{b1}}{I_{gh1}} * \frac{I_{gh2}}{E_{b2}}$$

$$\frac{800}{1000} = \frac{2205}{0.92} * \frac{I_{gh2}}{218}$$

$$I_{gh2} = 0.72 \text{ Amps}$$

Ohms law

$$\rightarrow V = I_{gh2} (R_x + R_{th})$$

$$I_{gh}$$

$$230 = 0.72 R_x + 0.72 * 250$$

$$R_x =$$

$$R_x = \frac{230 - 0.72 \times 250}{0.72} \Omega$$

$$R_x = 69.0 \Omega$$

\Rightarrow Speed control of DC series motor :-

L1) Field control


Note :-

The flux produced by a winding depends on the mmf (magnetic motor force) which is a product of current and no. of turns of the winding.

$$mmf = NI \quad \text{Amp 1 turn}$$



L1) Field control method

L2) (a) Field converter method :-



~~R~~

$\rightarrow N \propto I_a$ (as $I_{se} \propto I_a$) \bar{I}_a




$I_{se} \propto \frac{1}{\phi} \rightarrow \phi \downarrow \rightarrow N \uparrow$

- Speed control above rated speed cannot be done.

- As flux cannot be decreased,

As resistance R_x increases current through Rheostat decreases and the armature current (I_a) increases

b) Armature diverter method :-



As \rightarrow Load $\uparrow \rightarrow I_a \uparrow \rightarrow \phi \uparrow \rightarrow N \downarrow$

\rightarrow When the armature current is diverted through R_x thus reducing it.

Now w.k.t

$$T_a \propto \phi I_a \quad \text{and since } M_h$$

load torque remains constant, the motor draws more current from the supply. Thus the current I_a through the series field winding increases \rightarrow so does the flux increase.


Thus speed decreases

$\rightarrow I_a \downarrow \rightarrow T$ should remain constant \rightarrow

$$I_s \uparrow \rightarrow I_{se} \uparrow \rightarrow \phi \uparrow \rightarrow N \downarrow$$

thus N decreases due to diversion.

\hookrightarrow e) Tapped field method :- A (a) \leftarrow



- In this method, the change in flux is achieved by changing the no% of turns of the field winding.
- The field winding is provided with no: of steps and a selector switch 'S' to select the no: of turns (steps) as per requirement
 - when S is in position 1 \rightarrow entire winding is included \rightarrow no: of turns is more \rightarrow flux is high \rightarrow speed decreases

$S \rightarrow 1 \rightarrow$ No: of turns $\uparrow \rightarrow \phi \uparrow \rightarrow N \downarrow$

$S \rightarrow 2 \rightarrow$ No: of turns $\downarrow \rightarrow \phi \downarrow \rightarrow N \uparrow$

$S \rightarrow 3 \rightarrow$ No: of turns $\downarrow \downarrow \rightarrow \phi \downarrow \downarrow \rightarrow N \uparrow$



(ii)

(iii)

Lecture 2: D.C. Motor Speed Control

b2) Rheostatic control (or) Armature voltage control

control method :-



(i) Without R_x

$$N \propto \frac{1}{\Phi}$$

$$\Phi \propto I_{se}$$

(ii) With R_x


$$N \propto V$$

$$N \downarrow \Rightarrow V \downarrow$$

$$(N \propto E_b / \Phi \Rightarrow N \propto \Phi)$$

$V \rightarrow \downarrow \rightarrow$ due to voltage drop
as R_x is added $I_a \downarrow$
 $\therefore V \uparrow$

→ 3) Applied voltage control method :-



→ For the voltage obtained from the generator is controlled by a field converter resistance connected across series field winding of generator.

- This gives variable voltage at the output terminals of the generator by which various speeds of DC shunt motor can be obtained.

⇒ Necessity of a starter :-

Consider a DC shunt motor -

$$V = E_b + I_a R_a$$

At start, $N = 0$

then $E_b = 0$



$$V = 0 + I_a R_a$$

$$V = I_a R_a$$

$$I_a = \frac{V}{R_a}$$

$$w \cdot K_t$$

$$N \propto \frac{E_b}{\Phi}$$

$$N \propto E_b$$

$$N \propto \frac{1}{\Phi}$$

Eg:-

$$V = 220V$$

$$\text{say } R_a = 0.8\Omega$$


$$I_a = \frac{220}{0.8} = \approx 300 A$$

The current at start is approximately 10-20 times the rated current of the motor. This high value of starting current can damage the motor, in specific the armature winding since the value of ~~open~~ R_a is very low.

⇒ Starter :-


A starter is a safety device which is used to safely start a motor by limiting high starting current.

→ Three point starter :-



28/2/2017

Lot of new terms used so NEED TO TRY




[Nc and se field winding are in parallel]

(Q1) A d.c. shunt motor has a total

resistance of 10.5Ω and runs at 750 rpm
at 220 V supply with a current of 20 Amps .

Find the speed at which it will run when connected in series with a 40.5Ω resistance
and taking the same current.

Soln



Given

$$N_1 = 750 \text{ rpm}$$

$$I_{L1} = 20A$$

$$V = 220V$$

$$R_a + R_{se} = 105\Omega$$

To find :-

$$N_2 = ?$$

Soln

$$N \propto \frac{E_b}{\phi}$$

For series connection $\phi \propto I_a (on) I_{L1} (on) I_{se}$

$$N_1 \propto \frac{E_{b1}}{I_{L1}} \quad \text{and} \quad N_2 \propto \frac{E_{b2}}{I_{L2}}$$

$$I_{L1} = I_{L2} = 20A$$

$$\rightarrow E_{b1} = V - I_a (R_a + R_{se})$$

$$= 220 - 20(105)$$

$$= 190V$$

$$\rightarrow E_{b2} = V - I_a (R_a + R_{se} + R_s)$$

$$= 220 - 20(105 + 405)$$

$$= 100V$$

$$\frac{N_1}{N_2} = \frac{E_{b1}}{I_{L1}}$$

$$N_2 = \frac{E_b}{I_{L2}}$$

$$\frac{N_1}{N_2} = \frac{E_{b1}}{E_{b2}} \times \frac{I_{L2}}{I_{L1}}$$

$$\Rightarrow N_2 = \frac{750 \times 790}{100} \times \frac{N_1 \times E_{b2}}{E_{b1}}$$


$$N_2 = \frac{750 \times 100}{190}$$

$$= 394.73$$

$$\underline{N_2 \approx 395 \text{ rpm}}$$

- (Q2) A 200V, DC series motor drives a load at a certain speed and takes a current of 30Amps. The resistance across terminals is 1.5Ω . Find the external resistance to be added in series with motor circuit to reduce speed to 60% of its original value. Assume torque produced is proportional to cube of speed.

John



Given

$$I_L \rightarrow I_{A1} = 30A$$

$$R_a + R_{sh} = 10\Omega$$

$$N_2 = 60\% N_1$$

$$\Rightarrow N_2 = 0.6 N_1$$

$$T \propto N^3$$

To find :-

$$R_x = ?$$

reduced by 60%

$\therefore 60\% N_1$

John

$$T_a \propto \Phi I_a$$

$$T_a \propto I_a^2 \rightarrow \text{for DC series motor}$$

$$T_{a1} \propto I_{a1}^2 \quad \text{①}$$

$$; \quad T_{a2} \propto I_{a2}^2 \quad \text{②}$$

$$\frac{T_{a1}}{T_{a2}} \Rightarrow \frac{I_{a1}^2}{I_{a2}^2} \rightarrow (3)$$


$$T_{a1} \propto N_1^3 \quad \text{and} \quad T_{a2} \propto N_2^3$$

↳ (4)

[Given]

$$\frac{T_{a1}}{T_{a2}} \Rightarrow \frac{N_1^3}{N_2^3} \rightarrow (b)$$

Equate (3) and (b)



$$\frac{I_{a1}^2}{I_{a2}^2} \Rightarrow \frac{N_1^3}{N_2^3}$$

$$\frac{I_{a1}^2}{I_{a2}^2} = \frac{(N_1)^3}{(0.6 N_1)^3}$$

$$\frac{(30)^2}{I_{a2}^2} = \frac{1}{0.0216}$$

$$I_{a2}^2 \Rightarrow 19404$$

$$I_{a2} = 13.94 \text{ Amps}$$

$$N \propto \frac{E_b}{\Phi}$$

$$N_1 \propto \frac{E_{b1}}{\Phi_1} ; N_2 \propto \frac{E_{b2}}{\Phi_2}$$

$$N_1 \propto \frac{E_{b1}}{I_{a1}} \quad ; \quad N_2 \propto \frac{E_{b2}}{I_{a2}} \quad (8)$$

$$\frac{N_1}{N_2} = \frac{E_{b1}}{I_{a1}} \times \frac{I_{a2}}{\frac{1}{100} E_{b2}}$$

$$E_{b2} = \frac{0.06 N_1}{0.06 N_1} \times \frac{E_{b1} \times I_{a2}}{I_{a1}}$$

$$\rightarrow E_{b1} = V - I_{a1}(R_a + R_{se})$$

$$= 200 - 30(105)$$

$$\approx 155$$

$$\rightarrow E_{b2} = \frac{155 \times 13.94 \times 0.06}{0.06 \times 30}$$

$$= 43.021 V$$

$$\rightarrow E_b = V - I_{a2}(R_a + R_{se} + R_x)$$

$$43.021 = 200 - 13.94 (105 + R_x)$$

$$R_x = \frac{200 - 43.021 - 13.94 \times 105}{13.94} = 9.074 \Omega$$

→ Losses and Efficiency :-

Losses present in a DC motor are

- 1) Copper losses (or) Variable losses - P_{cu}
 - 2) Friction losses
 - 3) Mechanical losses
 - 4) Iron losses
- ↳ 1) Copper loss :-

Variable losses
- It is also called I^2R losses where

current I is the variable parameter

and generally R remains constant.
(It takes place in winding/iron material)

↳ 2) Iron losses :-

Constant losses (or) Magnetic losses

Denoted as by ' P_i '

(It takes place in core - i.e. magnetic material)

↳ (iii) Hysteresis losses :-

Rapid cycles of magnetisation and demagnetisation

To reduce hysteresis losses use a very good magnetic material with low

↳ iii) Early current losses :-

The uncontrolled flow in the unwanted positions of the core is called eddy currents.

The To reduce eddy eddy current loss -
laminated construction of core is used.

↳ 3) Mechanical losses :-

These losses are also called as windage


(04) functional losses

constant-loss (low) Magnetic losses + Mechanical losses \rightarrow Stray losses (constant \rightarrow)

Total losses % :-

Total loss = constant losses + variable losses

\Rightarrow Power flow diagram :- for DC motor



\rightarrow Efficiency % - what is efficiency (%)

$$\% \text{ Efficiency} = \frac{P_{\text{out}}}{P_{\text{in}}} * 100$$

for motor

$$\% \eta_m = \frac{P_{\text{in}} - \text{total loss}}{P_{\text{in}}} * 100$$

for generator

$$\% \eta_g = \frac{P_{\text{out}}}{P_{\text{out}} + \text{loss}} * 100$$

motor
electrical
o/p power
generator
electrical
o/p power

\rightarrow condition for maximum efficiency:-

mechanical is constant
or variable whereas
electrical watt is always
constant so using lotus

consider a DC generator

$$\text{let } P_{\text{out}} = VI$$

$$P_{\text{ew}} = \text{variable loss} = I^2 R_a$$

$$P_i = \text{constant loss}$$

$$\therefore \% \eta = \frac{P_{\text{out}}}{P_{\text{out}} + P_{\text{ew}} + P_i} * 100$$

$$= \frac{VI}{VI + I^2 R_a + P_i}$$

Efficiency
losses
constant
power
 $IV = \text{losses}$

∴ both numerator and denominator by
 \sqrt{I}

reduced 0.061 last notes true 00

$$\% \eta = \frac{\sqrt{I}}{\sqrt{I} + \frac{I^2 R_a}{\sqrt{I}} + \frac{P_i}{\sqrt{I}}}$$

now in $\frac{\sqrt{I}}{\sqrt{I}}$ neg sign bro positive

$\% \eta_{\text{max}} = \left[1 + \frac{I R_a}{\sqrt{I}} + \frac{P_i}{I \sqrt{I}} \right] * 100$

now in $\frac{I R_a}{\sqrt{I}}$ neg sign in pd

For efficiency to be maximum, the denominator should be minimum according to Maxima minima theorem

$$\therefore \frac{d}{dI} \left[1 + \frac{I R_a}{\sqrt{I}} + \frac{P_i}{I \sqrt{I}} \right] = 0$$

$$0 + \frac{R_a}{\sqrt{I}} + -\frac{P_i}{I \sqrt{I}^2} = 0$$

$$\frac{R_a}{I} = \frac{P_i}{I^2}$$

$$\boxed{P_i = I^2 R} \Rightarrow \text{losses} (I^2 R)$$

∴ iron loss > copper loss

Q1) A 6 pole 500 volts, wave connected

* DC shunt motor has 1200 armature

conductors and flux per pole is 20mWb

The armature and field resistances are

0.05 Ω and 250 Ω respectively. What

will be the speed and torque developed

by the motor when it draws a current

of 20 Amps from the supply? If the

magnetic and mechanical losses are 400W

Find

(i) Useful torque

(ii) Efficiency at this load

Soln

Given

$$P = 6$$

$$V = 500 \text{ V}$$

wave wound $A = 2$

$$Z = 1200$$

$$\Phi = 20 \times 10^{-3} \text{ Wb}$$

$$(R_a + R_f) I_a > 0.5 \Omega$$

$$R_{th} = 250 \Omega$$


$$I_L = 20 \text{ A}$$

To find :-

1) I_{sh}

2) α_{sh}

3) N



$$I_{sh} = \frac{V}{R_{sh}}$$

$$= \frac{500}{250} = 2A$$

$$I_L = I_a + I_{sh}$$

$$I_a = I_L - I_{sh}$$

$$= 20 - 2$$

$$= 18A$$

$$E_b = \frac{\mu_0 N Z}{60 A}$$

$$E_b = V - I_a R_a$$

$$= 500 - 18 \times 0.45$$

$$= 491V$$

$$E_b = \frac{P\phi NZ}{bDA}$$

$$N = \frac{E_b bDA}{P\phi Z}$$

$$= \frac{4.91 \times 60 \times 2}{6 \times 20 \times 10^{-3} \times 1200}$$

$$= 6138.75 \text{ rpm}$$

$$N = \approx 6139 \text{ rpm}$$

$$T = \frac{P\phi Z I_a}{602\pi A}$$

$$\approx \frac{6 \times 20 \times 10^{-3} \times 1200 \times 18}{2\pi \times 2}$$

$$T = 206.26 \text{ Nm}$$

Power developed in the armature

$$P_m = E_b \times I_a$$

$$= 4.91 \times 18 \text{ watts}$$

$$P_m = \underline{\underline{883.8 \text{ watts}}}$$

$$P_m = T_{ba} \times \omega = T_a \times \omega$$

$$T_{ba} = \frac{P_m}{\omega} \approx$$

$$\approx \frac{8838}{}$$

$$= \frac{P_m}{\frac{2\pi N}{60}}$$

same

$$= \frac{P_m \times 60}{2\pi N}$$

$$= \frac{8838 \times 60}{2 \times \pi \times 406}$$

$$T_{ba} = 2060.26 \text{ Nm}$$

~~$$P_{dn} = V I_a$$~~

$$= 500 \times 18$$


$$= 9000 \text{ watts}$$

$$\rightarrow P_{dn} = V I_L$$

$$= 500 \times 20$$

$$\underline{P_{dn} = 10,000 \text{ watts}}$$

← Power developed
in armature



[electrical parameters
if P in motor]

$$P_{out} = P_m - \text{Mechanical loss}$$

$$\rightarrow 8838 - 900$$

$$P_{out} = 7938 \text{ watts}$$

$$T_{sh} = \frac{P_{out}}{\omega}$$

$$= \frac{7938 \times 60}{2 \times \pi \times 400}$$

$$T_{sh} = \underline{185.033 \text{ N}}$$


% error
T_{sh} will
be lesser
than T_a

$$\% \eta = \frac{P_{out}}{P_{in}} \times 100$$

$$\rightarrow \frac{7938}{10000} \times 100$$

$$\underline{\underline{\% \eta = 79.38\%}}$$


MODULE - 2



↳ (i) Direct testing:-


↳ (ii) Indirect testing:-

→ Swinburne's testing:- [Indirect method of testing]



→ Swinburne's Test :-

Circuit diagram:-



Tabular column:-

-: power developed

Sl. No:	V (Volts)	I _a (Amps)	I _{sh} (Amps)	I _o = I _a + I _{sh}
---------	--------------	--------------------------	---------------------------	---

Calculation :-

[If V_1 is the supply voltage then

then

→ Power input on no load $\rightarrow V I_o$ watts

I_{sh} -

$$= V (I_a + I_{sh}) \text{ watts}$$

→ shunt field copper loss $= V I_{sh}$ watts.

→ Armature copper loss $= I_a^2 R_a$ watts

Thus the stray losses which includes iron, friction and windage losses.

Stray \rightarrow Iron loss + Mechanical loss

\rightarrow Iron loss + (friction + windage) loss

can be obtained

Stray losses = No load Φ P - field loss - Armature loss

$$\therefore \text{Stray loss} = V I_0 - V I_{sh} - I_a^2 R_a = W_s$$

When current flows through the field and armature windings there will be copper losses ($I^2 R$) in the respective winding which increases the temperature, in turn it affects their resistances

Thus new value of shunt field resistance = R_{sh}'

$$\text{and } \therefore R_{sh}' = R_{sh} [1 + \alpha] \text{ and}$$

new value of armature resistance = R_a'

$$\therefore R_a' = R_a [1 + \alpha]$$

$\boxed{\text{R}_a' \text{ and } R_{sh}' \text{ are}} \\ \boxed{\text{temperature}} \\ \boxed{\text{dependent}}$

→ To calculate efficiency at of the motor

at $\frac{1}{4} \text{ H.M. load}$:

Let I_{FL} = full load current of the motor

w_F = Field copper losses

w_A = Armature losses

Load current at $\frac{1}{4} \text{ H.M. load}$

$$\text{load current} = I_{FL} \times \frac{1}{4} = \frac{I_{FL}}{4}$$

Motor input at $\frac{1}{4} \text{ H.M. load}$

$$= N \times \frac{I_{FL}}{4} = \frac{N I_{FL}}{4}$$

Armature current at $\frac{1}{4} \text{ H.M. load}$

$$= I_a' = \underline{\underline{I_{a'}}}$$

$$I_a' = \frac{I_{FL}}{4} - I_{sh}$$

Armature copper loss at $\frac{1}{4} \text{ H.M. load} = (I_a')^2 R_a$

$$= (I_a')^2 R_a$$

→ I_a'

$$= [I_a']^2 R_a$$

$$\text{input A motor current} = \left[\frac{I_{FL}}{4} - I_{sh} \right]^2 R_a$$

$$\text{Motor loss} \rightarrow [I_a]^2 R_a \cdot \text{load on no}$$

$$\text{SD 100 is referred with respect to tank.} \\ \text{Efficiency} = \eta \left[\frac{I_{FL}}{4} - I_{sh} \right]^2 R_a$$

$$\text{Motor output at } 1/4 \text{ th load} = \left(\frac{V I_{FL}}{4} \right) - \frac{q}{P} - \text{loss}$$

$$= \left[\frac{V I_{FL}}{4} \right] - \left[\left(\frac{I_{FL}}{4} - I_{sh} \right)^2 R_a + W_F + W_S \right] \quad (ii)$$

$$\% \text{ Efficiency} \rightarrow \frac{\text{P. Motor output}}{\text{motor input}}$$

$$= \left[\frac{V I_{FL}}{4} \right] - \left[\frac{I_{FL}}{4} \right]$$

$$\rightarrow \frac{\text{Input} - \text{loss}}{\text{Input}} * 100$$

$$\% \eta_{1/4} = \frac{\frac{V I_{FL}}{4} - \left[\left(\frac{I_{FL}}{4} - I_{sh} \right)^2 R_a + W_F + W_S \right]}{\frac{V I_{FL}}{4}} * 100$$

$$\text{Now } 80 = 100 * 78 \Rightarrow 100 * 78 = 80 * R_a$$

$$0.78 = 9.5 \text{ load on no}$$

$$\text{Now } 0.06 = \mu * 0.08$$

Q1) A 500 volts DC shunt motor takes 4 Amps on no load. The armature resistance including that of the brushes is $0.2\ \Omega$ and the field current is 1 Amp. Estimate the output and efficiency when the P.I.P current is

(i) 20 Amps

(ii) 100 Amps

Soln Given :-

$$V = 500\ V$$

$$I_0 = 4\ \text{Amps}$$

$$R_a = 0.2\ \Omega$$

$$I_{sh} = 1\ \text{Amp}$$

To find :- O/P efficiency

$$\text{at } I_{L1} = 20\ A, I_{L2} = 100\ A$$

Soln

$$\rightarrow I_{ao} = I_0 - I_{sh}$$

$$I_{ao} = 3\ \text{Amp}$$

\rightarrow No load armature copper loss = 3

$$= I_{ao}^2 R_a = (3)^2 \times 0.2 = 1.8\ \text{watts}$$

$$\rightarrow \text{No load O/P} = V I_0$$

$$500 \times 4 = 2000\ \text{watts}$$

$$\rightarrow \text{constant loss} = \sqrt{I_a^2 - I_{ao}^2} R_a = \mu\% \\ = 2000 - 100 \\ = 1998.2 \text{ watts}$$

\hookrightarrow when $I_u = 20 \text{ Amps}$

$$I_{ai} = I_u - I_m \\ = 20 - 1 = 19 \text{ Amps}$$

$$\text{New value of in loss} = I_{ai}^2 R_a = 19^2 \times 0.02 \\ = 72.02 \text{ watts}$$

$$\text{New load } P/P = \sqrt{I_{L1}}$$

$$= 500 \times 20 \\ = 10000 \text{ watts}$$

$$\% \mu = \frac{P/P - \text{loss}}{P/P} \times 100$$

$$\rightarrow \frac{10000 - [72.02 + 1998.2]}{10000} \times 100$$

$$= 79.029 \%$$

\hookrightarrow when $I_{L2} = 100 \text{ Amps}$

$$I_{a2} = 100 - 1 \\ = 99 \text{ Amps}$$

$$\text{New in loss} > I_{a2}^2 R_a > (99)^2 \times 0.02 > 1960.2 \text{ W}$$

$$\text{New load } P/P = \sqrt{I_{L2}} = \sqrt{500 \times 100} \\ = 50000$$

$$\% \eta = \frac{50,000 - (1960.2 + 19980.2)}{50,000} \times 100$$


$$\underline{\underline{\% \eta = 92.08\%}}$$


\Rightarrow Brake test :-

This is direct method of testing a DC motor by means of a belt and pulley arrangement (brake drum).

By adjusting the tension of the belt, the load is adjusted to give various values of current.

Circuit diagram :-





Belt and pulley arrangement

Let R = radius of brake drum in metres

N = speed in rpm

w_1 = spring balance reading on tight side
in Kg

w_2 = spring balance reading on slack side

∴ Net pull on the belt due to friction

is given by $= (w_1 - w_2)$ Kgs

Net pull $= 9.81 (w_1 - w_2)$ Newtons

As the speed N and radius R is known,

the shaft torque developed is given by

$$T_{th} = \text{Net pull} * R$$

$$= 9.81 (w_1 - w_2) * R \text{ N-m}$$

The power of P is given by

$$P_{out} = T_{th} * w \text{ watts}$$

$$P_{out} = \left[\frac{9.81 (w_1 - w_2) * 2\pi N^2}{60} \right] \text{ watts}$$

Power Input $P_{in} = V I_L$ watts

where V = supply voltage

$I_L = \text{V}_{\text{m}} / \text{supply current}$

$$\% \text{ Efficiency} = \frac{P_{out}}{P_{in}} * 100$$

$$\% \eta = \frac{9.81 (w_1 - w_2) * 2\pi N^2}{60 * V I} * 100$$

- Q1) In a brake test conducted on a DC shunt motor, the full load readings are observed as - tension of flag $w_1 = 9.1 \text{ kg}$, tension of flag $w_2 = 0.8 \text{ kg}$, total current = 10A, supply voltage = 110V, speed = 1320 rpm, $R = 7.05 \text{ cm} = 0.075 \text{ m}$. Calculate its full load efficiency.

Soln

Given

$$w_1 = 9.1 \text{ kg}$$

$$w_2 = 0.8 \text{ kg}$$

$$N = 1320 \text{ rpm}$$

$$I_L = 10 \text{ A}$$


$$R = 7.05 \text{ cm} = 0.075 \text{ m}$$

$$\% \eta = \frac{9.081 (9.081 - 0.8) \times 2\pi \times 1320 \times 100}{60 \times 110 \times 40}$$

= Beds 76.73%

\Rightarrow Retardation Hst%:- (or) Running down Hst%:-

(iii) Breaker deem not :-



From this method we can get- stray losses.

It is generally employed for deshunt-machines

machines

If I in the moment of inertia of the

then

$$w = \left(\frac{2\pi}{60}\right)^2 IN \frac{dN}{dt_1} \rightarrow ①$$

In this method the time is noted for the machine to slow down by 50% of the rated armature voltage alone. say t_1 (Time)

Then retarding torque, preferably electrical retarding torque is applied (load resistance (R_L)) is applied and time required to slow down by 50% of rated armature voltage is noted again say t_2 (Time)

Thus

$$w + w' = \left(\frac{2\pi}{60}\right)^2 IN \frac{dN}{dt_2} \rightarrow ②$$

Dividing ② \Rightarrow ①

$$\frac{w + w'}{w} = \frac{dt_1}{dt_2} * \frac{dt_1}{dt_2} \Rightarrow \frac{dt_1}{dt_2}$$

$$wdt_2 + w'dt_2 = wdt_1$$

$$w'dt_2 = wdt_1 - wdt_2$$

$$w [dt_1 - dt_2] = w' dt_2$$

$$w = \frac{w' dt_2}{(dt_1 - dt_2)}$$

$$\Rightarrow w = \frac{w' t_2}{t_1 - t_2}$$

Q1) A retardation test is conducted on a separately excited DC shunt motor. The induced voltage falls from 240V to 220V in 25 seconds on opening the armature circuit and in 6 seconds on suddenly changing the armature connection from supply to load resistance which takes an average current of 10A. Find the efficiency of the machine when running as a motor taking a current of 25A from a supply of 250V. The resistance of the armature is 0.3Ω and field winding is 200Ω.

Soln

Given : - $R_a = 0.6 \Omega$, $R_m = 200 \Omega$

$$I_{avg} = 10 A$$

$$t_1 = 25 \text{ sec} = 25 \text{ sec}$$

$$t_2 = 60 \text{ sec} = 6 \text{ min}$$

$$\therefore V_1 = 240 V$$

$$V_2 = 220 V$$

$$V_{avg} = \frac{V_1 + V_2}{2} = \frac{240 + 220}{2} = 230 V$$

No. of turns in the two A (1)

Power absorbed by the load $= W' =$

$$W' = V_{avg} \times I_{avg}$$

$$= 230 \times 10$$

$$> 2300 \text{ watts}$$

$$W' = \frac{W' \times t_2}{t_1 - t_2}$$

$$> 2300 \times \frac{60}{25 - 6}$$

$$\therefore 726.31 \text{ watts} = \text{Steady losses (constant)}$$

Power input to the motor $= V I_d$

$$P = 250 \times 25$$

$$= 6250 \text{ watts}$$

• 2000 W

$$\rightarrow \text{loss per loss} = I_a^2 R_a$$

\rightarrow Amperes current loss in armature wire

$$I_a = I_L - I_{sh}$$

(Hence current in shunt field) (Hence)

$$= I_L - \frac{V}{R_{sh}}$$

(Hence current in shunt field) (Hence)

$$\approx 25 - \frac{250}{200}$$

$$I_a = 23.075$$

$$\text{Armature copper loss} = I_a^2 R_a$$

$$= (23.075)^2 \times 0.3$$

$$\approx 169.021 \text{ watts}$$

$$\text{Field copper loss} = \frac{V}{R_{sh}} I_{sh}$$

$$(Hence) I_{sh}^2 R_{sh}$$

$$\approx \left(\frac{250}{200} \right)^2 \times 200$$

$$= \underline{\underline{312.05 \text{ watts}}}$$

$$\text{total loss} \rightarrow \text{Armature loss} + \text{Field loss} + \text{Stray loss}$$

$$= 169.021 + 312.05 + 726.031$$

$$= \underline{\underline{1208.02 \text{ watts}}}$$

$$\% \eta_m = \frac{\text{Total power output}}{\text{Input power}} \times 100 = \frac{6250 - 1208.02}{6250} \times 100$$

$$\text{Voltage at full load current} = eI$$

$$= 80.67 \%$$

$$\text{Voltage at no load current} = zI$$


Hopkinson's test :-

(i) Regenerative test :-

(ii) back to back test :-

Without shunt
M & G were
of Generat does not
have path for
flowing

① made shunt
to avoid circulating
currents and
allow synchronizatⁿ
of motor & generator



Method :-
Motor $\left\{ \begin{array}{l} \text{IP} \text{ utilized through} \\ \text{generator} \end{array} \right.$

Generator $\left\{ \begin{array}{l} \text{IP} \text{ utilized through} \\ \text{motor} \end{array} \right.$

\therefore Back to back test

Over exciting - Generator $\left\{ \begin{array}{l} \text{IP} \text{ utilized through} \\ \text{generator} \end{array} \right.$
under exciting - Motor $\left\{ \begin{array}{l} \text{IP} \text{ utilized through} \\ \text{motor} \end{array} \right.$

Let V = Supply voltage

I_1 = Current drawn from the supply

I_2 = Current supplied by the generator

I_3 = exciting / field current of the generator

field current = exciting current

I_1 = exciting or field current of motor

R_a = resistance of each armature of each machine

→ Armature copper loss in the generator

$$= \underline{(I_2 + I_3)^2 R_a \text{ watts}}$$

→ Field copper loss in the generator

$$= \underline{\sqrt{I_3} \text{ watts}}$$

→ Armature copper loss the motor $= \underline{(I_1 + I_2 - I_4)^2 R_a \text{ watts}}$

Field copper loss in the motor $= \underline{\sqrt{I_4} \text{ watts}}$

The total losses in the generator and motor are equal to power supplied by the mains

\therefore Power drawn from the supply $= \underline{\sqrt{I_1} \text{ watts}}$

\therefore Total stray losses = Power $\times \eta -$ Total cu losses

$$W_s = \underline{V I_1 - \left[(I_2 + I_3)^2 R_a + \sqrt{I_3} + (I_1 + I_2 - I_4)^2 R_a + \sqrt{I_4} \right]}$$

\therefore Stray loss per machine $= \frac{W_s / 2}{V}$

(ii) Motor

(i) Motor efficiency %

$$\% \eta_m = \frac{P_{IP} - \text{losses}}{P_{IP}} \times 100$$

→ Power s/p to the motor = $V(I_1 + I_2)$ watts

Total loss of the motor =

$$= (I_1 + I_2 - I_u)^2 R_a + VI_u + W_{S12}$$

$$\% \eta_m = \frac{V(I_1 + I_2) - [(I_1 + I_2 - I_u)^2 R_a + VI_u + W_{S12}]}{V(I_1 + I_2)} \times 100$$

(iii)

Generator efficiency %

$$\begin{cases} \text{motor} = P_{IP} - \text{electric} \\ \text{generator} = P_{IP} - \text{electr} \end{cases}$$

$$\% \eta_g = \frac{P_{IP}}{P_{IP} + \text{losses}} \times 100$$

$$\therefore \eta_m = \frac{P_{IP}}{P_{IP} + \text{losses}}$$

$$\% \eta_g = \frac{P_{IP}}{P_{IP} + \text{losses}}$$

Power o/p of the generator = $V I_2$ watts


Total losses of generator

$$= (I_2 + I_3)^2 R_a + VI_3 + W_{S12} \text{ watt}$$

$$\% \eta_g = \frac{VI_2}{[(I_2 + I_3)^2 R_a + VI_3 + W_{S12}] + [VI_2]} \times 100$$

(a) Following results were obtained during Hopkinson's on two similar DC shunt machines of 230V, Armature currents 37A and 30A, field current 0.85 A and 0.80 A respectively calculate the efficiencies of the machines if each has an armature resistance of 0.33 ohms

John



Grumen

Almatall current = 37 A, 30A
field current = 0.85 A, 0.80 A

$$Ra = 0.3352$$

join // (method - 1 - some using)

For motor - generator set

→ Armature copper loss of generator = $I_a^2 R_a$

$$= 37^2 \times 0.33$$

Int jo spindly int total torque $\rightarrow 151.77 \text{ Nm}$

→ Field copper loss = $V I_{fm}$

$$= 220 \times 0.85$$

$$= 195.5 \text{ W}$$

skew

→ Armature copper loss of generator = $I_a^2 R_a$

$$= 30^2 \times 0.33$$

$$= 297 \text{ W}$$

→ Field copper loss of generator

$$= V I_{fg}$$

$$= (230) (0.80)$$

$$= 184 \text{ W}$$

loop

→ Total power input = $V I$

$$= 230 \times 80.65$$

$$= 1989.5 \text{ W}$$

$$\rightarrow \text{fray loss} = W_s = \frac{\eta}{P} - \text{total w loss}$$

$$= 1989.5 - (451.77 + 195.5 + 297 + 184)$$

$$= \underline{861.23} \text{ W}$$

$$\rightarrow \text{fray loss per machine} = 430.615 \text{ W}$$

A_{oe} = review

(i) Motor efficiency % :-

$$\rightarrow \text{Power o/p to the motor} = 230 \times 37.5$$

$$\rightarrow \text{loss due to motor} = \underline{8705.5 \text{ W}}$$

$$\rightarrow \text{Total loss of the motor} = 3(37.5^2 \times 0.33) + 230 \times 0.85 + 430.615$$

$$\rightarrow \text{motor loss} = \underline{1077.88 \text{ W}}$$

$$\% \eta_m = \frac{8705.5 - 1077.88}{8705.5} \times 100$$

$$= \underline{87.061 \%}$$

(ii) Generator efficiency % :-

$$\rightarrow \text{Power o/p of the generator} = VI = 230 \times 29.02$$



$$= \underline{6716 \text{ W}}$$

$$\rightarrow \text{Total loss} = 30 \times 29.02 +$$

$$= 80^2 \times 0.33 + 0.8 \times 230 + 430.615$$

$$= 911.061$$

$$\% \eta_g = \frac{6716}{6716 + 911.061} \times 100 = \underline{88.04 \%}$$

Q2) Two identical Dc shunt machines

when test by Hopkinson's method

gave the following results

(i) Line voltage 230V

(ii) Line current including field
current = 30 A


(iii) Motor armature current is 230A

Sols (iv) Field current 5A & 1A respectively

(v) The armature resistance of each machine

~~230V + 0.025Ω~~ calculate the efficiency of
both the machines

II (Method - 2) → Some working



Soln

For motor generator set

$$\rightarrow \text{Armature loss of motor} = I_{am}^2 R_a$$

$$= (230)^2 0.025$$

$$= 13220.5 \text{ W}$$

$$\rightarrow \text{Field losses} = VI_{fm}$$

$$= 230 * 5$$

$$= 1150 \text{ W}$$

$$\rightarrow \text{Armature losses of generator} = I_{ag}^2 R_a$$

$$= (200)^2 0.025$$

$$= 1000 \text{ W}$$

$$\rightarrow \text{Field loss of generator} = 230 * 4$$

$$= 920 \text{ W}$$

$$\rightarrow \text{Total power } S/P = VI^2$$

$$= 230 * 39$$

$$= 8970$$

$$W_s > S/P - \text{losses}$$

$$> 8970 - (13220.5 + 1150 + 1000 + 920)$$

$$= 45770.5 \text{ W}$$

$$W_s/2 \approx 2288.077 \text{ W}$$

(ii) Motor efficiency

$$\rightarrow \text{Power } P/P = 230 \times (230 + 5)$$

$$= 54050 \text{ W} \quad \underline{\underline{54050 \text{ W}}}$$

$$\rightarrow \text{Total loss} = (230^2 \times 0.0025) + (230 \times 5) + 2288.75$$

$$= \underline{\underline{4761.25 \text{ W}}}$$

$$\% \eta_m = \frac{54050 - 4761.25}{54050} \times 100$$

$$= \underline{\underline{91.19\%}}$$

(iii) Generator efficiency

$$\rightarrow \text{Power } O/P = 230 \times 200$$


$$= \underline{\underline{46000 \text{ W}}}$$

$$\rightarrow \text{Total loss} = (200^2 \times 0.0025) + (230 \times 4) + 2288.75$$

$$= \underline{\underline{4208.75 \text{ W}}}$$

$$\% \eta_g = \frac{46000}{46000 + 4208.75} = \underline{\underline{91.61\%}}$$

\Rightarrow Field rest on DC series machines :-



Let V = supply voltage

I_1 = Current drawn by the motor

I_2 = Current supplied by the generator

V_1 = Voltage drop across motor

V_2 = Voltage drop across generator

R_a & R_g = Armature and series field

resistance of each machine.

Ques: What are the losses in a motor?


→ Power drawn from the supply = $\underline{V I_1}$ watts

→ Output of the generator = $\underline{V_2 I_2}$ watts

→ ∴ Total loss in both the machines = $\underline{(V I_1 - V_2 I_2)}$ watts

→ Armature and field

- in losses =



$$\underline{i_1 P - o_1 P}$$

$$(V I_1 - V_2 I_2)$$

$$I_1^2 (R_a + R_{se}) + I_2^2 R_{se}$$

$$I_1^2 (R_a + 2 R_{se}) + I_2^2 R_{se}$$

$I_1^2 R_a + I_2^2 R_{se}$ = Armature by field in loss of motor

$I_1^2 R_{se} + I_2^2 R_a$ = Armature by field in loss of generator

→ Stray loss = Total loss - $I_1^2 R_a$

$$W_s = \underline{(V I_1 - V_2 I_2) - [I_1^2 (R_a + 2 R_{se}) + I_2^2 R_{se}]}$$

Stray loss per machine = $W_s / 2$

(P) Motor efficiency % = $\frac{\text{Power input to the motor}}{\text{Power input from the supply}} \times 100$

$$\% \eta_m = \frac{P_{IP} - \text{losses}}{P_{IP}} \times 100$$

→ Power input to the motor = $\underline{V I_1}$ watts

$$\rightarrow \text{Total losses in the motor} = I_1^2 R_a + I_1^2 R_{se} + W_s/2$$


losses due to magnetism

$$= I_1^2 (R_a + R_{se}) + W_s/2 \text{ watt}$$

losses due to magnetism

$$\% \eta_m = \frac{VI_1 - (I_1^2 (R_a + R_{se}) + W_s/2) \times 100}{VI_1}$$

(iii) Generator efficiency :-



$$\% \eta_g = \frac{V_2 I_2}{V_2 I_2 + I_2^2 R_a + I_1^2 R_{se} + W_s/2} \times 100$$

- Q1) A test on two coupled similar frame way motors, with their field connected in series, gave the following result when one machine acted as a motor and the other as a generator.


(a) Motor :- $I_a = 56 \text{ A}$, Armature Voltage = 590 V ,
Voltage drop across field winding = 40 V

(b) Generator :- $I_a = 14 \text{ A}$, Armature voltage = 400 V ,
voltage drop across field = 20 V

\rightarrow Resistance of each armature $= 0.3 \Omega$

Calculate the efficiency of the motor and the generator.

Soln



Armature voltage $= \underline{m} + \underline{\text{M}}$
 (both ~~phasor~~ phasor sum)
 \hookrightarrow not single armature alone

$$\rightarrow \text{Total supply voltage } = V_g = 590 + 40 = 630$$

$$\rightarrow \text{Supply current } = I_1 = 5.6 \text{ A}$$

$$\rightarrow \text{Total power } P = V_g I_1 = 630 \times 5.6 = 35280 \text{ W}$$

$$\rightarrow \text{O/P of generator } = V_2 I_2 = 400 \times 4 = 1600 \text{ W}$$

$$\rightarrow \text{Total loss } = \text{O/P} - \text{O/P} = 35280 - 1600$$

$V_{OPA} = \text{power loss in Amperes} \times A_{H.L.} = 17680 \text{ W}$

$V_{OPA} = \text{power loss in Amperes} \times A_{H.L.} = 17680 \text{ W}$

$V_{OPA} = \text{power loss in Amperes} \times A_{H.L.} = 17680 \text{ W}$

$V_{OPA} = \text{power loss in Amperes} \times A_{H.L.} = 17680 \text{ W}$

$$\rightarrow \text{loss} = [I_1^2 (R_a + 2R_{se}) + I_2^2 R_a]$$

$$= (56)^2 (0.3 + 2 \cdot 0.3) \approx 5990$$

$$R_{se} = \frac{V_{ab}}{I_1} = \frac{5990}{56} \approx 107.14$$

R_{se} = Voltage drop across field winding
current

$$\text{loss} = (56)^2 (0.3 + 2(0.714)) + (24)^2 (0.3)$$

$$= 5999.80$$

$$\text{Stray loss} = 17680 - 5999.8 \text{ W}$$

$$= \underline{11680.2 \text{ W}}$$

$$= \underline{W_{1/2} = 5840.01 \text{ W}}$$

(Q) Motor efficiency :-

$$\% \eta_m = \frac{P_{IP} - W_{1/2}}{P_{IP}} * 100$$

in only forward
50 rot (630V)

$$\rightarrow \text{Power } P_{IP} \text{ to motor} = V I_1 = 590 \times 56$$

$$= \underline{33040 \text{ W}}$$

$$\rightarrow \text{losses} = I_1^2 R_a + I_2^2 R_{se} + W_{1/2}$$

$$= 56^2 (0.3) + 56^2 (0.714) + 5840.1$$

$$= \underline{9020.00 \text{ W}}$$

$$\% \eta = \frac{33040 - 9020}{33040} \times 100$$

Sync m/e with
→ synchronous
speed
 $N_s = 1200$

$$= 72.7\%$$

→ (iii) & Generator efficiency :-

$$\eta_g = \frac{\text{O/P}}{\text{D/P} + \text{P/L}} * 100$$

RMF → current produced by
rotor winding

$$\rightarrow \text{Power O/P} > V_2 I_2 = 400 \times 44$$

$\geq 17600 \text{ W}$

$$\rightarrow \text{Total loss} = I_2^2 R_a + I_1^2 R_{se} + V_o S / 2$$

$$= (44^2 \times 0.3) + (50)^2 (0.0714) + 5839.12$$

$$\rightarrow 8659.16$$

purely rotam (9)

$$\% \eta = \frac{17600}{17600 + 8659.16} \times 100$$


$$= 67.02\%$$

DC supply $\approx 220V$

1φ AC $\rightarrow 230V, 50Hz$

3φ AC $\rightarrow 415/430/440V$

$1.048 \times 50Hz + (41500) \times 32 +$



$$\rightarrow V_{ph} = \frac{V_L}{\sqrt{3}} ; I_L = \frac{17600}{0.6702} =$$

D.C. machine \rightarrow physical pole
 A.C. motor \rightarrow imaginary pole
 $I_m \rightarrow$ Imaginary pole

\Rightarrow Three - phase induction motor :-

R.M.F creates
 the effect
 of imaginary
 pole
 \downarrow
 starts at
 synchronous
 speed.

Stator \rightarrow 3 ϕ (compo.) \rightarrow Y or D conn
 & some type of winding Y or D

Rotor \rightarrow

Three types \rightarrow require

$$\Phi_R = \Phi_{\text{main}} \sin(0-0)$$

$$\Phi_Y = \Phi_m \sin(0-120)$$

$$\Phi_B = \Phi_m \sin(0-240)$$

By instantaneous
time variation

// works on electromagnetic induction

R.M.F

stator -

zero crossing at


$0^\circ, 60^\circ, 120^\circ, 180^\circ$

$$\Phi_R = \sin 0 = 0$$

$$\Phi_Y = \Phi_m \sin(-120) = -0.866 \Phi_m$$

$$\Phi_B = \Phi_m \sin(-240) = +0.866 \Phi_m$$

Assumed the
direction phaser diagram



III(a)


Case 2 $\theta = 60^\circ$

$$\Phi_R = \Phi_m \sin 60^\circ = 0.866 \Phi_m$$

$$\Phi_Y = \Phi_m \sin(60 + 60) = -0.866 \Phi_m$$

$$\Phi_B = \Phi_m \sin(60 - 60) = 0$$

$$\Phi_T = \Phi_R + \Phi_Y + (\Phi_B / \epsilon) / 2$$



$$\cos 30^\circ = \frac{OD}{OB} = \frac{\Phi_Y / 2}{0.866 \Phi_m}$$

$$\Phi_T = 1.5 \Phi_m$$



III(b)

Case (b) $\theta = 120^\circ$

$$\Phi_T = 1.5 \Phi_m$$

II Case (ii) $\theta = 180^\circ$

$$\Phi_T = 1.5 \Phi_m$$




// Stator flux + rotor flux interact to produce force and torque is produced \Rightarrow and rotor conducts starts rotation

(P)

Salient pole motor (a)

short-circuited slots (a) unslotted
ring or Al bld




end rings

slots (conductors)


extreme value

in fluid
(one designed it
in fluid)

no external current
can be added



(ii) Slip ring motor:- slip ring and brush assembly is stationary



Stator winding + Rotor winding \rightarrow armature (R.M.F.)

Current gets induced in rotor
switch is off

* External resistance can be added to centrifugal switch
* Frequent maintenance is necessary

→ Slip of an induction motor :- (S) :-
(or) (Absolute slip)

Let N_s = synchronous speed of the R.M.F.
in rpm

N = speed of the motor in rpm

$N_s - N$ = Relative speed or slip speed
in rpm

$N < N_s$ = N is always less than N_s

Definition :-

It is defined as the difference between the synchronous speed [N_s] and the actual speed [N] of the motor expressed as a fraction of synchronous speed N_s .

$$\rightarrow \text{Actual slip} (\%) \quad \text{Slip} = \frac{N_s - N}{N_s}$$

(Q1)

$$\% s = \frac{N_s - N}{N_s} * 100$$

\Rightarrow Actual speed (N) in terms of N_s :-

$$(s * N_s) = (N_s - N)$$

$$s N_s - N_s = -N$$

$$N_s (s - 1) = -N$$

$$N = N_s (1 - s)$$

* At start

$$N = 0$$

$$0 = N_s (1 - s)$$

$$1 - s = 1$$

$$s = 1$$

[maximum value that the induction motor can attain i.e., $s = 1$]

[s is maximum at start]

- The value of Slip is maximum i.e.,

$s = 1$ only at start, and goes

on reducing as the motor starts

- Slip can never be zero

Q1) A 4 pole 3 phase induction motor (IM) is supplied from a 50Hz supply. Determine its synchronous speed on full load, its speed is observed to be 1410 rpm calculate its full load slip.

Soln

$$P = 4$$

$$f = 50 \text{ Hz}$$

$$N = 1410 \text{ rpm}$$

To find = $s = ?$

$$N_s = \frac{120f}{P}$$

$$= \frac{120 \times 50}{4}$$

$$= 1500$$

$$\boxed{s} = \frac{N_s - N}{N_s}$$

$$= 1500 - 1410$$

$$\frac{1500}{1500}$$

$$\boxed{s} = \frac{0.06}{1}$$

$$(04) \boxed{s} \approx 6\%$$

It cannot be more than 1% and cannot be zero] and values from 1% - 15%]

→ Effect of slip on the motor

(M1) parameters:-
 - slip affects ~~lower~~ the frequency
 of the motor induced emf
 and hence some motor parameters
 also get affected.

→ the following motor parameters gets affected due to slip:-

- (i) Rotor frequency
- (ii) Magnitude of motor induced emf
- (iii) Rotor reactance
- (iv) Rotor power factor
- (v) Rotor current

→ (i) Effect on motor frequency :- $(f_m) \%$ -

w.k.t

$$\text{speed of rpm} = \frac{120f}{P} \text{ Ns} \rightarrow ①$$

$\downarrow \text{at start}$

f = frequency of supply

$$\text{At start } N = 0, S = 1$$

- Thus stationary motor has maximum relative motion w.r.t RMF
- Hence maximum emf gets induced at start and frequency of this induced emf is same as supply (motor)
- As the motor starts running with a speed of 'N' rpm, the relative motion between the motor w.r.t 'RMF' decreases and becomes equal to the slip speed $[N_s - N]$
- Hence in running condition, the magnitude of induced emf decreases and so does the frequency (decreases)
- If f_m = frequency of motor induced emf in running condition at slip speed $N_s - N$ then

$$N_s - N = \frac{120 f_m}{P} \rightarrow ②$$

\rightarrow Running condition

Dividing eqn ② by eqn ①

$$\frac{N_s - N}{N_s} = \frac{120 f_m / P}{120 f_s / P}$$

$$S = \frac{f\alpha}{f}$$

$$\therefore f\alpha = Sf$$

At start $S = 1, N = 0$ [step in man at start]

$$\therefore f\alpha = f$$

→ (iii) Effect on magnitude of motor induced emf :-
(E_{m})

• W.K.T at start $N = 0, S = 1$ and

relative speed is maximum

(as motion)

∴ Induced emf is also maximum

Hence this emf will be E_2

i.e., $E_2 = \frac{\text{motor induced emf per phase}}{\text{at stand still}}$

→ As the motor starts running relative speed decreases, the induced emf in the motor also decrease proportional to the diff. speed ($N_s - N$)

$$E_2 \propto N_s \rightarrow ①$$

$$E_{2M} \propto \{N_s - N\} \rightarrow ②$$

E_{2M} = induced emf in motor at running condition

∴ dividing ② / ①

$$\frac{E_{2M}}{E_2} = \frac{N_s - N}{N_s}$$

$$\frac{E_{2M}}{E_2} = s$$

$$E_{2M} = s E_2$$

At start $s=1, N=0$

$$E_{2M} = E_2$$

→ L (iii) Effect on motor reactance :- (X_{2M})

(it will not no effect on reactance II only on reactance)

$(R + jX_L)$ varies
constant

∴ resistance is independent
frequency

$X_L = 2\pi f L$
y const
change

∴ X_L changes as frequency change

But R_2 = motor reactance per phase on standstill

X_2 = motor reactance per phase on standstill

→ At standstill, $N=0$, $s=1$

$$\text{W.K.T} \rightarrow f_{\text{ac}} = s f_{\text{line}} \quad \{s=1\}$$

at standstill

$$f_{\text{ac}} = f_{\text{line}} \quad \{s=1\}$$

If L_2 is the motor inductance per phase

$$\text{then } \left[\begin{array}{l} X_2 = 2\pi f_{\text{ac}} L_2 \\ \qquad \qquad \qquad \text{2 phases} \\ = 2\pi f L_2 \qquad \qquad \qquad \text{1 phase} \end{array} \right] \quad \{1\}$$

In running condition

$$X_{2\text{m}} = 2\pi f_{\text{ac}} L_2$$

$$\text{W.K.T} \quad f_{\text{ac}} = s f_{\text{line}} \quad \text{in running condition}$$

$$\therefore \boxed{X_{2\text{m}} = 2\pi s f L_2} \quad \text{2 phases} \quad \{2\}$$

where $X_{2\text{m}}$ is motor reactance per phase

In running condition

$$\therefore \boxed{X_{2\text{m}} = s X_2}$$

$$X_{2\text{m}} = (2\pi f L_2) s$$

from eqn 1

$$\boxed{X_{2\text{m}} = s X_2}$$

- The motor resistance per phase remains unchanged because R_2 is independent of frequency
- Thus the motor impedance per phase in Z_2 at standstill is

$$\boxed{Z_2 = R_2 + j X_2} \quad | \text{ } s_2 \text{ / phase}$$


- Thus the motor impedance per phase under running condition is

$$\boxed{Z_{2R} = R_2 + j X_{2R}} \quad | \text{ } s \text{ / phase}$$

$$\therefore \boxed{Z_{2M} = R_2 + j s X_2}$$

- (iv) Effect on motor power factor:-


At standstill



$$\cos \phi_2 = \frac{R_2}{Z_2}$$

$$\cos \phi_2 = \frac{R_2}{R_2 + j X_2} = \frac{R_2}{\sqrt{R_2^2 + X_2^2}}$$

At running condition



$$\cos \phi_{2m} = \frac{R_2}{Z_{2m}}$$

$$= \frac{R_2}{R_2 + jX_{2m}}$$

$$= \frac{R_2}{R_2 + j(\delta X_2)}$$

$$\Rightarrow \frac{R_2}{\sqrt{R_2^2 + (\delta X_2)^2}}$$

As the motor winding is inductive, the motor power factor is always lagging

→ L (v) Effect on motor current :-

Let I_2 = motor current per phase on standstill

I_2 depends on the magnitude

of E_2 and Z_2


Z_2 is impedance at standstill

When E_2 = motor induced emf per phase on standstill

$$\therefore I_2 = \frac{E_2}{Z_2} \text{ per phase}$$

$$I_2 = \frac{E_2}{\sqrt{R_2^2 + (X_2)^2}} \text{ per phase}$$

→ The equivalent motor circuit on standstill is as shown




Let I_{2m} = motor current per phase under running condition.

$$I_{2m} = \frac{E_{2m}}{Z_{2m}} \text{ per phase}$$

$$I_{2m} = \frac{E_{2m}}{\sqrt{(R_2)^2 + (X_{2m})^2}} \text{ per phase}$$

$$I_2 = \frac{s E_2}{\sqrt{(R_2)^2 + (s X_2)^2}} \text{ per phase}$$



→ Effect of slip on motor parameters :-

Soln

$$(i) f_m = s f$$

$$(ii) E_{2m} = 2E_2$$

$$(iii) X_{2m} = sX_2$$

and

$$X_{2m} = \sqrt{R_2^2 + (sX_2)^2}$$

$$(iv) \cos \phi_{2m} = \frac{R_2}{X_{2m}} = \frac{R_2}{\sqrt{R_2^2 + (sX_2)^2}}$$

$$(v) I_{2m} = \frac{E_{2m}}{X_{2m}} = \frac{2E_2}{\sqrt{R_2^2 + (sX_2)^2}}$$

- (Q1) In a 6 pole, three phase IM 50Hz with star connected motor, the motor resistance per phase is 0.3 ohm. The reactance at standstill is 1.5 Ω per phase. On applying the slip rings on open circuit is 175V. Calculate

(i) Slip at a speed of 960 rpm

(ii) Rotor EMF per phase

(iii) Rotor frequency and reactance at

a speed of 950 rpm.

Soln Given :-

$$P = 6$$

$$f = 50 \text{ Hz}$$

$$R_2 = 0.3 \Omega \text{ / phase}$$

$$X_2 = 1.5 \Omega \text{ / phase}$$

$$E_2(\text{rms}) = 175 \text{ V}$$

To find :-

$$(i) S = ? \rightarrow N_s = 120 \text{ rpm}$$

$$(ii) E_{2m} = ?$$

$$(iii) f_a \text{ and } X_{2m} = ? \rightarrow N = 150 \text{ rpm}$$

Soln

Rotor \rightarrow star connect-

$$V_{ph} = \frac{E_2}{\sqrt{3}}$$

$$E_{ph} = \frac{E_2}{\sqrt{3}}$$

$$= \frac{175}{\sqrt{3}}$$

$$= 101.036 \text{ V}$$

$$\Rightarrow N_S = \frac{120f}{P}$$

$$= \frac{120 \times 50}{6}$$

$$= \underline{\underline{1000 \text{ rpm}}}$$

$$N = 960 \text{ rpm}$$

$$\rightarrow s = \frac{Ns - N}{Ns}$$

$$= \frac{1000 - 960}{1000}$$

$$s = \underline{\underline{0.04}}$$

$$\rightarrow E_{2ph} = 101.036 \text{ V}$$

$$E_{2M} = s \times E_2$$

$$= 0.04 \times 101.036$$

$$E_{2M} = 4.041 \text{ V } 1 \text{ phase}$$

$$\xrightarrow{*} f_{ac} = s f_i$$

$$f_{ac} = 0.05 \times 50$$

$$f_{ac} = \cancel{0.25} 2.5$$

$$\rightarrow X_{2ac} = s \times r$$

$$= 0.05 \times 0.15$$

$$= 0.075 \Omega \text{ 1 phase}$$

New value of speed $N = 950 \text{ rpm}$

$$s = \frac{1000 - 950}{1000} = 0.05$$

Always E
should be in
phase

→ Induction motor as a rotating transformer :- T108/2/60

Transformer	Induction machine / motor
1) Rotating Alternating flux is produced	Rotating flux (R.M.F.)
2) There is no air gap between the windings	There is air gap between winding (stator and rotor)
3) Frequency of induced voltage and current in primary and secondary is same	The frequency of rotation motor voltage and current depends on slip and slip depends only on motor except starting condition
4) The entire energy present in the secondary circuit is in electrical form	Some part of the energy in the motor circuit is electrical form and major part of the energy is in mechanical form

→ Transformation ratio on 3Φ IM :-

→ At start $N=0$, $s=1$

$$\text{where } \frac{E_2}{E_1} = K$$

where E_2 = motor induced emf at stand

still (or) start

E_1 = stator induced emf per phase

$$\boxed{\frac{E_2}{E_1} = \frac{\text{Rotor emf / phase}}{\text{Stator emf / phase}} = K = \frac{\text{Rotor Mmfs / phase}}{\text{Stator turns / phase}}}$$

(i) A 1000V, 50Hz, 3Φ induction motor

has start connected stator. The ~~rat~~ ratio
of stator to motor turns is 3.6. The
standstill impedance of motor per phase

is $0.01 + j 0.02 \Omega$. Calculate

(ii) Rotor current at start

(iii) Rotor power factor at start

(iv) Rotor current at a slip of 3%

Solu

$$\text{Given :- } V_L = 1000 \text{ V}$$

$$\hookrightarrow V_{ph} = 577.035 \text{ V}$$

$$f = 50 \text{ Hz}$$

$$\frac{\text{Stator turns}}{\text{Rotor turns}} = 3.6$$

$$K = \frac{\text{Rotor turns}}{\text{Stator turns}} = \frac{1}{3.6} = 0.277$$

$$Z_2 = R_2 + j X_2 = 0.1 + j 0.2 \rightarrow \begin{matrix} \text{Stand still} \\ \text{value} \end{matrix}$$

To find :-

$$(i) I_2$$

$$(ii) \cos\phi_2$$

$$(iii) T_{2w} \text{ at } s = 3\%$$

Solu

$$I_2 = \frac{E_2}{Z_2}$$

$$E_{1(w)} = 1000 \text{ V}$$

$$E_{1(ph)} = 577.035 \text{ V}$$

$$E_{2(ph)} = K \times E_1$$

$$= 0.277 \times 577.035$$

$$= 155.88 \text{ V} \quad \underline{160.375 \text{ V}}$$

$$\rightarrow I_2 = \frac{E_2}{Z_2}$$

$$= \frac{15588 \angle 160.375^\circ}{0.014 \angle 0.2^\circ}$$

$$= 1180.87 \angle -1.52^\circ$$

$$= 39.99 - j 799.87$$

$$\underline{I_2} = 800.87 \angle -1.52^\circ A$$

$$\rightarrow \text{load } \phi_2 = \frac{R_2}{Z_2}$$

$$= \frac{0.01}{0.014 \angle 0.2^\circ}$$

$$= 0.0499 \angle -1.52^\circ$$

$$\rightarrow f = 0.03$$

$$I_{2m} \approx \frac{E_{2m}}{Z_{2m}}$$

$$= \frac{8 E_2}{\sqrt{R_2^2 + (8x_2)^2}}$$

$$= \frac{0.03 \times 800.87 \angle 160.375^\circ}{\sqrt{(0.01)^2 + (0.03 + 0.02)^2}}$$

$$= 412.056 A$$

→ Torque equation of 3φ Induction motor:-
The torque produced in an IM depends

on

- (i) The RMF which is responsible for inducing emf in the motor (Φ)
- (ii) The magnitude of motor current in running condition (I_{2m})
- (iii) The power factor of the motor in running condition ($\cos \phi_{2m}$)

Mathematically it is expressed as torque

$$T \propto \Phi I_{2m} \cos \phi_{2m}$$

The flux (Φ) ~~and~~ RMF Φ produced by stator winding is proportional to E_1 (stator voltage E_1 induced emf)

WKT
 E_1 and E_2 are related by the turns ratio K

$$K = \frac{\text{Rotor turns / phase}}{\text{Stator turns / phase}} = \frac{E_2}{E_1} = T$$

$$\therefore K = \frac{E_2}{E_1}$$

Assuming constant of proportionality

$$K = 1$$

$$E_2 = E_1$$

∴ $\Phi \propto E_1$

$$E_2 = E_1$$

$$\therefore \Phi \propto E_2$$

∴ Sub in torque expression

$$T \propto E_2 I_{an} \cos \phi_m$$

$$T = K E_2 I_{an} \cos \phi_m$$

where $K = \text{constant of proportionality}$

$$\text{for } 3-\phi \text{ IM} \Rightarrow K = \frac{3}{2\pi n_s} = \frac{3}{2\pi n_s}$$

$$\text{where } n_s = \frac{N_s}{60} \text{ revs./min. other}$$

$$T = \frac{3}{2\pi n_s} E_2 \times \frac{I_{an}}{\chi_{an}} \times \frac{R_2}{\chi_{2M}}$$

$$T = \frac{3 E_2}{2\pi N_s} * \frac{3 E_2}{\sqrt{R_2^2 + (3X_2)^2}} * \frac{R_2}{\sqrt{R_2^2 + (3X_2)^2}}$$

$$\boxed{T = \frac{3SE_2^2 R_2}{2\pi N_s (R_2^2 + (3X_2)^2)}} \quad \text{N-m}$$

~~Ans~~ Qd

\Rightarrow Starting torque

at start $S = 1$

$$\boxed{T = \frac{3 E_2^2 R_2}{2\pi N_s (R_2^2 + (1X_2)^2)}} \quad \text{N-m}$$

- Q1) A 3ϕ , 400V 50Hz, 4 pole IM has start connected stator winding. The motor resistance and reactance are 0.1Ω and 1Ω respectively at standstill. The full load speed is 1440 rpm calculate the torque developed on full load by the motor. Assume stator to motor ratio as 2%.

John :- Given :-

$$E_1(w) = 400 \text{ V}$$

$$E_1(\text{ph}) = 230.94$$

(after converted
year)

$$f = 50 \text{ Hz}$$

$$P = 4$$

$$R_2 = 0.1 \Omega$$

$$X_2 = 1 \Omega$$

$$N = 1440 \text{ rpm}$$

$$\frac{\text{stator turns/phas}}{\text{rotor turns/ph}} = \frac{2}{1}$$

$$k = \frac{1}{2} = 0.5$$

To find :-

$$T = \frac{3 S E_2^2 R_2}{2 \pi N_1 (R_2^2 + (S X_2)^2)}$$

$$N_1 = \frac{120 f}{P}$$

$$= 120$$

$$= \frac{120 \times 50}{4}$$

$$N_1 = 1500$$

$$n_3 > \frac{n_s}{60} = \frac{1500}{60}$$

$$n_3 = 25 \text{ revs}$$

$$\pi \propto -2\alpha$$

$$\rightarrow \delta = \frac{n_s - N}{n_s}$$

$$= \frac{1500 - 1440}{1500}$$

$$= 0.04$$

$$\pi \propto -3\alpha \theta^2$$

$$\frac{E_2}{E_1} = K$$

$$E_2 = 280.9 \times 0.5$$

$$= 115.47 \text{ V}$$

$$\rightarrow \frac{3 \times 0.04 \times (115.47)^2 \times 0.1}{2 \times \pi \times 25 \times (10.1)^2 + (0.004 \times 1)^2}$$

$$= \underline{\underline{87.71 \text{ N-m}}}$$

→ Condition for maximum torque (T_m) :-

w.k.t

the torque depends on slip at which
the motor is running

$$T = \frac{K s E_2^2 R_2}{(R_2^2 + (s x_2)^2)} \text{ N-m} \quad K = \frac{2}{2\pi N_A}$$

where K_1 , E_2 , R_2 and x_2 are constants

To find the condition for maximum torque
using maxima, minima theorem -

$$\frac{dT}{ds} = 0$$

where $T = \frac{K s E_2^2 R_2}{(R_2^2 + (s x_2)^2)} \text{ Nm}$

$$\frac{dT}{ds} = \frac{(R_2^2 + (s x_2)^2)(K E_2^2 R_2) - K s E_2^2 R_2 (2 s x_2^2)}{(R_2^2 + (s x_2)^2)^2}$$

Differentiate w.r.t 's'

$$\frac{dT}{ds} = \frac{(R_2^2 + (s x_2)^2)(K E_2^2 R_2) - K s E_2^2 R_2 (2 s x_2^2)}{(R_2^2 + (s x_2)^2)^2} = 0$$

$$(R_2^2 + (s x_2)^2)(K E_2^2 R_2) = K s E_2^2 R_2 (2 s x_2^2)$$

$$R_2^2 + (sx_2)^2 = 2s^2x_2^2 \quad (1)$$

$$R_2^2 = 2s^2x_2^2 - s^2x_2^2$$

$$R_2^2 = s^2x_2^2$$

$$s^2 = \frac{R_2^2}{x_2^2}$$

$$s > \frac{R_2}{x_2}$$

$$\Rightarrow s_m = \frac{R_2}{x_2}$$

= slip at maximum torque

\Rightarrow Magnitude of maximum torque :-

WKT

$$T = \frac{k s E_2^2 N_s}{(R_2^2 + (sx_2)^2)} \text{ N-m}$$

Replacing s by s_m in the above equation
we get magnitude of maximum torque

$$T_m = \frac{k s_m E_2^2 R_2}{R_2^2 + (s_m x_2)^2}$$

$$T_m = \frac{k s_m E_2^2 R_2}{R_2^2 + (s_m x_2)^2} \quad \text{N-m}$$

$$= \frac{k E_2^2}{2x_2} T_m \quad \text{N-m}$$

$$\text{where } s_m = R_2/x_2$$

(Q1) Calculate the torque exerted by an 8 pole, 50 Hz, 3φ - IM operating with a 4% slip which develops a maximum torque of 150 kg-m at a speed of 660 rpm. The resistance per phase of the motor is 0.5 Ω

Soln:- Given

$$P = 8$$

$$f = 50 \text{ Hz}$$

$$\delta = 0.04$$

$$T = 150 \text{ kg-m} - \cancel{1470} \text{ Nm}$$

$$(150 \times 9.8 \\ = 1470 \text{ Nm})$$

$$N_m = 660 \text{ rpm}$$

(at maximum torque
speed is also maximum
Nm)

$$R_2 = 0.5 \Omega$$

To find :-

$$T = \frac{3}{2\pi f s} \times \frac{\delta E_2^2 R_2}{(R_2^2 + (\delta X_2)^2)}$$

$$N_s = \frac{120 f}{P}$$

$$= \frac{120 \times 50}{8}$$

$$\Rightarrow 750 \text{ rpm}$$

$$N_s = \frac{N_g}{60} = \frac{750}{60} = 12.5 \text{ rpm}$$

$$\rightarrow \delta_m = \frac{R_2}{x_2}$$

$$\rightarrow \delta_m = \frac{N_s - N_m}{N_s}$$

$$= \frac{750 - 660}{750}$$

$$(down) \leftarrow \underline{0.12}$$

$$\rightarrow x_2 = \frac{0.5}{0.12}$$

$$= \underline{4.167}$$

$$T_m = \frac{k E_2^2}{2x_2}$$

$$E_2 = \sqrt{\frac{T_m x_2}{R}}$$

$$k E_2^2 = T_m x_2$$

$$= 1470 \times 2 \times 4.167$$

$$k E_2^2 = \underline{12242.88} \text{ N}$$

$$T = \frac{K S E^2 R_2}{R_2^2 + (S X_2)^2}$$

$$= \frac{K E^2 S R_2}{R_2^2 + (S X_2)^2}$$

$$= \frac{12242.88 \times 1004 \times 0.5}{(0.5)^2 + (1004 \times 0.16)}$$

$$\underline{T = 881.76 \text{ - Nm}}$$

(Q2) A 3Φ IM having 6 pole start connected stator winding runs on 240 V, 50 Hz supply. The motor resistance & reactance on standstill are 0.12 Ω and 0.85 Ω per phase respectively. The ratio of stator to motor turns is 1.8 and full load slip is 4%. Calculate the torque developed at full load, maximum torque and the speed at maximum torque.

Soln

Given :-

$$E_1(L) \rightarrow 240 \Rightarrow E_{1(pn)} = 138.56 V$$

$$f = 50 Hz$$

$$R_2 = 0.12 \Omega$$

$$X_2 = 0.85 \Omega$$

$$\frac{\text{stator turns } 1 \text{ phase}}{\text{motor turns } 1 \text{ phase}} = 1.8$$

$$K = \frac{1}{1.8} = 0.56$$

$$S_m = 0.04$$

To find :-
 (i) T
 (ii) T_m
 (iii) N_m

Soln :-

$$T = \frac{K \cdot S E_2^2 R_2}{(R_2^2 + (S X_2)^2)}$$

$$E_2 = K E_1 = 0.56 \times 138.56 \\ = 77.059$$

$$K = \frac{3}{2\pi N_s} = \frac{3}{2\pi \times 16.66} = 0.028$$

$$N_s = \frac{120 f}{P}$$

$$= \frac{120 \times 50}{6} = 1000$$

$$N_s = \frac{1000}{60} = 16.66$$

$$T = \frac{0.028 A (77.59)^2 \times 0.04 \times 0.12}{(0.12)^2 + (0.04 \times 0.85)^2}$$

$$\Rightarrow \underline{\underline{52001 \text{ N-m}}}$$

$$(iii) \rightarrow T_m = \frac{K g_m E_2^2 R_2}{R_2^2 + (g_m x_2)^2}$$

$$g_m = \frac{R_2}{x_2} = \frac{0.12}{0.85} = 0.141$$

$$= \frac{0.028 \times 0.141 \times (77.59)^2 \times 0.12}{(0.12)^2 + (0.0141 \times 0.85)^2}$$

$$\Rightarrow \underline{\underline{99.15 \text{ N-m}}}$$

$$(iii) \quad N_m$$

$$N = N_s (1 - s)$$

$$N_m = N_s (1 - g_m)$$


$$\Rightarrow 1000 (1 - 0.141)$$

$$N_m = 859 \text{ rpm}$$

$$\underline{\underline{\frac{859 \times 0.01}{\pi}}}$$

$$dd-ft = \frac{0001}{0.01} = 2N$$

→ Torque vs characteristics :-



OA = stable region

from A → unstable region
AB of operation

C = full load torque

A = maximum torque

B = starting torque.

↳ It consists of

- Low slip region
- High slip region

(a) Low slip region :-

$$T \propto \frac{s E_2^2 R_2}{R_2^2 + (s x_2)^2}$$

If supply voltage V_g remains constant

then E_2 is also constant

$$T \propto \frac{s R_2}{R_2^2 + (s x_2)^2}$$

$$\text{slip} \downarrow \downarrow \downarrow \rightarrow (s x_2)^2 \downarrow \downarrow$$

if slip is low

then $(s x_2)^2$ will be

∴ Neglecting $(sx_2)^2$ term from denominator

$$T \propto \frac{SR_2}{R_2^2} \times \frac{s}{R_2}$$

R remains constant

$$\boxed{T \propto s}$$

→ (iii) High slip region :-

w.r.t

$$T \propto \frac{SR_2}{R_2^2 + (sx_2)^2}$$

as $s \uparrow \uparrow \rightarrow s = 1$

as slip increases upto 1 (max value of slip)

T_e \propto

R₂ remains constant

$$T \propto \frac{s}{s^2 x_2^2}$$

$$\boxed{T \propto \frac{1}{s}}$$

x_2 = constant at standstill

$$\boxed{T_{FL} < T_m}$$

Full load torque will be always less than maximum torque.

$$T \propto \frac{PR_2}{s^2 + R_2^2}$$

$$s^2 + R_2^2$$

$$s^2 + R_2^2$$

$$s^2 + R_2^2$$

Motoring,

⇒, Generating and breaking regions (iii) at

, modes of operation :-

L(i) Motoring mode (or) region :- normal

- when slip lies in the region between

0 and 1 i.e. operation in I.e., $0 \leq S \leq 1$

- The machine runs as a motor

- The direction of rotation of the motor
is same as that RMF.

- The motor speed and corresponding torque
is in the same direction

L(ii) Braking mode :-

- when the slip is greater than the machines
works in braking mode.

- The motor is rotated in opposite direction
to that of RMF


- The motor comes to a quick stop under
the influence of counter torque which
produces braking action

- The method is also known as plugging

- motor expert ←

↳ (iii) Generating mode ~~at two positions~~ ↪

- The value of the slip must be less than zero, (negative slip) which indicates that the motor is rotating at a speed above synchronous speed
- The nature of torque slip characteristics reverses in generating mode



(Both waves should be identical)

⇒ Torque variations :-

→ Torque ratios :-

(i) Full load and man torque ratios :-

$$T \propto \frac{SE_2^2 R_2}{R_2^2 + (Sx_2)^2}$$

→ For full load $S = S_F$

$$T_{FL} \propto \frac{S_F E_2^2 R_2}{(R_2^2 + (S_F x_2)^2)}$$

→ For maximum load $S = S_m$

$$T_m \propto \frac{S_m E_2^2 R_2}{(R_2^2 + (S_m x_2)^2)}$$

$$\therefore \frac{T_{FL}}{T_m} = \frac{S_F E_2^2 R_2}{R_2^2 + (S_F x_2)^2} * \frac{R_2^2 + (S_m x_2)^2}{S_m E_2^2 R_2}$$

$$\frac{T_{FL}}{T_m} \propto \frac{S_F}{S_m} * \frac{(R_2^2 + (S_m x_2)^2)}{(R_2^2 + (S_F x_2)^2)}$$

Dividing both sides by x_2^2

$$\frac{T_{FL}}{T_m} \propto \frac{S_F (R_2^2/x_2^2 + S_m^2)}{S_m (R_2^2/x_2^2 + S_F^2)}$$

$$\therefore WKT = \frac{R_2}{x_2} = S_m$$

$$\frac{R^2}{x_2^2} = S_m^2$$

$$\frac{T_{FL}}{T_m} \propto \frac{s_F}{s_m} \times \frac{(s_m^2 + s_F^2)}{(s_m^2 + s_F^2)}$$

← Tendril

$$\propto s_F \times \frac{2s_m}{(s_m^2 + s_F^2)}$$

$$\frac{T_{FL}}{T_m} \propto \frac{2s_F s_m}{s_m^2 + s_F^2}$$

$$\frac{T_{FL}}{T_m} = K \frac{2s_F s_m}{s_m^2 + s_F^2}$$

If $K > 1$

$$\frac{T_{FL}}{T_m} = \frac{2s_F s_m}{s_m^2 + s_F^2}$$

L(iii) Starting torque and maximum torque
relation:-

$$T \propto \frac{s E_2^2 R_2}{R_2^2 + (s x_2)^2} \rightarrow ①$$

At start $s = 1$ and $x_2 = 0$

$$T_{st} \propto \frac{E_2^2 R_2}{R_2^2 + x_2^2} \rightarrow ②$$

$$s_F s = s_m$$

then

$$T_m \propto \frac{s_m E_2^2 R_2}{R_2^2 + (s_m x_2)^2} \rightarrow ③$$

Dividing ② and ③

$$\frac{T_{st}}{T_m} = \frac{\frac{E_a^2 R_2}{(R_2^2 + X_2^2)} \times (R_2^2 + (8m X_2)^2)}{8m \frac{E_a^2 R_2}{(R_2^2 + X_2^2)}}$$

$$\frac{T_{st}}{T_m} = \frac{R_2^2 + 8m^2 X_2^2}{8m [R_2^2 + X_2^2]}$$

Dividing both Nr and Dr by X_2^2

$$= \frac{\frac{R_2^2}{X_2^2} + 8m^2}{8m \left[\frac{R_2^2}{X_2^2} + 1 \right]}$$

Substitute $R_2/X_2 = 8m$

$$\frac{T_{st}}{T_m} = \frac{8m^2 + 8m^2}{8m (8m^2 + 1)}$$

$$= \frac{28m^2}{8m (1 + 8m^2)}$$

$$\boxed{\frac{T_{st}}{T_m} = \frac{28m}{1 + 8m^2}}$$

- Q1) A 4-pole, 3 ϕ 50 Hz IM runs on full load with a slip of 4%. The motor standstill impedance per phase $0.0 + j0.05 \Omega$. Calculate the available maximum torque in terms of full load torque. Also determine speed at which maximum torque occurs.

Given :-

$$\text{Solen} \quad S^0 \omega = U^0 / \omega$$

$$S = 0.04 = S_f = 0.04$$

$$P = 6$$

$$f = 50 \text{ Hz}$$

$$Z_2 = (0.01 + j0.05) \Omega / \text{ph}$$

$$R_2 = 0.01 \Omega / \text{ph}$$

$$X_2 = 0.05 \Omega / \text{ph}$$

To find :-

Tm in terms of Tst

and Nm at Tm

Solen

$$T \propto \frac{S E_2^2 R_2}{R_2^2 + (X_2 S)^2}$$

R E_2 remains constant
 if the supply voltage
 remains constant

$$T \propto \frac{S R_2}{R_2^2 + (S X_2)^2}$$

$$\text{where } \frac{\Phi}{\text{MT}} \propto \frac{S_f R_2}{R_2^2 + (S_f X_2)^2} \quad \text{for } A \text{ (A)}$$

$\therefore T_m \propto \frac{S_f R_2}{R_2^2 + (S_f X_2)^2}$ $\propto \frac{S_m R_2}{R_2^2 + (S_m X_2)^2}$

$\therefore T_m \propto \frac{S_m R_2}{R_2^2 + (S_m X_2)^2}$ $\propto \frac{S_m R_2}{R_2^2 + (S_m X_2)^2}$

$\therefore T_m \propto \frac{S_m R_2}{R_2^2 + (S_m X_2)^2}$ $\propto \frac{S_m R_2}{R_2^2 + (S_m X_2)^2}$

$$J_m = \frac{R_2}{X_2}$$

$$= \frac{0.01}{0.05} = 0.2$$

$$\rightarrow T_m = \frac{(0.2)(0.01)}{(0.01)^2 + (0.02)^2 (0.05)^2} \quad \left\{ K=1 \right\}$$

$$T_m = \underline{\underline{10}}$$

$$\rightarrow T_{RL} = \frac{(0.04)(0.01)}{(0.01)^2 + (0.04 \times 0.05)}$$

$$T_{RL} = 3.084$$

$$\frac{T_{FL}}{T_m} = \frac{3.084}{10} = 0.384$$

$$\therefore T_m = 2.6 T_{FL}$$

$T_m = 2.6 T_{FL}$

$$\rightarrow N_s = N_s(1-s)$$

$$\rightarrow N = N_m(1-s_m)$$

$$\cancel{N_m} \cancel{N} \cancel{1-s_m}$$

$$\cancel{N_m} \cancel{N} \cancel{1-s_m}$$

$$\cancel{N_m} \cancel{N} \cancel{1-s_m}$$

$$\rightarrow N_s = N_g(1-s)$$

at man

$$\rightarrow N_m = N_g (1-s_m)$$

$$N_g > \frac{120}{P}$$

$$> \frac{120 \times 50}{500}$$

$$> 1000$$

$$\rightarrow N_m = 1000 (1-0.2)$$

$$\underline{N_m = 800 \text{ rpm}}$$

(Q2) A 746 kW, 3 ϕ , 50 Hz, 16 Pole IM

has a motor impedance of $0.02 + j0.15 \Omega$

at standstill. The ~~for~~ full load torque

is obtained at 360 rpm. Calculate

(i) speed at which maximum torque occurs

(ii) Ratio of maximum to full load torque

(iii) The internal resistance 1 per unit to be inserted in the motor circuit to get maximum torque at start

John

(M)

$$P = 16$$

$$f = 50 \text{ Hz}$$

$$Z_2 = 0.02 + j0.15$$

$$(P_{\text{out}} = 74.6 \text{ kW}) = 0.1 P \text{ power}$$

$$\therefore R_2 = 0.02 \text{ } \Omega/\text{ph}$$

$$X_2 = 0.15 \text{ } \Omega/\text{ph}$$

$$N_{\text{mag}} = 360 \text{ rpm}$$

Now To find %:-

$$(P) \quad N_m = ?$$

$$(ii) \quad T_m / T_{fl} = ?$$

$$(iii) \quad R_m / \Omega = ?$$

John

$$N_m = N_s (1 - \delta_m)$$

(P)

$$N_s = \frac{120 f}{P}$$

$$= \frac{120 \times 50}{16}$$

$$= 375 \text{ rpm}$$

$$\rightarrow \delta_m = \frac{R_2}{X_2} = \frac{0.02}{0.15} = 0.133$$

$$N_m = 375 (1 - 0.133)$$


$$= 325 \text{ rpm}$$

(ii)

$$\rightarrow T_m \propto \frac{8m R_2}{R_1^2 + (8m X_2)^2}$$

$$= \frac{(0.133)(0.02)}{(0.02)^2 + ((0.133)(0.015))^2}$$

$$T_m = 3.33$$

 \rightarrow 

$$\rightarrow \text{To find } S_{fl} > N = N_0 (1 - S_f)$$

$$360 = 375 (1 - S_f)$$

$$S_f = 0.04$$

WKT

 T_{sf}

$$T_{sf} = \frac{T_m + 2S_m S_f}{S_m^2 + S_f^2}$$

$$\rightarrow \frac{3.33 + 2 \times 0.133 \times 0.04}{(0.133)^2 + (0.04)^2}$$

$$= \underline{\underline{1.812}}$$

(iii)

$$\text{for } T_m \text{ at start} \quad S_m = 1 = \frac{R_2}{X_2}$$

$$\therefore R_2 = X_2$$

$$R_2 = X_2 = 0.15 \Omega \rightarrow \begin{matrix} \text{(new value} \\ \text{of resistance)} \end{matrix}$$

~~Rm~~ ~~at~~ that needs to be added

in

$$R_m = 0.15 - 0.02 = \frac{0.13 \Omega / ph}{(0.02 = \text{old value of resistance})}$$

- Q3) A six pole 3ϕ , 50Hz IM develops a maximum torque of 30Nm at 960rpm . Determine the torque exerted by the motor at 5% slip. The motor resistance per phase is 0.06Ω .

Given

Given

$$P = 6$$

$$f = 50\text{Hz}$$

~~Given~~ $T_m = 30\text{Nm}$

$$N_m = 960$$

$$R_2 = 0.06 \Omega / ph$$

$$\therefore S = 0.05$$

To find

$$T_{\text{at } 5\% \text{ slip}} = ?$$

$$N / 120 * 2000 = T$$

$$\rightarrow N_m = N_B (1 - \delta m) \quad (\text{iii})$$

$$\delta m = \frac{R_2}{X_2}$$

$$N_B = \frac{120 \times 50}{P} = \frac{120 \times 50}{6} = 1000 \text{ Nm}$$

$$960 = 1000(1 - \delta m)$$

$$0.96 = 1 - \delta m$$

$$\delta m = 0.04$$

apakah MI diperlukan untuk A (dapat)

$$\rightarrow T_m = \frac{\delta m / R_2}{X_2 + (\delta m)^2}$$

MI perlu diketahui supaya kita dapat

$$\delta m = \frac{R_2}{X_2}$$

$$X_2 = \frac{0.6}{0.05} = 12 \text{ Nm}$$

$$\rightarrow T \propto \frac{SE^2 R_2}{R_2^2 + (SX_2)^2} \quad J = 9$$

E^2 = constant

$$T \propto \frac{\delta R_2}{R_2^2 + (\delta X_2)^2} \quad (K=1)$$

$$= \frac{0.05 * 0.6}{(0.6)^2 + (0.05 * 0.5)^2}$$

$$T = 0.0325 \text{ Nm}$$

$$\frac{T_m}{T} = \frac{30}{T}$$

$$\geq \frac{30}{8R_2} \times \frac{(R_2^2 + (sx_2))^2}{1}$$

$$\frac{T_m}{T} = \frac{30}{(0.05 \times 6)} \times (0.6)^2 + (0.05 \times 15)^2$$

using (Tm)

$$\frac{T_m}{T} = \frac{8mR/2}{R_2^2 + (8m \times 2)^2} \times \frac{R_2^2 + (sx_2)^2}{8R/2}$$

$$\frac{30}{T} = \frac{0.04}{0.05} \times \left\{ \frac{(0.6)^2 + (0.05 \times 15)^2}{(0.6)^2 + (0.04 \times 15)^2} \right\}$$

$$T = \underline{\underline{29.26 \text{ Nm}}}$$

MODULE - 4 ~~for 1 or 2 phases~~

SINGLE PHASE INDUCTION MOTORS

construction

- 1) Station
- 2) Rotor \rightarrow squirrel cage (or) shell-rotor

3Φ IM

1Φ IM

- | | |
|--|---|
| <ul style="list-style-type: none">1) self starting2) Flux produced in rotating field (or) (field)3) varying poles in rotor | <ul style="list-style-type: none">1) Not self starting2) Flux produced in alternating (or) (field) |
|--|---|

$3\phi \rightarrow$ stator \rightarrow air gap \rightarrow core \rightarrow current flow \rightarrow flux in air \rightarrow stator & rotor flux linkage \rightarrow torque production

1ϕ bus, 1ϕ flux varying poles in p

→ To understand why single phase induction motors are not self starting.

Let us consider Double rotating field theory


- * According to this theory, any alternating quantity (referring to flux) but can be resolved into two rotating components which rotate in opposite directions and each having magnitude half of the maximum magnitude of the alternating quantity.
- In case of single phase induction motors the stator winding produces an alternating magnetic field say Φ_s
- According to double rotating field theory consider the two rotating components of the stator flux say Φ_f and Φ_b

where $\Phi_f = \frac{\Phi_s}{2} = \Phi_b$


$$(a) \quad \Phi_f = \Phi_b = \frac{\Phi_s}{2}$$

- Φ_f is the forward component rotating in anti-clockwise direction and Φ_b is the backward component rotating in clockwise direction
- The resultant of these two components gives the resulting rotation free

At start :-



After $\theta = 90^\circ$



- (i) At start both the components are opposite to each other

Thus $\Phi_R = 0$

- (ii) After $\theta = 90^\circ$ both the components

are pointing in the same direction

hence Φ_R is the algebraic sum

of two components

continuous rotation of these two

components gives the original alternating
stator flux

- Both the components are rotating

and cut the motor conductor

and hence emf gets induced in

the motor which is called motor

current which in turn produces

motor flux ~~stator~~

- This motor current interacts with Φ_f and produces torque

in anticlockwise direction and

R_{shunt}
 I
 R_{f}
 $+ R_{\text{d}}$

motor flux
 \downarrow
 Φ_f
 \downarrow
and motor flux

the same motor sum interacts with ϕ_b and produces "torque in clockwise direction." (say -ve torque)

- At start these two torques are also in opposite direction with equal magnitudes \rightarrow Each torque tends to rotate the motor in its own respective direction
- " The net torque experienced or resultant torque experienced by the motor at start is zero!"
Hence 1Φ IM are not self starting.

→ Types of single phase induction motor:

- 1) Split phase induction motor
- 2) Capacitor start IM
- 3) Capacitor start, capacitor run IM
- 4) Shaded pole IM

winding → Stator / main
 winding → Auxiliary / starting
 (i) split phase induction motor:- → Starting
 → running

(ii)

To produce RMF, it is necessary


to have minimum two alternating
 fluxes having a phase difference $\pi/2$, the
 two.

The interaction of these two fluxes

produce a resultant flux which is

rotating in space at a speed of

synchronous speed ($N_s = 120 f/P$)



α = split phase angle

now the angle $\alpha + \alpha'$, more in

the starting torque produced

rotor in 1ϕ IM rotates in same direction as that of R.M.F


b) Split phase induction motor -

This type of motor has single phase stator winding called the main winding.


In addition to this stator carries one more winding called auxiliary winding or starting winding.

Stator winding → (a) Main winding →
more inductive in nature

Auxiliary winding → (b) Starting winding →
more resistive in nature



Circuit diagram



fit - obtain no torque using flux (ie)


I_m = current through the main winding

I_{st} = current through the starting winding

V = main supply voltage


For speed of motor reaches 75-80% of synchronous speed centrifugal switch opens
To start the motor RMF is required.

Phasor diagram :-



α is fixed it depends on starting and main winding current


ϕ_m is more, ϕ_{st} is less (more reactance) (more inductance)



Starting winding ~~is~~ has a centrifugal switch in series with it ~~which~~. When the motor attains the speed of 75 - 80% of synchronous speed, the centrifugal switch gets opened mechanically and then in running condition the starting winding gets removed ~~from~~ the circuit. As current I_m and I_{st} are splitted from each other by an angle α at start, the motor is called split phase motor.

Torque speed characteristic :-

MOTOR TIGGA



Starting torque is equal to around 150% full load torque

$$T_{st} \propto \delta$$

δ - split phase angle or

phase difference angle

- Split phase IM have poor starting torque which is 125 - 150% of full load torque
- Direction of rotation of the motor can be reversed by reversing the terminals of either main winding or auxiliary winding


Applications

- These motors have low starting current and moderate starting torque
- Used for fans, blowers, cylinders, centrifugal pumps, washing machines etc.
- They are available in the rating of $\frac{1}{20}$ to $\frac{1}{2}$ kW


M.W. rot i n g o s) m o t o r s rot i n g o s) (i n j e c t)

→ iii) Capacitor start induction motor :-

→ Current diagram




→ Phasor diagram :-



L²iii) Capacitor start capacitor run

- : rotary starters both with induction motor -



→ Depending whether the capacitor remains in the circuit permanently or is disconnected in the circuit using a centrifugal switch. Then motors are classified as -

- (i) Capacitor start IM
- (ii) Capacitor start capacitor run IM

Due to the capacitor the current I_{st} leads the voltage by an angle ϕ_{st} hence there exists a large phase difference b/w I_m and I_{st} which is

W.K.T

- ~~T_{st}~~ $T_{st} \propto (\alpha)$ more torque


Hence such motors produce a very high starting torque i.e.,

for capacitor start $I_M - T_{st}$ lies between 350 - 400% of full load torque and for capacitor start capacitor run $I_M - T_{st}$ lies below 50 - 100% of full load torque.

In case of capacitor start capacitor run I_M there is no centrifugal switch and the capacitor remains permanently in the circuit.

These motors are costly when compared to split phase induction motors

→ Torque speed characteristic






Applications

- These motors have high starting torque
- Used for compressors, conveyors, grinders, fans, refrigerators, air conditioners etc.
 - capacitor start
- Used for ceiling fans, blowers, air ventilators etc.
 - capacitor start capacitor run
- These motors are available upto 6 kW

Liv) Shaded pole induction motor :-

(only this consists of physical poles)





T-salient pole motor - has salient poles
 copper shading bands are mounted on these poles
 to convert alternating flux to RMF
 As I flows $\rightarrow \Phi$ flows \rightarrow when Φ cuts the shading bands
 \rightarrow emf gets induced in Cu shading \rightarrow current starts
 per unit length in Cu shading band \rightarrow if speed increases
 Φ of L1 \rightarrow this Cu produced Φ opposes main
 Φ (Lenz's law) (Phasor)
 Φ due to this there will be subtraction
 Φ of flux ($\Phi - \Phi_m$)
 when Cu \rightarrow produced emf is maximum
 At $t_2 \rightarrow \Phi_m$ constant \rightarrow there is no induced
 emf in Cu current is zero \rightarrow no flux
 its speed
 $t = t_3 \rightarrow \Phi_m$ reduces \rightarrow induced emf is not
 zero

due to the ~~semen~~ ~~semen~~ alternating
flux is converted to RMF.

If RMF is ~~not~~ established \rightarrow rotor
rotates and IM becomes self start.

15/4/2017



- At $t = t_1$, rate of rise of current
and hence the flux is very high.

- Due to transformer action, large emf
gets induced in the copper shading
bands and ~~induces~~ ~~induces~~ current
through the copper shading bands
producing its own flux Φ .
- By Lenz's law, the shading band
flux opposes main ^{stator} flux.
- Hence there is crowding / gathering /
accumulation of flux under the non
shaded part while there is weakening
of flux under the shaded part.
- Small magnetic axis shifts to the
non shaded part shown.

• \hookrightarrow At $t = t_2$, rate of rise of current

(or) flux is ~~at~~ almost constant i.e.,
almost zero as the flux reaches
maximum value thus

$$\frac{d\phi}{dt} = 0$$

- Hence very little ~~emf~~ gets induced
in the copper shading bands.

Thus shading band flux is almost
negligible.

- Thus it does not affect the
distribution of main stator flux,
hence the main stator flux
gets equally under both shaded
and non shaded part of pole

• \hookrightarrow At $t = t_3$, the current ~~and~~ ^{top} flux
is reducing, the rate of decrease
is high and thus a large ~~emf~~
gets induced in the copper shading
band.

- This shading band flux is in the same


- Thus there is more flux under the shaded part when compared to non shaded part.
- Thus magnetic flux lies under the shaded part of the pole.

→ During -ve half cycle

This sequence keeps on repeating for -ve half cycle also and produces the effect of rotating magnetic field which is from the non shaded part of the pole to shaded part of the pole.

∴ From → shaded to non shaded part

⇒ Torque speed characteristic :-



- Starting torque is low which is about 40 - 50% of % full load torque

- Limitations :-

- Starting torque is low.
- Power factor is also low.
- Due to I^2R losses (copper losses) in the shading band, the efficiency is very low.
- Speed reversal is very difficult.
- Size and power rating of these motor are available in the range of $\frac{1}{300}$ to $\frac{1}{20}$ KW.

- Applications:-

- Used for small fans, toy motors, advertising display, film projectors, hair dryers, photo copier machines etc.
- Available in the range of $\frac{1}{300}$ to $\frac{1}{20}$ KW

⇒ Starting and speed control of three phase induction motor :-

- Necessity of a star :-

WKT

$$I_{2u} = \frac{s E_2}{\sqrt{R_2^2 + (sX_2)^2}} \text{ Amps}$$

I_{2u} = motor current under running condition

But at start $s=1$, $N=0$

$$I_{2u} = \frac{E_2}{\sqrt{R_2^2 + X_2^2}}$$

Thus the magnitude of motor induced emf is very large at start

$$E_{2u} = s E_2$$

$$E_{2u} = E_2 \quad \{s=1\}$$

as the motor conductors are short circuited, large emf gets induced in the motor which generates very high current in the motor at start.


- when the motor current is high, consequently the stator draws a very high current from the supply. This current can be of the order of ~~5-10 times~~ 5-8 times the full load current at start.

- rotor winding terminals are available only at slip ring motor
- not and not for induction motor as internal resistance cannot be added
- To limit the high starting current, a starter is used for a three phase induction motor.


- Types of starters used for three phase induction motors :-

- 1) Station resistance starter
- 2) Auto-transformer starter
- 3) Star delta starter
- 4) Rotor resistance starter
- 5) Direct on line starter

- 1) Station resistance starter :-




- allow at start position



\rightarrow supply well \rightarrow in state reduced
the total induced emf

(ii) In been

allow at run position resistance in bypassed



when the motor picks up 20-80% of speed arrow comes to been position

$I \downarrow \rightarrow$ induced emf $\downarrow \rightarrow$ been $\downarrow \rightarrow$ motor will stop

\rightarrow Relationship between starting torque T_{st} and full load torque T_{FL} %

$$P_2 = T * W_s$$

P_2 = Rotational input power at N_s

T = torque produced

$$T \propto P_2$$

$\therefore W_s$ remains constant

WKT

relationship between P_2 , P_c and P_m is given by -

$$\left| \begin{aligned} W_s &= \frac{2\pi N_s}{60} \\ N_s &= \frac{120}{P} \end{aligned} \right.$$

= constant

$$\left| \begin{aligned} P_2 &= T \times W_s \\ P_2 &\propto P_c \end{aligned} \right.$$

$P_2 : P_c : P_m$ is $1 : s : 1-s$

$$\left[\frac{P_2}{P_c} = \frac{1}{s}; \frac{P_c}{P_m} = \frac{s}{1-s} \right]$$

where P_2 = motor E/P power at N_s in watt

P_c = motor copper loss in watt

P_m = ~~gross~~ mechanical power developed in the motor

$$\left[\begin{array}{l} \text{electrical equivalent of gross} \\ \text{mechanical power developed} \end{array} \right] \approx P_m = E_a I_a$$

$$\frac{P_2}{P_c} = \frac{1}{s}$$

$$P_2 = \frac{P_c}{s}$$

$$\frac{P_2}{P_c} = \frac{P_1}{s}$$

$$P_2 = \frac{3 I_{an}^2 R_2}{s}$$

$$I_a = \sqrt{\frac{P_2}{s R_2}}$$


for 3 phase phase winding copper loss
 $P_c = 3 I_{an}^2 R_2$

$$P_2 = \frac{3 I_{an}^2 R_2}{s}$$

$$[T \propto P_2]$$

$$\therefore \boxed{T \propto P_2 \propto \frac{I_{an}^2}{s}}$$

S. DATA
A. DATA
S. DATA
R. DATA
DDL F



Note :-

The motor current I_{2M} and the stator current are related to each other through transformer action.

$$T \propto \frac{I_1^2}{s} \rightarrow ①$$

where I_1^2 is stator current-

$$T_{2M} \propto I_1^2$$

At start $s = 1$, $T = T_{st}$ and $I_1 = I_{st}$

The stator voltage reduces by a factor ' n ' which is always less than 1

i.e., $n < 1$

and starting current proportional to this factor ' n '

If I_{se} is the normal current drawn under full rated voltage condition at start then

$$I_{st} = n I_{se}$$

Note

\therefore when $\delta \rightarrow 0$ becomes $\text{starting torque} = (n^2)$

$$T_{st} \propto \frac{(I_{st})^2}{1} \propto \left(\frac{n I_{sc}}{1}\right)^2 \quad \rightarrow (2)$$

$\delta = 1$

\hookrightarrow Under full load condition

$$S = S_f, T = T_{fl} \text{ and } I_i = I_{fl}$$

\Rightarrow becomes

$$\therefore T_{fl} = \frac{(I_{fl})^2}{S_f} \quad \rightarrow (3)$$

\therefore Dividing (2) by (3)

$$\frac{T_{st}}{T_{fl}} = \frac{\left(\frac{n I_{sc}}{I_{fl}}\right)^2}{S_f}$$

$$\frac{T_{st}}{T_{fl}} = \left(\frac{n I_{sc}}{I_{fl}}\right)^2 * S_f$$


$$\boxed{\frac{T_{st}}{T_{fl}} = n^2 \left(\frac{I_{sc}}{I_{fl}}\right)^2 S_f}$$

Note :-

As $n < 1$, the starting reduces by a fraction n^2 due to stator resistance \neq starter. ($T_{st} \propto n^2 T_f$)

↳ 2) Auto transformer starter :-

A three phase star connected auto-transformer is used to reduce the voltage applied to the motor.



At start - switch \Rightarrow Auto trans Hed side
 $(0-400)$ V can be taken

\therefore current is reduced
 reduced voltage is applied by
 varying auto H from 0 to 400 V
 $\therefore \rightarrow$ (change over switch in start condition)

- It consists of a suitable change over switch
- when the switch is in start position, the winding is supplied with reduced voltage.
- This can be controlled by tapping provided in the autotransformer
- when motor gathers 80% of normal speed, change over switch is thrown into run position and the rated voltage gets applied to stator winding

→ Relationship b/w T_{st} and T_{FL} :-

Let "n" be the fractional percentage tapping used for the autotransformer



If I_{sc} = starting motor current at rated voltage

I_{st} = starting motor current with the starter

then

$$I_{st} = n I_{sc} \rightarrow ①$$

n = fraction



There exists a fixed ratio ~~between~~ $\frac{I_{st} \text{ (supply)}}{I_{st} \text{ (motor)}}$ Dek
 between I_{st} (supply) and I_{st} (motor)
 due to auto-transformer shunt - motor (etc)

$$\boxed{I_{st} \text{ (supply)} = n I_{st} \text{ (motor)}} \quad \text{②}$$

→ At start $s=1$, $T = T_{st}$, $N = 0$

$$T_{st} \propto I_{st}^2 \text{ (motor)}$$

$$T_{st} \propto n^2 I_{sc}^2 \quad \rightarrow \textcircled{③}$$

$$T_{fl} \propto \frac{I_{fl}^2}{S_f} \quad \rightarrow \textcircled{④}$$

$$\frac{T_{st}}{T_{fl}} = \frac{n^2 I_{sc}^2}{\frac{I_{fl}^2}{S_f}} = S_f$$

$$\boxed{\frac{T_{st}}{T_{fl}} = n^2 \left(\frac{I_{sc}}{I_{fl}} \right)^2 \times S_f}$$

Note




II Starting torque reduced by η^2

3) Star - delta starter :-

Star	Delta
$V_{ph} = \frac{V_L}{\sqrt{3}}$	$I_{ph} = \frac{I_L}{\sqrt{3}}$

$$I_{ph} = I_{Lm}$$

$$\frac{V_{ph}}{I_{ph}} = \frac{V_L}{I_{Lm}}$$



squirrel cage motor

St-gives normal rot
delta voltage
connected with
motor gather
sufficient speed

Due to this
at start
per phase voltage
is limited
hence
starting
current is
reduced

V_{coz}

- Ratio of T_{st} and T_{fl}

\rightarrow Relationship between T_{st} and T_{fl} :-

W. K.T in case of autotransformer

Starter

T_{29T4}

$$\frac{T_{st}}{T_{fl}} = n^2 \left(\frac{I_{sc}}{I_{fl}} \right)^2 S_f$$

Now the factor 'n' for star-delta

Starter is $\frac{1}{\sqrt{3}}$

$$\{ n = 1/3$$

$$\therefore \frac{T_{st}}{T_{fl}} = \left(\frac{1}{3}\right) \left(\frac{I_{sc}}{I_{fl}}\right)^2 S_f$$

4) Rotor resistance starter :-


- This type of starter is applicable only for self-starting induction motor.

Initially max torque as motor gathers speed when R_s is removed

$$T \propto \frac{I_{2e} R}{S} \Rightarrow T_{fl} \propto I_{st}^2 R$$

as $R \uparrow \Rightarrow T_{st}$ improves

Not applicable for squirrel cage motor




At first station we should be stationary ~~max~~ current on internal resistance & load

20/4/2017

↳ 5) DOL starter :-

It does not reduce the supply voltage.

{ Direct on line starter }



Timer relay - sensor → senses any abnormality]
 - Protective device

Thermal overload relay - senses change in high current
 when temperature variation

→ Motor below 5 HP - DOL starter
 i.e., small rating motor - higher starting is
 present in motor for only less duration of
 time so does not affect the motor

→ Contactor - switch gear arrangement

2 Push button switches - NO & NC

T safety devices - fuses and thermal overload relay

Working (own)

↳ fees NO - contact

↳ own magnetic coil get energized

↳ attracts contactor

↳ touches the supply

stator gets supply, so motor rotates

↳ To switch off NC is pressed - circuit de-energized
contactor is to keep coil energized

T The additional contact provided, ensures that
as long as supply is ON, the coil gets supply
and keeps contactor ON until it's

Q) Determine the starting torque of 3φ in
terms of full load torque,

* when started by

(i) star delta starter

(ii) auto transformer with 50% tapping.

- The short circuit current of the motor
is 5 times the full load current and
full load MFP is $5^{\frac{1}{4}} \text{ per cent}$

Improved step starters - reference

in p. 01 - authors noted new

$$\underline{\text{Soln}} : - \% n = 50\%$$

$$n = 0.5$$

$$I_{sc} = 5 I_f$$

- $S_f = 5\%$
 $\Rightarrow 0.05$

o प्राचीन बो मध्य से प्रा विद्युत

$$\rightarrow \frac{T_{st}}{T_{fl}} = (n^2) \left[\frac{I_{sc}}{I_f} \right]^2 * S_f$$

o ज्ञात करने के लिए प्राचीन बो मध्य से प्रा विद्युत

↳ (i) Star - delta वॉल्टेज :-

$$n = \frac{1}{\sqrt{3}} \quad (\text{a}) \quad n = \frac{1}{3}$$

$$\frac{T_{st}}{T_{fl}} = \frac{1}{3} \left(\frac{5 I_f}{I_f} \right)^2 (0.05)$$

$$T_{st} = 0.416 T_{fl}$$

$$T_{st} = 41.66 \% T_{fl}$$

↳ (ii) Auto transformer वॉल्टेज

$$n = 0.5$$

$$\frac{T_{st}}{T_{fl}} = (0.05)^2 \left(\frac{5 I_f}{I_f} \right)^2 (0.05)$$

$$T_{st} = 0.3125 T_{fl}$$

$$T_{sr} = 31.25\% T_f$$

Q2) A three phase 6 pole, 50 Hz induction motor takes 60 Amperes at full load speed of 940 rpm and develops a torque of 150 Nm. The starting current at rated voltage is 300 Ampere. What is the starting torque? If a star delta starter is used, determine the starting torque and starting current.

Soln :- |||| (i) In case (i) starting is mention n_2 is not considered

Given :-

$$P = 6$$

$$f = 50 \text{ Hz}$$

$$I_{fl} = 60 \text{ A}$$

$$N_f = 940 \text{ rpm } [(or) \text{ N}]$$

$$T_{fb} = 150 \text{ Nm}$$

$$I_{sc} = 300 \text{ A}$$

- To find :-
- T_{st} = without any starter
 - T_{fl} = with star delta starter
 - I_{st} = starting current with starter

Soln :-

- Without Starter

$$\frac{T_{st}}{T_{fl}} = \frac{n^2}{1^2} \left(\frac{I_{st}}{I_{fl}} \right)^2 S_f$$

$$N_{fl} = N_s (1 - S_f)$$

$$\rightarrow N_s = \frac{120P}{\Phi}$$

$$= \frac{120 \times 50}{\Phi}$$

$$N_s = 1000 \text{ rpm}$$

$$\rightarrow 1000 = 1000 (1 - S_f)$$

$$S_f = 0.06$$

$$\rightarrow \frac{T_{st}}{150} = \frac{\left(\frac{300}{60} \right)^2 \times 0.06}{150}$$

$$\underline{T_{st} = 225 \text{ Nm}}$$

- With star delta starter

$$n^2 = \sqrt{3}$$

$$\rightarrow \frac{T_{st}}{150} \rightarrow \frac{1}{3} \left(\frac{300}{60} \right)^2 \times 0.06 = 75 \text{ N-m}$$

$$\rightarrow T_{st} = 75 \text{ N-m}$$

Wheel rotates with starting current with start

$$\frac{T_{st}}{T_{fl}} = n^2 \left(\frac{I_{sc}}{I_{fl}} \right)^2 s_f$$

$$\sqrt{\frac{T_{st}}{T_{fl}}} = n \sqrt{\frac{I_{sc}}{I_{fl}}} T_{sf}$$

$$I_{sc} = \frac{\sqrt{\frac{T_{st}}{T_{fl}}} \times I_{fl}}{n \sqrt{s_f}}$$

$$= \frac{\sqrt{\frac{75}{150}} \times 60}{\sqrt{1/3} \times \sqrt{0.06}}$$

$$= \underline{300 \text{ A}}$$

Wheel rotates with starting current (iii)

→ Speed control of three phase induction motors:-

WKT

$$N = N_s (1 - s)$$

(or)

$$s = \frac{N_s - N}{N_s}$$

From the above expression, it is seen that speed of the induction motor can be changed either by changing the synchronous speed N_s or by changing the slip (s).

Similarly, torque produced is given

by -

$$T_d = \frac{s E_2^2 R_2}{R_2^2 + (s X_2)^2}$$

$$T_d = \frac{s E_2^2 R_2}{R_2^2 + (s X_2)^2}$$

If Parameters

E_2 and R_2 are changed, then to keep the torque constant in constant load condition, the

motor ~~reacts~~ before changing its speed and in turn the speed changes.

[N_s and N_p]

→ Types of speed control
Speed control of 3 ϕ IM can be achieved from two methods

- ↳ 1) From station side
- ↳ 2) From motor side

1) From the station side :-

- ↳ (i) Supply frequency control ^{to control by varying N_s} called $(\frac{V}{f})$ method
- ↳ (ii) Supply voltage control
- ↳ (iii) Adding ~~voltage~~ rheostat in the station circuit
- ↳ (iv) Controlling the no. of stator poles to control N_s

2) ↳ From the motor side :-

- ↳ (i) Adding external resistance in the motor circuit

- L(iii) Cascade control
- L(iii) Inputting ulp frequency voltage on the motor circuit.

→ i) From the stator side :-

- L → (i) Supply frequency control or ($\frac{V}{f}$) method :-

w.r.t

$$N_s = \frac{120f}{P}$$

thus by controlling the supply frequency 'f' smoothly synchronous speed can be controlled over a wide range.

- The expression for air gap flux is given by -

$$\Phi_g = \frac{1}{4.044 K_{ITph}} \left(\frac{V}{f} \right)$$

Due to transformer action

[For motor or generator = $T = N \cdot \text{No. of turns}$
For Transformer = $N = \text{No. of turns}$

$$\Phi_g = \frac{1}{4.044 K_{ITph}} \left(\frac{V}{f} \right)$$

where

K_1 = Stator winding constant

T_{pn} = Stator turns per phase

V = Supply voltage

f = Supply frequency

(N)


3Φ

415V


50Hz

AC supp

- It can be seen that if the supply frequency f is changed, the value of air gap a also gets affected.
- This results saturation of stator and motor poles cores and hence it is necessary to maintain air gap a constant.
- To achieve this, along with frequency f , supply voltage V also must be changed and ratio of V/f should be maintained constant.
- Hence this method is called V/f control.



→ Torque vs. slip characteristics :-



f = supply frequency

$f_1 = f_2$ = variable frequency

f_1 = frequency greater than supply frequency

f_2 = frequency less than supply frequency

• → (iii) Supply voltage control :-

w.k.t

$$T \propto \frac{SE_2^2 R_2}{R_2^2 + (Sx_2)^2}$$

E_2 = motor induced emf at standstill

E_{2r} = motor induced emf at running

E_2 depends on supply voltage V

$$E_2 \propto V$$

- For low slip region ($s < 1$)

Note :-

A 3 ϕ IM operates majority in the low slip region.

Thus neglecting $(s x_2)^2$

$$\therefore T \propto \frac{SV^2 R}{R_s^2}$$

assume R_s ~~remaining~~ remains constant
(squirrel cage motor)

$$\therefore T \propto SV^2$$

- If the supply voltage is \downarrow in reduced ~~then~~, torque also decreases.

* - But to sustain the same load it is necessary to develop the same torque, hence slip increases

so that the torque remains same.

Step increase means the motor rotates by running at lower speed.


In this method due to reduction in voltage, the current drawn by the motor increases

- * Large change in voltage is necessary for small change in speed.
- * Additional voltage changing equipment is necessary.


→ (iii) Adding rheostats in the stator

Circuit :-

3φ supply



stator of IM



squirrel cage motor

- Reduced voltage can be applied to the stator by adding rheostat in the stator circuit.
- A part of the supply voltage gets dropped across the rheostat and in turn reduces the voltage applied to the stator.
- This causes a reduction in speed.

Disadvantage

- There are large power loss due to the rheostats.
- L → iv) controlling no: of poles in the stator :-

- L → → • (a) consequent poles method
 L → → • (b) multipole stator winding method

- In this method it is possible to have 1, 2, 4 or 8 speeds in steps, by changing the no: of stator poles.

- A continuous smooth speed control is not possible by this method.

↳ → (a) consequent poles method :-

- In this method, connections of the stator winding are changed with the help of simple switching technique.
- Due to this, the no's of stator poles gets changed in the ratio $2:1$.
- Hence, either of the two synchronous speeds can be selected.

↳ → (c) multiple stator winding method :-

- In this method instead one winding, two separate stator windings are placed in the stator poles.
- The windings are placed in the same stator slots, but are electrically isolated from each other.
- Each winding is divided into coils to which the pole changing with consequent pole method is provided.

Limitations

- 1) Can be applied to squirrel cage motors ~~but only wdg suspended~~
- 2) Smooth speed control is not possible, only steps changes in speed is possible
- 3) Two different stator windings are required to be wound, which increases the cost.
- 4) Complicated design

~~L₂) Power~~

~~2) Speed control from motor side :-~~

~~L₂) Adding internal resistance to motor circuit -~~

~~W.K.T~~

$$T_2 \propto \frac{SE^2 R_2}{R_2^2 + (sX_2)^2}$$

~~for now H.P. unchanged~~

$$(sX_2) \propto R_2$$

$$T_2 \propto \frac{SE^2 R_2}{R_2^2}$$

If E_2 is assumed to be constant for constant supply V_g


$$S \left| T \propto \frac{S}{R_2} \right.$$

So As $R_2 \downarrow \rightarrow T \uparrow$
 as $S \downarrow \rightarrow$ speed \downarrow
 smooth speed control below rated
 speed is possibl.


$R_2 \uparrow$
 $T \downarrow$ but $S \uparrow$
 so speed \uparrow

- Advantages
 - By increasing R_2 , speeds ~~more~~ below normal speed can be achieved
 - The starting torque of the motor increases proportional to the increase in motor resistance.
- Disadvantages
 - Large speed changes are not possible
 - cannot be used for variable ~~motor~~ IM
 - Speed above normal speed cannot be achieved
 - Large power loss due to $I^2 R$ losses
 - Efficiency is low.

\hookrightarrow (iii) Cascade control :-



Cascade control of IM



- In this method, 2IM are mounted on the same shaft, first motor called the main motor is slipping IM.
- Second motor called Auxiliary motor can be slip ring or several each IM.

operation

- The supply to the main motor is from 3Ø ACN.
- The supply to the auxiliary motor is derived at a slip frequency from the slip rings of main motors.

- This is called cascading of motors
- If the torque produced by the motors act in the same direction, then the motor resistance decreases and is called ~~cumulation~~ cascading
- If the torque produced by the motors are in opposite direction then the motor resistance increases called differential cascading

Let

P_A = no. of poles of the main motor

P_B = no. of poles of the auxiliary motor

f = frequency of supply

f_A = frequency of ~~not~~ motor

f_A = frequency of main motor induced emf

f_B = [frequency of motor induced emf of auxiliary motor] ×

↳ input frequency to the auxiliary motor.

$$\text{Pole}, f_A = f_B$$

N = speed of the ~~not~~ motor rev

$$\text{Q} \quad \frac{148.06}{39} = 3.74$$

→ Synchronous speed of main motor

$$N_{SA} = \frac{120 f_A}{P_A}$$

$$N_{SA} = \frac{120 f}{P_A} \quad \text{(m)}$$

Slip of main motor

$$\% S_A = \frac{N_{SA} - N}{N_{SA}} * 100$$

$$S_A = \frac{N_{SA} - N}{N_{SA}} \rightarrow ①$$

$$f_A = S_A f$$

w.k.t

$$f_B = f_A = S_A f = \frac{120 S_A}{P_B} = \frac{120 f_{SA}}{P_B}$$

→ Synchronous speed of auxiliary motor :-

$$N_{SB} = \frac{120 f_{BA}}{P_B}$$

$$= \frac{120 f_B}{P_B}$$

$$N_{SB} = \frac{120 S_A}{P_B} \rightarrow ②$$

Sub ⑥ von ②

$$N_{SB} = \frac{120}{P_B} \left[\frac{N_{SA} - N}{N_{SA}} \right]$$

under no load condition

$$N \geq N_{SB}$$

$$N = \frac{120}{P_B} + \left[\frac{N_{SA} - N}{N_{SA}} \right]$$

$$\Rightarrow \frac{120}{P_B} \left[1 - \frac{N}{N_{SA}} \right]$$

-> The result return int re

R. from (m)

$$N = \frac{120f}{P_B} \left[1 - \frac{N}{\frac{120f}{P_A}} \right]$$

Simplifying

$$N = \frac{120f}{P_A + P_B}$$

for cumulative cascading

$$N = \frac{120f}{P_A - P_B}$$

for differential cascading

Thus the speed of n is decided by total no: of poles equal to $P_A + P_B$ for ~~some~~ cumulative cascading

$P_A - P_B$ for differential cascading


L → (iii) Injecting slip frequency voltage

in the motor circuit :-

In this method voltage V_{mf} having the slip frequency is injected into the motor circuit.

- It is possible that the injected slip frequency voltage may oppose the motor induced V_{mf} thus the effective motor resistance increases
- If the injected slip frequency voltage assists or helps the motor induced V_{mf} (in phase) then effective motor resistance decreases

rotor induced emf
emf → internal speed emf



f There are two methods available for this principle -

(i) Krämer system


Steer

(ii) Senechal system


object of view below

horizontal mirror

→ (i) Krämer system :-



Kraman system



slip frequency ω_s is needed to be injected
slip wings of MM is connected to slip
wings of RC

converter \rightarrow converts DC and AC

DC motor and RC are connected electrically
MM and DC motor are connected mechanically
(coupling)

\rightarrow R.M.F is produced \rightarrow rotor speeds rotating
2 additional motors / equipment \rightarrow lost

in motor

\downarrow vary \rightarrow R \rightarrow current changes (DC)
from change \rightarrow Induced \rightarrow produced
then given to RE through RC bushes
RE convert DC to AC

(Speed remains same throughout as
From RC \rightarrow to slip ring goes
 \rightarrow to main motor so injecting
frequency vary into the main motor)

then \rightarrow rotor induced amp if these two
slip ring frequency changes will

- Advantages

- Smooth speed control is possible
- Wide range of speed control is possible

- Design of motor converter is independent of speed control.

- Disadvantages

a) - It can be used only ~~for~~ for speed control slip using IM


- To control the speed of motor two additional equipments i.e., a DC shunt motor and a motor converter is required which increases the overall cost.

- Application

- used for speed control of motor of 4000 KW in steel rolling ~~not~~ mills

Q. (iii)

Semiblank system :-



- \rightarrow 3 ϕ AC supply \rightarrow main motor \rightarrow (i) \leftarrow
- speed to be controlled
 emf induced in MM \rightarrow ii fed fed
- \rightarrow From slip ring to shuntless machine

Regulating transformer \rightarrow SLP of shuntless machine keeps changing by varying it

from brush ii fed back to MM slip ring

shuntless operates at slip frequency
 \rightarrow emf in produced \rightarrow SLP frequency
 emf ii fed back to main motor

\rightarrow Auxiliaries
 i is used to control the SLP of shuntless machines under control

at MM \rightarrow {
 \rightarrow slip frequency emf
 \rightarrow motor induced emf

Drawbacks of DPM

cost	R	high
initial	per unit	SLP is very small

→ MODULE - 3

PERFORMANCE OF

THREE PHASE

DIAGRAM :-

Losses in an Induction motor :-

↳ 1) Core losses

↳ 2) Copper losses

↳ 3) Mechanical losses - friction and
windage losses

(loss)

→ Power flow diagram of a 3Φ IM :-

- Various stages of conversion is called
the power flow of an IM.

- Let P_{in} = be the net electrical
input power to the motor

$$P_{in} = \sqrt{3} V_L I_L \cos \phi$$

$$P_{in} = \sqrt{3} V_L I_L \cos\phi$$


where V_L = line voltage
 I_L = line current
 $\cos\phi$ = Power factor of the motor

This is nothing but stator input

- Part of this input power is wasted
 || to supply the stator core loss
 as well as copper loss
- The remaining power is delivered
 to the motor magnetically through
 the air gap with the help of

RMF

- This is called motor input
 power denoted by P_2



$$P_2 = P_{in} - (\text{stator core + stator copper loss})$$

$$P_{in} = P_2 + \text{stator & rotor losses}$$

- The motor is not able to convert its entire input (P_2) to mechanical power as has to supply motor losses

- The motor iron losses are very small because of motor frequency (for) is very less


for = 8% in induction value
 - Thus effectively the motor P1P (P_a) has to supply not only the motor copper losses only
 - Thus motor copper losses are given by
- $P_{Cu} = 3 I_{2a}^2 R_2 \rightarrow$ (for slip ring only due to R_2)
- I_{2a} = motor current under running
- R_2 = rotor resistance
- $P_m = P_a + \text{static}$
 $P_a = 3 I_{2a}^2 P_s$
 $P_s = P_m + P_{Cu}$
- After supplying the motor copper loss the remaining part of P_a is converted into mechanical power called gross mechanical power developed by the motor denoted by P_m
- $\boxed{P_2 = P_a + P_{Cu}}$


- This power P_m , the motor tries to deliver to the load connected via the shaft.
- But during this mechanical transmission, part of P_m is utilised to overcome the mechanical losses (Friction + windage).
- Finally the power available at the shaft end of the motor is called net output power of the motor denoted by P_{out}

$$P_m = \text{Power} + \text{mech. loss}$$

$$P_{out} = P_m - \text{mechanical losses}$$

* The power flow diagram is as shown -





→ Relationship between P_2 , P_c and P_m :-

Rotor $\frac{dP}{dt}$

Let T = gross torque developed by the motor in N-m

$w \cdot kT$

$$P = T \times w$$

where $w = \frac{2\pi N}{60} \text{ rad/sec}$

where N is in rpm

Now the motor input - P_2 is

R_2 through RMF which is
rotating at synchronous speed N_s .

Thus the corresponding torque developed
by the motor and P_2 is given
by

$$P_2 = T * N_s$$

where $N_s = \frac{2\pi N_s}{60}$ rad/sec

$$N_s = R_s \text{ in rpm}$$

$$P_2 = T * \frac{2\pi N_s}{60}$$

The motor tries to deliver this
torque to the load

Thus the motor output P_m and
torque T is related by

$$P_m = T * w$$

$$P_m = T * \frac{2\pi N}{60} \quad \rightarrow (2)$$

New

~~P_m~~

$$P_m = P_2 - P_e$$

$$P_e = P_2 - P_m$$

$$\Rightarrow \cancel{P_e} = T \times \frac{2\pi N_s}{60} - T \times \frac{2\pi N}{60}$$

$$P_e = T \times \frac{2\pi}{60} [N_s - N] \quad \rightarrow ③$$

↳ motor in losses

Dividing eqn ③ by ①

$$\frac{P_e}{P_2} = \frac{\frac{T \times 2\pi}{60} [N_s - N]}{\frac{T \times 2\pi}{60} \times N_s}$$

$$\frac{P_e}{P_2} = \frac{N_s - N}{N_s}$$

$$\frac{P_e}{P_2} = S$$

-; motor northumb no p Efficiency E ←

$$\frac{P_e}{P_2} = S$$

$$P_e = S P_2$$

$$P_2 = \frac{T \times N_s}{60}$$

$$P_m = T \times \frac{2\pi N}{60}$$

$$P_m = N_s - N = P_e$$

$$P_m = P_2 - P_c$$

$$= P_2 - s P_2$$

$$P_m = P_2 (1 - s)$$

$$\frac{P_m}{P_2} = (1 - s)$$

$$P_2 : P_c : P_m = 1 : s : (1 - s)$$


Note :-

The road torque is the net output torque or useful torque given by

$$T_{rh} = \frac{P_{out}}{\omega} \text{ N-m}$$

→ Efficiency of an induction motor :-

$$\% \eta = \frac{P_{out}}{P_{in}} * 100$$



(i) A 4 pole, 50Hz, 3Ø IM, running on full load with 4% slip develops a torque of 149.3 N-m at its pulley rim (T_m). The friction and windage losses are 200W, the stator copper and iron losses are 1620Watt, calculate.

- (i) D/P power
- (ii) Rotor Cu losses
- (iii) Efficiency at full load

Given

$$P = 6$$

$$f = 50 \text{ Hz}$$

$$\delta = 4\% = 0.04$$

$T_m = 149.3 \text{ Nm}$

$P_{fr} = 200 \text{ W} = \text{friction and windage losses}$


$P_d = 1620 \text{ W} = \text{stator iron and Cu losses}$

To find :-

(i) $P_{out} = ?$

(ii) $P_e = ?$

(iii) $\% \eta = ?$



$$\rightarrow N_s > \frac{120f}{P}$$

principle: $N_s > \frac{120 \times 50}{f}$, $f = 500$ Hz, N_s be in A (i)

principle: $N_s > \frac{120 \times 50}{f}$, $f = 500$ Hz, N_s be in A (i)

$$\rightarrow s > \frac{N_s - N}{N_s}$$

principle: $N_s = N_r + s N_s$, $N_r = 1000$ rev/min

principle: $N_s = N_r + s N_s$, $N_r = 1000$ rev/min

$$\rightarrow 1000 - 0.004 \times 1000$$

$$= 960 \text{ rev/min}$$

$$\rightarrow P_{out} = T_m \times \omega$$

$$\approx 149.3 \times \frac{2\pi \times 960}{60}$$

$$\rightarrow 15.009 \text{ kW}$$

~~$R_e = \frac{s}{1-s}$~~

~~$R_e = \frac{\theta_0}{1-\theta_0}$~~

$P_{\text{out}} = P_{\text{m}}$

from power flow diagram

$$P_{\text{out}} = P_m - \text{Mechanical loss}$$

$$P_m = P_{\text{out}} + \text{Mech loss}$$

$$= (15.009 + 1.02) \text{ kW}$$

$$= 15.209$$

$$P_m = \underline{\underline{15.209 \text{ kW}}}$$

$$\rightarrow \frac{P_e}{P_m} = \frac{s}{1-s}$$

$$P_e = 15.209 \times 0.04$$

94.08% of power is lost due to A (6)

$$94.6 \text{ kW} = 0.6337 \text{ kW}$$

$$P_{\text{el}} = \underline{\underline{0.6337 \text{ Watts}}}$$

$$\rightarrow \% \text{ loss} = \frac{P_{\text{out}}}{P_m} \times 100 \text{ % loss, VDZ}$$

$$P_2 = P_m - \text{total iron loss} \quad (i)$$

$$P_{\text{in}} = P_2 + \text{loss} \quad (ii)$$

$$\frac{P_2}{P_e} = \frac{1}{s} \text{ iron loss INT} \quad (iii)$$

$$P_2 = \frac{P_e}{s}$$

$$> \frac{633.7}{0.04}$$

$$= 15.84 \text{ kW}$$

$$P_{in} = (15.84 + 1.62) \text{ kW}$$

$$> 17.46 \text{ kW}$$

$$\% \eta = \frac{15.009}{17.46} * 100$$

$$\approx 85.96\%$$

(2) A 6 pole 3φ IM develops 30HP including mechanical losses of 2HP at a speed of 950 rpm on

550V, 50Hz supply. Power factor is 0.58. Calculate for this load

- (i) Slip
- (ii) Rotor copper loss
- (iii) Total i/p if stator losses are 2000W
- (iv) The efficiency
- (v) The max current

John

$$P = 6$$

$$P_{out} = 30 \text{ HP}$$

$$= 30 \times 735.5$$

$$= 22065 \text{ Watts}$$

$$f = 50 \text{ Hz}$$

$$N_s = 950 \text{ rpm}$$

$$\text{mechanical loss} = 2 \text{ HP}$$

$$= 2 \times 735.5$$

$$= 1471 \text{ watts}$$

$$V_L = 550 \text{ V}$$

$$\cos\phi = 0.58$$

$$\text{stator loss} = 2 \text{ KW}$$

To find :-

$$(i) S = ?$$

$$(ii) P_C = ?$$

$$(iii) P_{in} = ?$$

$$(iv) \% \eta$$

$$(v) I_L$$

$$(vi) f_m$$

$$\rightarrow N_s = \frac{120f}{P}$$

$$= \frac{120 \times 50}{6}$$

$$= 1000$$

$$\rightarrow S = N_s(1-s)$$

$$= 1000(1 -$$

$$\rightarrow \eta = \frac{N_s - N}{N_s}$$

$$\approx \frac{1000 - 950}{1000}$$

$$\eta \rightarrow \underline{0.05}$$

$\rightarrow P_e$

$$P_m = P_{out} + \text{Mech Loss}$$

$$\approx 22065 + 1471$$

$$\approx \underline{230536 \text{ KW}}$$

$$\rightarrow \frac{P_e}{P_m} = \frac{\eta}{1-\eta}$$

$$P_e = \frac{(0.05)(230536)}{(1-0.05)}$$

$$\approx \underline{10238 \text{ KW}}$$

$$\rightarrow P_{in} = P_2 + \text{Mech Loss}$$

$$P_2 = \frac{P_e}{\eta}$$

$$\approx 24076$$

$$P_{in} = 24076 + 2$$

$$= \underline{26076 \text{ KW}}$$

efficiency = $\frac{P_{out}}{P_{in}} \times 100$ (eq)

more efficiency to primitive or MI

Efficiency = $\frac{220065}{26076} \times 100$
more efficiency = 82.028 %

Efficiency = 82.045 %

$$\rightarrow P_{in} = \sqrt{3} V_L I_L \cos \phi$$

Efficiency = $\frac{P_{in}}{\sqrt{3} V_L I_L \cos \phi}$ (i)

$$I_L = \frac{P_{in}}{\sqrt{3} V_L \cos \phi}$$

= $\frac{26774.6}{\sqrt{3} \times 550 \times 0.58}$ A

A = 48.45 A

48.45 A - more current (ii)

$$\rightarrow f_m = S_f$$

$$> 0.005 \times 50$$

$$> 2.5 \text{ Hz} = 2.5 \text{ cycles/sec}$$

$$\approx 2.5 \times 60 \text{ cycles/min}$$

$$f_m = 150 \text{ cycles/min}$$

Q3) A 25 kW, 4 pole, 3 phase 50 Hz IM is running at 1410 rpm supply full load. The mechanical losses are 850 W and stator losses are 1.07 times motor iron loss on full load.

Calculate

- (i) Gross mechanical power developed
- (ii) Motor copper losses
- (iii) Value of motor resistance / phase
If the motor current on full load / phase
is 65 A
- (iv) Full load efficiency

Given

Given

$$P_{\text{rated}} = 25 \text{ kW} \Rightarrow P_{\text{out}}$$

$$P = U$$

$$f = 50 \text{ Hz}$$

$$N = 1410 \text{ rpm}$$

$$\text{Mech loss} = 850 \text{ W}$$

$$\text{Stator loss} = 1.07 * \text{iron loss}$$

To find

- P_m
- P_e
- R_m

$$N_3 = \frac{120f}{P}$$

$$\rightarrow \frac{120 \times 50}{2} = 1500 \text{ rpm}$$

$$\eta = \frac{1500 - 1410}{1500} = 0.06$$

$$P_m = P_{out} + \text{mwh loss}$$

$$\approx (25 + \cancel{11} 0.85) \text{ kW}$$

$$= 25.$$

$$\left\{ A_2 \cdot P_c \% \cdot P_m \approx 103\% \right.$$

$$\Rightarrow \frac{P_c}{P_m} = \frac{25.85 \text{ kW}}{1+0.06}$$

$$P_c = 25.85 \times 0.06$$

$$= 1.65 \text{ kW}$$

$$\rightarrow P_c = 3 I_{2m}^2 R$$

$$\rightarrow R_2 = \frac{P_e}{3 I_{2a}^2}$$

$$= \frac{1.65000}{3 \times (65)^2}$$

$$= \underline{0.0195 \Omega} \quad \underline{0.130 \Omega}$$

$$\rightarrow \eta = \frac{P_{out}}{P_{in}} \times 100$$

$$P_{in} = P_2 + \text{loss}$$

$$P_2 = \frac{P_e}{\delta}$$

$$= 26.75$$

$$= 27.05 \text{ KW}$$

$$\text{stator loss} = 1.7 \times \text{loss}$$

$$> 1.7 \times P_e$$

$$> 1.7 \times 1650$$

$$= 2805$$

$$= 2.805 \text{ KW}$$

$$P_{in} = 27.05 + 2.805$$

$$= 30.30$$

$$\% \eta = \frac{P_{out}}{P_{in}} * 100$$

$$= \frac{25}{30.3} * 100$$

$$= 82.49 \%$$

\Rightarrow Equivalent circuit of a 3Φ IM :-

- 3Φ IM can be treated as a generalised transformer
- If E_1 = emf induced in stator per phase
- E_2 = rotor induced emf per phase on standstill

Transformation ratio $K = \frac{\text{motor turns}}{\text{stator turns}}$

$$K = \frac{\text{motor turns}}{\text{stator turns}}$$

$$K = \frac{E_2}{E_1}$$

If V_1 is the supply voltage per phase given to the stator, it produces the flux (Φ_{NP}) which links with both stator and motor.

In running condition E_2 becomes E_{2u}

$$E_{2u} = 5 E_2$$

Now E_{2u} = motor induced emf
per phase in running condition

R_2 = motor resistance per phase



X_{2u} = motor reactance per phase

in running condition.

R_1 = stator resistance per phase

X_1 = stator reactance per phase



thus the induction motor can be represented as a transformer, as shown.



Note :-

- When I_m is on no load, it draws current from the supply to produce flux in air gap and to supply iron losses.
- This current I_0 has two ~~more~~ components I_m and I_c .
- I_m = magnetizing component which ~~sustains~~ sets up the flux in the core and air gap
- I_c = active component which supplies

$$R_o = \frac{V_1}{I_c} ; X_o = \frac{V_1}{I_m}$$



Basic equivalent circuit

Rotary current in running condition is given by -

$$I_{2m} = \frac{E_{2m}}{Z_{2m}}$$

$$= \frac{E_{2m}}{\sqrt{R_2^2 + (sX_2)^2}}$$

$$= \frac{sE_2}{\sqrt{R_2^2 + (sX_2)^2}}$$

Note :-

As the load on the motor changes, the speed of the motor also changes. Thus slip changes and hence the reactance X_m also changes and is shown as a variable reactance.

Representation of motor Impedance :-

w.r.t

$$I_{dm} = \frac{\beta E_2}{\sqrt{R_2^2 + (\beta E_2)^2}}$$

∴ Neglects
No. and one by β^2

$$I_{dm} = \frac{E_2}{\sqrt{\left(\frac{R_2}{\beta}\right)^2 + \left(\frac{\beta E_2}{\beta}\right)^2}}$$

$$\boxed{I_{dm} = \frac{E_2}{\sqrt{\left(\frac{R_2}{\beta}\right)^2 + (X_2)^2}}}$$

- || Thus it is assumed that the equivalent motor ~~motor~~ has a fixed reactance X_2 , fixed voltage E_2 but

a variable resistance $\frac{R_2}{s}$

- 9.10.19

Now $\frac{R_2}{s}$ can be written as

$$\frac{R_2}{s} = R_2 + \frac{R_2}{s} - R_2$$

$$= R_2 + R_2 \left[\frac{1}{s} - 1 \right]$$

$$\frac{R_2}{s} = R_2 + R_2 \left[1 - \frac{s}{s} \right]$$

the variable rotor resistance $\frac{R_2}{s}$

has two parts

i) Rotor resistance R_2 itself which represents copper loss

ii) $R_2 \left(1 - \frac{s}{s} \right) R_1$ which represents the load resistance R_1 which is

called electrical equivalent of mechanical load on the motor.

[$X_{ar} =$ armature reaction reactance]

$$\text{Note :- } R_L = R_2 \left(\frac{1-s}{s} \right)$$

The mechanical load on the motor



is represented by the frictional

resistance R_L


$$R_L > R_2 \left(\frac{1-s}{s} \right)$$

→ Thus the motor equivalent circuit

can be shown as Driver - Motoring



$$E_2 = R_2 + s X_{2m}$$



Equivalent circuit supplied to stator :-

Transfer all the motor parameters to the stator

w.k.t

$$K = \frac{E_2}{E_1} \rightarrow \text{transformation ratio}$$

$$\therefore E_2' = \frac{E_2}{K}$$

The motor current I_{2m} when transferred

to the stator becomes I_{2m}'

$$R_L = R_2 \left(\frac{1-s}{s} \right)$$

$$I_{2m}' = K I_{2m}$$

$$= K \frac{s E_2}{\sqrt{R_2^2 + (sX_2)^2}}$$

$$R_2' = \frac{R_2}{K^2}$$


$$X_2' = \frac{X_2}{K^2}$$


$$R_L = R_2' \left(\frac{1-s}{s} \right)$$

$$R_L = \frac{R_2}{K^2} \left(\frac{1-s}{s} \right)$$

Thus R_L' is the required mechanical load on the stator


Thus the equivalent circuit required to the stator is as shown -





Approximate equivalent circuit:-

By shifting the exciting ~~at~~ circuit [R₀ and X₀] to the left of R₁ and X₁, we get the approximate equivalent circuit. Due to this, we are neglecting the drop across R₁ and X₁ due to I₀ which is very small.



R_{ie} = vertical equivalent of mechanical resistances

R_{ie} = equivalent resistance offered
to stator

$$R_{ie} = R_1 + R_2'$$

X_{ie} = equivalent reactance offered
to stator

$$X_{ie} = X_1 + X_2'$$

$$\vec{I}_1 = \vec{I}_o + \vec{I}_{2u}'$$

where

$$\vec{I}_o = \vec{I}_c + \vec{I}_m$$

$$Z_{ie} = R_{ie} + j X_{ie}$$

→ Phasor diagram of induction motor :-

- Phasor diagram of loaded I_m is
similar to a loaded transformer.

- Let Φ = magnetic flux which links
both stator and rotor = [RMF]

There is self induced emf E_1 in the
stator and mutually induced Emf
Emf in the motor under running

Let R_1 = stator resistance per phase

X_1 = stator reactance per phase

The supply voltage V_1 has to overcome self induced emf E_1 and also supply voltage drops $I_1 R_1$ and $I_1 X_1$.

$$\vec{V}_1 = -\vec{E}_1 + \vec{I}_1 R_1 + \vec{I}_1 X_1$$

$$\vec{V}_1 = -\vec{E}_1 + \vec{I}_1 (R_1 + jX_1)$$

$$\vec{V}_1 = -\vec{E}_1 + \vec{I}_1 Z_1$$

motor induced emf in running condition

has to supply drop across impedance as the motor is short circuit.

$$\therefore \vec{E}_{2m} = \vec{I}_{2m} R_2 + \vec{I}_{2m} X_{2m}$$

$$\vec{E}_{2m} = \vec{I}_{2m} (R_2 + jX_{2m})$$

$$\vec{E}_{2m} = \vec{I}_{2m} Z_{2m}$$


$$I_{2n}^1 = K T_{2n}$$

$$\vec{I}_1 = \vec{I}_{10} + \vec{I}_{2m}$$

→ Steps to draw phase diagram :-

- take ϕ as reference phasor
 - The induced emf E_1 lags ϕ by 90°
 - Show $-E_1$ by reversing uphase E_1 .
 - Phasor E_{2m} is in phase with E_1 .
 - Show I_{2m} lagging E_{2m} i.e., E_1 by an angle ϕ_{2m}
 - Show $I_{2m} R_2$ in phase with I_{2m} and ~~$I_{2m} X_{2m}$~~ leading resistive drop by 90° to get the next location of E_{2m}
 - Reverse I_{2m} to get I_{2m}'
 - I_m is in phase with ϕ and I_e is at 90° leading with ϕ .
 - Add I_m and I_e to get I_o
 - Add I_o and I_{2m}' to get I_i
 - From the N.P.O - 1, add $I_i R_1$ in phase with I_i and $I_i X_1$ at 90° leading to I_i to get

- Angle b/w V_1 and I_1 in ϕ_1



$$\vec{I}_0 = \vec{I}_e + \vec{I}_m$$

$$\vec{I}_1 = \vec{I}_0 + \vec{I}_{2m}$$

$$\begin{aligned} \vec{V}_1 &= -\vec{E}_1 + \vec{I}_{1R} \\ &\quad + \vec{I}_{1X} \end{aligned}$$

$$\begin{aligned} \vec{E}_{2m} &= \vec{I}_{2m} R_2 \\ &\quad + \vec{I}_{2m} X_{2m} \end{aligned}$$


→ Circle diagram of a $3\Phi IM\%$ -

- To plot the circle diagram of $3\Phi IM$, two tests are conducted

(i) No load (on) open circuit test :-

(ii) Break motor (on) short circuit test :-

(iii) No load test on $3\Phi IM\%$:-



Tabular column :-

Sl. No.	V_0 (volt)	T_0 (Nm)	w_1 (watts)	w_2 (watts)	$w_0 = w_1 + w_2$ (watts)
1)	no load				

If P_f is low \rightarrow reactive power is more
means \int

- \therefore M.T.P.F. on no load is very low
 \hookrightarrow I_m decreases reactive power
 \hookrightarrow Wattmeter measures only active power
 \therefore Wattmeter reads back
 \therefore Interchange L and V
 \hookrightarrow So L.P.F. Wattmeter is used
 \hookrightarrow on no load P.F. is low
- Calculations are :-

i) No load power

$$W_0 = \sqrt{3} V_0 I_0 \cos \phi_0 \text{ watts}$$

$$\cos \phi_0 = \frac{W_0}{\sqrt{3} V_0 I_0}$$

$$\phi = \tan^{-1} \left[\frac{W_0}{\sqrt{3} V_0 I_0} \right]$$

where V_0 and I_0 are rms value

ϕ_0 = power factor angle at no load

Parameters of the equivalent circuit are obtained as follows -

$I_c = I_0 \cos \phi_0 \rightarrow$ active component of the no load current

$I_m = I_0 \sin \phi_0 \rightarrow$ reactive component of the (or) magnetising component of no load current.

$$R_o = \frac{V_o}{I_e}$$

$$= \frac{V_o}{I_o \cos \phi_o}$$

$$X_o = \frac{V_o}{I_m}$$

$$= \frac{V_o}{I_o \sin \phi_o}$$

The no load input W_o consists of

i) stator copper loss i.e., $3 I_o^2 R_s$

ii) stator core loss

iii) friction and windage loss

Effectively W_o = fixed losses (or) constant losses

(ii) Blocked motor test :-

In this test, the motor is blocked manually and is not allowed to rotate

Then $s = 1$ (maximum)

$$\therefore R'_L = R'_2 \left(\frac{1-s}{s} \right)$$

$$\therefore R'_i = R'_2 \left(\frac{1 - \frac{1}{s}}{\frac{s}{s-1}} \right) \quad \text{at } s=1$$

$$R'_i = R \cdot 0$$

If this test is similar to short circuit test on a transformer

when supply is switched on and rated current is passed through the IM at a reduced voltage.

Def. $V_{sc} =$ short circuit induced voltage (line value)

I_{sc} = short circuit current
(or) rated current (line value)

$W_{sc} =$ short circuit S.P. power

$$W_s = \sqrt{3} V_{sc} I_{sc} \cos \phi_{sc} \text{ watts}$$


$$\cos \phi_{sc} = \frac{W_{sc}}{\sqrt{3} V_{sc} I_{sc}}$$

$$\therefore \phi_{sc} = \cos^{-1} \left[\frac{W_{sc}}{\sqrt{3} V_{sc} I_{sc}} \right]$$

ϕ_{sc} is short circuit power factor angle

Sl. No:	Vse (volts)	Ise (amps) Rated	W ₁ (watts)	W ₂ (watts)	W _{se} = W ₁ + W ₂

Equivalent circuit is as shown -



$$W_{se} = 3 I_{se}^2 R_{ie}$$

[R_{ie} consumes power]

$$R_{ie} = \frac{W_{se}}{3 I_{se}^2} \Omega/\text{ohm}$$

R_{ie} = equivalent resistance referred to stator

$$Z_{ie} = \sqrt{R_{ie}^2 + X_{ie}^2}$$

$$X_{ie} = \sqrt{Z_{ie}^2 - R_{ie}^2}$$

Note

During this test the stator carries rated current and thus losses are dominant.

Similarly motor also carries short circuit component and thus losses are dominant.

→ applied voltage is low → iron losses are low (so neglected)

$W_{se} = \text{stator copper loss} + \text{motor copper loss}$
(variable losses)

I_{sc} → short circuit current at reduced voltage

I_{sn} → full rated voltage

8/5/2017

It is necessary to obtain short circuit current when normal rated voltage is applied to the motor, this is practically not possible.

But from the reduced voltage test results it is possible to find current I_{SN} which is short circuit current when normal voltage is applied.

∴

$V_L =$ normal rated voltage (line value)

$V_{sc} =$ reduced short circuit voltage

then
$$I_{SN} = I_{sc} \times \left(\frac{V_L}{V_{sc}} \right)$$

Now power input is proportional to the square of the ~~use~~ current

$$W_{SN} = \left(\frac{I_{SN}}{I_{sc}} \right)^2 \times W_{sc} \quad \text{watts}$$

$W_{SN} =$ core losses + stator copper loss

+ Rotor copper loss

→ Construction of circle diagram :-

Reqd to

By using the data obtained from no load and blocked diagram

circle diagram can be constructed using following steps -

1) Take reference phasor V as reference

axis

2) Select suitable current scale such that the diameter of the circle

is 20 - 30 cm

From no load test I_0 and ϕ_0 are obtained

3) Draw vector I_0 , lagging V

by an angle ϕ_0 . This is done

$$0^{\circ} \text{ below } \left(\frac{90^{\circ}}{2\pi} \right) = 0^{\circ}$$

a) Draw horizontal through extremity of I_o i.e., at 0° , parallel to x axis.

b) Draw the current I_{sc} I_{sn} calculated from I_{sc} with the same scale lagging $\sqrt{3}$ by an angle ϕ_{sc} from the origin O .

This is phase OA .

c) Join $O'A$ called the output line.

d) Draw a line bisector of $O'A$ intended to meet the line drawn till to x axis at point C . This is the centre of the circle.

e) With C as centre radius = $O'C$ draw the semi circle which meets the horizontal line p ~~parallel~~ drawn to x axis at point B .

f) Draw a line from point A on the x axis to be $O'B$ at point F and D the x axis at point B .

g) Construction of tangent line.

~~benefits~~

- Construction of torque line
- length AD represents the power input at short circuit M_{SN}
- Now FD represents iron losses
∴ length of (AP) \propto (stator cu loss + Rotor cu loss)

Then point E can be located as follows

(ii) slip ring IM

In slip ring IM stator and rotor currents can be measured using ammeters

If I_1 = stator current

and I_2 = rotor current

$K = \frac{I_1}{I_2}$ - transformation ratio

∴ Assuming O'E represents the torque line


$$\text{Now } \frac{AE}{EF} \Rightarrow \frac{\text{motor cu loss}}{\text{stator cu loss}} = \frac{I_2^2 R_2}{I_1^2 R_1}$$

$$= \frac{R_2}{R_1} \left(\frac{I_2}{I_1} \right)^2 = \frac{R_2}{R_1} \times \frac{1}{K^2}$$

$$= \frac{R_2}{R_1} [R_2 / K^2]$$

Thus point E is obtained by dividing

the line in the ratio R_2 / K^2



(ii) Squirrel cage IM :-

$$\text{stator cu loss} = 3 I_{SN}^2 R_1$$

where I_{SN} is phase value

Neglecting core loss

$$W_{SN} = \text{stator cu loss} + \text{Rotor cu loss}$$

\therefore Rotor cu loss

$$= W_{SN} - \text{stator cu loss}$$

$$= W_{SN} - 3 I_{SN}^2 R_1$$

$$\therefore \frac{AE}{EF} = \frac{W_{SN} - 3 I_{SN}^2 R_1}{3 I_{SN}^2 R_1}$$

Power scale :-

$$\text{Power scale} = \frac{W_{SN}}{U(\text{AD})} \text{ watts/cm}$$

Predicting performance parameters using

circle diagram :-

Let the motor take a current of

OP

using the power scale and voltage
distance, draw performance
parameters on the circle.

- i) Total motor $\eta / P = PT * \text{power scale}$
 ii) Fixed loss = $ST * \text{power scale}$
 iii) Stator cu loss = $RS * \text{power loss}$
 iv) Rotor cu loss = $QR * \text{power loss}$
 v) Total loss = $QT * \text{power scale}$.
 vi) Rotor $\eta / P = PQ * \text{power scale}$
 vii) Rotor $\eta / P = (PQ + QR) * \text{power scale}$
 viii) Slip $s = \frac{\text{rotor cu loss}}{\text{rotor } P / P}$
 ix) $\eta = \frac{PQ}{PR}$
 x) Power factor = $\cos \phi = \frac{PT}{OP}$
 xi) Motor efficiency = $\eta_{\text{motor}} = \frac{PQ}{PT}$
 xii) Rotor efficiency = $\eta_{\text{rotor}} = \frac{PQ}{PR}$

→ Full load condition -

The full load motor η / P is given
on the name plate of the IM
in watt or HP

Calculate the slip and corresponding
no full load output using the
power scale.

from

Extend AD upto upwards, draw
to the distance corresponding to
full load O/P i.e., A'

Draw parallel to the O/P line OA
from A' to meet the circle at
point P

(i) Draw a phasor diagram for a 20 HP,
50 Hz, 3 φ star connected IM with
the following data

(ii) No load test :- 400V, 90 A, 0.2 pf lag

(iii) Blocked motor test :- 200V, 50 A, 0.4 pf lag

Determine the line current, efficiency
and k/f for full load condition from the
phasor diagram.

Soln

$$\cos \phi_0 = 0.2 \quad - \text{no load test} \leftarrow$$

$$\phi_0 = 78.46^\circ, I_0 = 90 A, \cancel{200V}$$

$$\cos \phi_{se} = 0.4$$

$$\phi_{se} = 66.42^\circ, I_{se} = 50 A, \cancel{200V}$$

$$I_{SN} \rightarrow \frac{I_{SC} * V_L}{V_{SC}}$$

$$\approx \frac{50 * 100}{200}$$

$$I_{SN} = 100A$$

$$W_{SC} = \sqrt{3} V_{SC} I_{SC} \cos \phi_{SC}$$

$$\approx \sqrt{3} * 200 * 50 * 0.4$$

$$\approx 6928.020 W$$

$$W_{SN} = A_{vds} \cdot W_{SC} \left(\frac{I_{SN}}{I_{SC}} \right)^2$$

$$= \frac{\cancel{6928.020}}{6928.020} \left(\frac{100}{50} \right)^2$$

$$W_{SN} = \underline{27712.81 \text{ watts}}$$

(or)

$$W_{SN} = \sqrt{3} * V_L I_{SN} \cos \phi_{SC}$$

$$\approx \sqrt{3} * 100 \approx 100 * 0.4$$

$$\approx \underline{27712.81 \text{ watts}}$$

$$\text{Power scale} = \frac{W_{SN}}{I (\text{A.D})}$$

$$= \frac{327712.8 \text{ k}}{8.6}$$

$$= 3222.41 \text{ watts/cm}$$

$$\text{Full load } \alpha P = 20 \text{ HP} = 20 \times 735.5$$

$$= 14710 \text{ W}$$

$$= 14710$$

$$= \underline{6.5 \text{ cm}} = A'$$

$$\alpha (OP) = 6.5 \text{ cm} \times 5 = \underline{32.5 \text{ A}}$$

= full load line current

$\text{P.F.} = \text{power factor} = \cos (\text{angle angle by OP w.r.t Y axis})$

$$= \cos (2\alpha)$$

$$= \underline{0.8746 \text{ lag}}$$

$$\eta = \frac{P_S}{P_S} = \frac{\cancel{P_S}}{\cancel{P_S}} = \frac{407}{557} \approx 100$$

$$= \underline{82.54}$$

$$\text{Slip} = \frac{Q R}{P R} = \frac{0.65}{5.03} * 100$$

$$= \frac{12.22}{100} \% = 0.1222$$

To determine various maximum quantities from generalised stress diagram

To determine various maximum quantities from generalised stress diagram :-

(i) Man O/P :-

Draw a line MN || all O'A which is also tangent to the curve at point M

The man O/P is given by $\sigma_{(MN)}$ at power scale.

(ii) man S.P.-

It occurs on the highest point on the curve i.e., point I

man I/P is given by

$\lambda (LL')$ at power scale.

(ii) Man torque % -

Draw a line parallel to the torque line which is also tangent to the circle at point J.

$\lambda (JK)$ = represents the man torque in synchronous watts at the power scale.

(iii) Man power factor % -

Draw a line tangent to the circle from the origin O meeting the circle at point H.

Drop a line from H on the radius until point I

Then maximum pf = $\cos \angle OHI$

$$(\text{or}) \frac{HI}{OH}$$

Q1) Draw the circle diagram for from no load and short circuit test of a 3 ϕ motor 14.92 kW, 400 V, 6 pole IM with the following test data (line value).

No load :- 400 V, 11 A, 0.2 Pf (lag)

SC test :- 100 V, 25 A, 0.4 Pf (lag)

The motor cu loss at standstill is half the total cu losses.

From the diagram find - line current, slip, efficiency, power factor at full load, max torque.

Tan

$$\cos \phi_0 = 0.2$$

$$\phi_0 = 78.46^\circ$$

$$I_0 = 11 \text{ A}$$

$$\cos \phi_{sc} \approx 0.4$$

$$\phi_{sc} = 66.42^\circ$$

$$I_{sc} \approx 25 \text{ A}$$

May 1994 ~~margin~~ $I_{SN} = I_{SC} \times \frac{V_L}{V_L + 25 \times 10^{-3}}$ with current (12)

test current V_{SC} across load as

$$\text{VOC} = \text{CVR} - \frac{25 \times 10^{-3}}{100} \quad \text{PS} = \text{P}$$

(12) test I_{SC} at $V_L = 110 \text{ V}$ MLI $\phi = 90^\circ$

$$= 100 \text{ A} \quad (\text{current } 110 \text{ V}) \text{ of load}$$

$$W_{SC} = W_{SC} = \sqrt{3} V_{SC} I_{SC} \cos \phi \text{ load on}$$

$$(12) 19.4 \text{ A} \times \sqrt{3} \times 100 \times 100 \text{ V} = 104.32 \text{ W}$$

$$W_{load} = \sqrt{3} \times 100 \times 25 \times 10^{-3} \text{ W}$$

W_{load} is distributed to load in reverse with

reverse angle $= 173.2^\circ$ which is total

May do ~~margin~~ $\frac{\text{margin}}{\text{margin}}$ in margin

$$W_{SN} = \sqrt{3} V_L I_{SN} \cos \phi \text{ load}$$

$$= \sqrt{3} \times 100 \times 100 \times 10^{-3} \text{ W}$$

$$= \underline{2771.2081 \text{ W}}$$

$$\text{Power scale} = \frac{W_{SN}}{W_{AD}} = \frac{2771.2081}{804}$$

$$= \underline{32.9914 \text{ watt/cm}}$$

$$\text{Full load O/P} = 140.92 \text{ kW}$$

~~Ans~~ $\lambda (AA) = \frac{\text{Full load OP}}{\text{Power seas}}$

$$\rightarrow \frac{14.92 \times 10^3}{3299.14}$$

$$= 4.52 \text{ m}$$

$$\lambda (OP) = 6.45$$

$$\phi_e, V_{OP} = \underline{324}, \text{ speed, curv op } (x)$$

$$\text{Hence } \lambda_{op} = \underline{32} \text{ m}$$

$$\text{for } f_9 = 0, A_{95} = 0.8 \text{ kN/m}^2 \text{ for boat } (i)$$

$$\text{for } f_9 = 0, \underline{A_{95}}, V_{op} = -3 \text{ m/s } (ii)$$

$$\text{Max slip } \lambda_{slip} = \frac{QR}{PR} \text{ rotates in same dir}$$

$$= \frac{0.25}{5.2} \text{ or } 0.048 \text{ m/s}$$

$$f_9 = 0.048 \text{ m/s } (iii)$$

$$M = \frac{PQ}{PF} \text{ boat has to go } (iv)$$

$$= \frac{4.45}{5.2} \times 100$$

$$= \underline{82.40\%}$$

$$u(JK) = 8.5$$

$$\rightarrow 8.5 \times 3299.14$$

$$= 28.042.69$$

$$\rightarrow \cancel{28.042}$$

$\rightarrow 28.042$ syn watts

\rightarrow [synchronous
watts]

Q2) 50 KW, 6 poles, 50 Hz, 450 V, 3φ

IM gave the following test results

- (i) No load test :- 450 V, 20 A, 0.15 pf lag
- (ii) S.C. test :- 200 V, 150 A, 0.3 pf lag

The ratio of stator to rotor cu loss
in 5% H. Draw a circle diagram

and determine

- (i) full load current and pf
- (ii) max torque and max power if
- (iii) slip at full load
- (iv) Efficiency on full load

$$\cos \phi_0 = 0.955$$

$$\phi_0 = 50^\circ 81.87^\circ$$

$$\cos \phi_{se} = 0.3$$

$$\phi_{sc} = 72.054$$

$$I_{SN} = \frac{I_{sc} \times V_L}{V_{sc}}$$

$$= \frac{150 \times 450}{200}$$

$$= 337.5 \text{ A}$$

$$W_{sc} = \sqrt{3} N_{se} I_{sc} \cos \phi_1$$

$$= \sqrt{3} \times 200 \times 150 \times 0.3$$

$$= 15,588.45 \text{ W}$$

$$W_{EN} = \sqrt{3} V_L I_{SN} \times 0.3$$

$$= 78916.56 \text{ W}$$

$$\text{power scale} = \frac{W_{EN}}{u(\text{CAD})} = \frac{78916.56}{4.85}$$

$$= 16271.45 \text{ W/cm}$$

Full load o/p \Rightarrow 50 kW

$\eta(AA') \approx$

$$\frac{\text{Stator loss}}{\text{Rotor loss}} = \frac{5}{4} \cdot \frac{4}{5} \cdot \frac{52}{4} \cdot \frac{EF}{AE}$$

$1.025 \approx$

$$1.025 AE \approx EF$$

$$AR = AE + EF$$

$$AF = AE + 1.025 AE$$

$$\Rightarrow 2.025 AE$$

(a) $AE = \frac{AF}{2.025}$

$$= \frac{1.065}{2.025}$$

$$= 0.525 \text{ cm}$$

Power scale $\frac{50 \times 10^3}{16271.45}$

$$= 30.7 \text{ m}$$

MODULE - 5

SYNCHRONOUS

MOTORS


alternator → field winding / rotor windings
→ given DC supply →
single phase
mechanical to electrical energy conversion

synchronous motor (1) generator remains same
↳ working on the principle of magnetic

rotating

Not self starting

$E_m \rightarrow RMF \rightarrow$ synchr speed
from



→ construction of synchronous motor - 3Φ

Two major parts are stator and rotor

motor -

Salient pole motor

Non salient pole motor

If an alternator (3Φ synchronous generator) is run as a motor,

it will rotate at synchronous speed and is called synchronous motor

The speed at which RMP rotates is given by -

$$N_s = \frac{120f}{P} \text{ rpm}$$


Then rotor rotates in same direction as that of RMP (RMP at synchronous speed) $N_1 - N_2 = S_1$ poles get attracted. (magnetically locked)

changing direction of rotor → change the phase sequence RYB

Supply $\left\{ \begin{matrix} R \\ Y \\ B \end{matrix} \right\} \rightarrow \left\{ \begin{matrix} R \\ Y \\ B \end{matrix} \right\} \text{ stator}$

\rightarrow RM

\rightarrow Schematic representation of 3 ϕ synchronous motors :-



90% of motors are salient pole type.

It contains 1 ϕ field winding +
DC supply using slip ring
(DC supply \rightarrow station) \rightarrow rotor (rotating)
 \rightarrow through slip ring

Stator \rightarrow is supplied by 3 ϕ
AC supply and it produces RMF

→ Working principle :-

- Works on the principle of magnetic locking
- To have magnetic locking there must exist two unlike pole and the magnetic axis of the two poles must be brought very close to each other.
- Assume the stator is wound for 2 poles (say) with 50 Hz supply.
- Let these two pole stator poles be N_1 and S_1 , which are rotating at a speed of N_s (e.g. 1000 rpm)
- Assume the direction of rotation of RMF as clockwise.
- Assume the field winding is excited by a DC supply, it also produces two poles, N_2 and S_2 in N_1 and S_1 respectively.
- If these two motor poles

At standstill N_1 & S_1 all rotating
at N_s rpm

N_2 & S_2 all ~~not~~ yet

If by somehow methods N_1 gets attracted
to S_2 and N_2 get attracted
to S_1 then magnetic locking
takes place
and N_2 & S_2 starts rotating at
synchronous speed.

At start/beginning when mechanical
load is applied momentarily it
get reduced and still maintains
synchronous speed

Synchronous motor will never rotate

In any other speed other than
synchronous. (It is effect of RMF
that is considered as 2 pole N_1 & S_1)


⇒ Synchronous motor is not self
starting.

Consider the RMF is equal
numerical value N_1 and S_1


and are at a position where
stator magnetic axis is vertical

i.e., along A-B

At this instant, the rotor
poles are arbitrarily positioned, at
this instant motor is stationary
and with unlike poles will try
to attract each other.




case (ii) :-



Due to this the motor gets subjected to an instantaneous torque in clockwise direction.

Case (ii) :-



To start a synchronous motor:-

Suppose the motor is rotated by some external means at a speed almost equal to synchronous speed and then motor is excited to produce the poles. At a certain instance, the stator and motor poles will face each other and then there is a force of attraction between the stator and motor and pulls both of them into magnetic locking condition.

The external device used to rotate the motor near synchronous speed can be removed once synchronisation / magnetic locking takes place.

Methods of starting synchronous motor :-

- 1) Using pony motor :-
- 2) Using damper winding :-
- 3) As a slip ring IM :-
- 4) Using small DC motor machine :-

1) Using Pony motor :-

In this method, the motor of synchronous motor is brought to synchronous speed with the help of a small internal IM called pony motor.

Once synchronisation is established, the pony motor is decoupled / removed.


2)

Wing damper winding :-

In this method, in addition to the normal field winding (or vector winding), an addition winding consisting of U bars are placed in the slots in the pole face.

The bars are short circuited with the help of end rings.

Such an additional winding is called damper winding.



Damper \rightarrow Pole phase rotor

The synchronous motor works as

IM Initially (At start)

- supply - 3 ϕ \rightarrow stator \rightarrow RMF \rightarrow

RMF \rightarrow in produced and cuts
vector windings (DC is not supplied)

and this RMF \rightarrow current \rightarrow
produced \rightarrow emf is induced \rightarrow
current is produced \rightarrow Induced
current \rightarrow Dampen
winding

- 1) current \rightarrow (i) RMF
- (ii) Dampen winding current

Thus due to interaction of 2 forces

motor stalls rotating at speed

less than synchronous speed

— IM motor action

(No N)
(less synchronous)

one DC supply is on motor

stalls rotating at synchronous
speed and action synchronous

(is mounted on same
motor)

\hookrightarrow so Dampen winding is rotating
in same synchronous speed

so there is change in

At start total in station

Damper winding in stationary bugs
RMF in rotating

6

- Same $N_2 - S_1, N_1 - S_2$ magnetic working — synchronous speed
→ rotor does not stop
→ then motor action stops and synchronous action continues.
→ no flux is induced —



- At start, the RMF cuts the stationary damper winding which is placed in the rotor slots.
- Thus emf gets induced in the damper winding — then
- Once ~~if~~ in running condition, one synchronisation / magnetic locking takes place, the induced emf in the damper winding becomes zero because after magnetic locking the motor will rotate at synchronous

speed N_s which is same as R.M.F.

- { Dumper motor winding all placed on the slots in the winding slots]
- { Dumper winding operation remains same initially as that of squirrel cage in (or) short circuited rotor]
 - Starters has to be removed to start

3) As a slip ring $1M\%$ -

- In the dumper winding method it is difficult to achieve high starting torque.
- To achieve high torque instead of shorting the dumper winding, it is designed to form a 3ϕ star or delta connected winding.
- The 3 ends of this winding are brought out through slip rings.



- At start
TPDT in start position
 (i) It acts as stop plug IM
 Here starting torque can be varied by
 varying starting resistance
 (ii)
 same steps as previous one IM
 but stop plug connected to variable
 resistance to get high starting

4) Using small DC machine :-

- Usually large synchronous motors we use a DC motor machine.
- This machine is used as a DC motor to rotate the rotor of the synchronous motor at synchronous speed.
- Once motor starts running as a synchronous motor, the same DC machine acts a DC generator and excites the field winding of synchronous motor.

one synchronous motor attains synchronous speed if it is used as synchronous generator.

Unstated previous question
for this question

if the motor is to operate most efficient at full load first give load torque and then at no load

→ Behaviour of synchronous motor on loading

Observation :- Ideal conditions or neglect :-

In 3^Ø AC motor

emf induced in stator \rightarrow back emf

emf \rightarrow this is called back emf
of the IM - it is used to
create poles

\hookrightarrow Current from rotor (DC supply winding)

cuts the stator (3^Ø supply winding)

and emf is induced in the stator

\rightarrow Back emf \rightarrow PMS

This emf induced after motoring

of motor i.e.; as a generating action
into machine in the stator & winding

is called back emf of 3^Ø IM;

Consider a DC shunt motor where
voltage v_m is given by

$$V = (E_b) + I_a R_a$$
$$(s.t) \text{ m.m.f}$$

$$E_b = V - I_a R_a$$

$$E_b = \frac{P \phi N Z}{60 A}$$

E_b > back emf, induced
emf in a dc motor due to
generating action

Similarly in synchronous motor,
there is an induced emf in the 3Φ
stator winding due to alternation
action (or synchronous auto generator)

after magnetic working takes place

This induced emf is known as
back emf of a synchronous
motor whose magnitude is given

$$E_{bph} = K_e N \Phi T_p n \text{ in Volts}$$

where $K_e = \pi s (\lambda/2)$

$$K_d = \frac{\pi s n (m\lambda/2)}{m \sin (\theta/2)}$$

$$\therefore \boxed{E_{bph} \propto \phi}$$

As the speed ω is always synchronous
 (N.S) frequency is constant and
 Hence magnitude of back emf can
 be controlled by flux ϕ produced
 by the motor.

Let R_a = stator winding resistance
 and X_s = synchronous reactance of
 the stator

then synchronous impedance of the motor
 is given by -

$$Z_s = R_a + j X_s \quad \Omega / \text{ph}$$

Thus similar to a D.C. motor, voltage
 equation for a synchronous motor

can be written as

$$\vec{V}_{ph} = \vec{E}_{bph} + \vec{I}_{aph} Z_s$$

$$\vec{I}_{apn} = \frac{\vec{V}_{pn} - \vec{E}_{bpn}}{Z_s}$$

Amps


- \hookrightarrow (i) Ideal condition on no load :-

Magnitude of E_{bpn} is made almost equal to V_{pn} by controlling the flux produced by field winding.

Thus for ideal condition on no load, neglecting various losses

$$V_{pn} = E_{bpn}$$

Under this condition the magnetic locking between stator & rotor is in such a way that the magnetic fluxes of both coincide with each other.



(a) Ideal condition with no load

The magnitudes of ~~E_{ph}~~ E_{ph} and V_{ph}

are equal but they are in
opposite direction Henry's law

$$E_{ph} \leftarrow V_{ph} \rightarrow$$

$$|E_{ph}| = |V_{ph}|$$

~~W.K.T~~
W.K.T

$$I_{ap} = \frac{V_{ph} - E_{ph}}{Z_s}$$

$$\vec{I}_{\text{app}} = \frac{\vec{O}}{E_s} = \frac{\vec{O}}{Z_s}$$

$$\vec{I}_{\text{app}} = \underline{\underline{0}}$$


In practicals current cannot be zero and the motor has to supply mechanical and iron losses under no load condition.

To produce the torque required to overcome these losses - the motor draws current from the supply.

- \rightarrow iii) On no load (with losses): -


Due to various losses present practically in a motor on no load, the magnetic working units between the stator and rotor but in such a way that ^{they} creates a small angular difference b/w the air gap of 2 magnetic fields.

- The rotor magnetic axis falls back with respect to stator magnetic axis by an angle ' s ' (delta)
- This angle decides the amount of current required to produce torque to supply various losses and this angle is called as load angle or power angle or coupling angle or torque angle or angle of retardation.



greater angle (s)
(above $s \geq 90^\circ$)
speed is stopped

magnetic locking is less
and synchronous
currents flow into



phasor diagram for no load with losses

$$|V_{ph}| = |E_{ph}|$$


$$\bar{V}_{ph} - \bar{E}_{ph} = \bar{I}_a Z_s = \bar{E}_{Rph}$$

This resultant \bar{E}_{Rph} decides the amount of current i.e., \bar{I}_{apn} to be drawn from the supply to produce voltage to pass which meets the various losses under no load condition & is very small and hence \bar{E}_{Rph} is also very small.


• \rightarrow (iii) Synchronous motor on load

As the load on the synchronous motor increases there is no change in its speed but load angle δ gets affected.

Hence if the load increases, δ increases but speed remains synchronous.




$$\boxed{\delta_2 > \delta_1}$$



MODULE - 5 [continuation]

Torque angle characteristics :-



as load on synch motor increases
if also increases beyond 90° magnetic locking in
motor comes out of synchronisation
and no torque

Enquiry 7: In a synchronous

→ Types of torques in a synchronous motor: -

1) Starting torque :-

- : DFL behavior developed by SM (synchronous motor) at start when rated voltage is applied to the motor, it is also called break away torque

2) Running torque :-

Torque developed by the motor under running condition.

It is decided by the output rating of the motor and speed

3) Pulling torque :-

when the speed of the motor is near synchronous speed

The amount of torque developed by the motor at the time of pulling into synchronisation is called ~~synchr~~ pulling torque.

- 4) Pull out torque (maximum torque) :-
 Maximum torque developed by the SM without pulling out of synchronisation is called pull out torque.
 (at $\theta = 90^\circ$)



Analysis of phasor diagram :-

Consider a phasor diagram with ~~normal excitation~~ ~~normal magnet~~
normal ~~excitation~~ ~~magnet~~

$$|E_{bpn}| \rightarrow |V_{pn}|$$

$$|E_{bpn}| = |V_{pn}|$$

$$|Z + jX| = |Z_X|$$



$$\rightarrow \bar{V}_{pn} - \bar{E}_{bpn} = \bar{E}_{Rph}$$

$$\Rightarrow \bar{V}_p - \bar{E}_{ph} = \frac{\bar{I}_a}{\bar{Z}_s}$$


$$Z_s = R_a + j X_s \quad \Omega / ph$$

R_a → stator resistance per Rph phase

X_s → synchronous reactance of stator per phase

$$|Z_s| = \sqrt{R_a^2 + X_s^2}$$

phasor diagram under normal working condition



$$\theta = \tan^{-1} \left(\frac{X_a}{R_a} \right)$$

The angle θ is called impedance angle or internal machine angle.

Practically R_a is very small

compared to X_a [NOT synch.]

X_a = reactance of stator

Hence θ tends to 90°

operation of synchronous motor
at a constant with variable
excitation :-

when the load changes, for a
constant excitation, current drawn
 by the motor increases

But if the excitation (field
 current I_f) is changed keeping
 the load constant, SM meets

by changing its power factor

of operation.

Types of excitation :-


- 1) Normal excitation
- 2) Under excitation
- 3) Over excitation
- 4) Critical excitation

10%
0%


m

S.No No°	Excitation	Power factor	Relationship
1)	Normal excitation	lagging P_f	$E_{bph} = V_{ph}$
2)	Critical excitation	unity P_f	$E_{bph} \approx V_{ph}$
3)	Over excitation	leading P_f	$E_{bph} > V_{ph}$
4)	Under excitation	lagging P_f	$E_{bph} < V_{ph}$


23/2




1) Normal
mutation




- Normal Excitation
 $E_{ph} = V_{ph}$
 I_a constant



- Under Excitation
 $|E_{ph}| < |V_{ph}|$
 $(\phi \text{ is greater than } 90^\circ)$
 I_a decreases



- Over Excitation
 $|E_{ph}| > |V_{ph}|$
 $(\phi \text{ is less than } 90^\circ)$
 I_a



- Critical Excitation
 $E_{ph} \approx V_{ph}$
 unity power factor

I_a less/decreases

V and inverted V curves of synchronous motor:-

motor:-

can be increased

- The emf is increased by increasing the

field current passing field winding

of the synchronous motor

- If the graph of armature current

drawn by the motor (I_a) against

field current (I_f) is plotted, then

its shape looks like an

English alphabet 'V'

- If such graphs are obtained at various excitation/load conditions, we get

a family of waves called V


waves of synchronous motor

$E_a = \Phi N$

Φ


$E_a = \Phi N$

$E_a = \Phi N$





If the power factor ($\cos \phi$) is plotted against field excitation current (I_f) then the shape of the graph looks like a inverted V.

Such curve obtained at various load / excitation conditions are called inverted V curves of synchronous motor.



→ Experimental ~~set~~ setup :-





Tabular column → decrease angle between currents ← angle between voltages

Sl. No:	V_r (volts)	I_a (amps)	I_f (amps)	w_1 (watts)	w_2 (watts)	$\cos\phi$ constant $\left(\frac{\sqrt{3}(w_1-w_2)}{w_1+w_2}\right)$

$$\cos\phi = \cos \left[\tan^{-1} \frac{\sqrt{3}(w_1-w_2)}{w_1+w_2} \right] \quad \left[\phi = \tan^{-1} \frac{\sqrt{3}(w_1-w_2)}{w_1+w_2} \right]$$

→ Switch off on AC supply + then use
(pump, damper, DC motor, 1φ IM, fan pump etc,
de-magnetise) ~~not~~ motor
one motor starts station supply
DC field

poles all create

b pole $N_1 S_1, N_2 S_2$

magnetic locking

Vary Rhostat \rightarrow vary I_f
and not down various values

of I_a, w, w_2, V_L

[E_{app} is for inverted V curves]

→ Expression for back emf (E_{app})

For under excitation	E_{app}	V_{ph}

$$E_{app} \propto V_{ph}$$

$$Z_s = R_a + j X_s$$


(or)

$$Z_s = |Z_s| L \theta$$

$$R_1 ph$$

where

$$\theta = \tan^{-1} \left(\frac{X_s}{R_a} \right)$$



$$X = \theta - \phi$$

E_{Rph} $E_{Rph} = I_a Z_s$ volts

angle b/w E_{Rph} and V_{ph} = θ

angle b/w V_{ph} and I_{apn} = ϕ

applying cosine rule to triangle OAB

$$(E_{Rph})^2 = (V_{ph})^2 + (E_{Rph})^2 - 2 V_{ph} E_{Rph} \cos(\text{angle b/w } V_{ph} \text{ & } E_{Rph})$$


$$(E_{Rph})^2 = (V_{ph})^2 + (E_{Rph})^2 - 2 V_{ph} E_{Rph} \cos(X)$$

$$(E_{Rph})^2 = (V_{ph})^2 + (E_{Rph})^2 - 2 V_{ph} E_{Rph} \cos(X)$$

$$(E_{bph})^2 = (V_{ph})^2 + (E_{Rph})^2 - 2 V_{ph} E_{Rph} \cos(\theta - \phi)$$

where $\bar{E}_{Rph} = \bar{I}_{ph} Z_s$

Applying



$$\frac{E_{bph}}{\sin \chi} = \frac{E_{Rph}}{\sin \delta}$$

i.e.,


$$\frac{E_{bph}}{\sin(\theta - \phi)} = \frac{E_{Rph}}{\sin \delta}$$

$$\sin \delta = \frac{E_{Rph} \times \sin(\theta - \phi)}{E_{bph}}$$

- $\rightarrow 2)$ over saturation :-

$$E_{bph} > V_{ph}$$

$$E_{bph} = (E_{Rph}) + (V_{ph}) = (E_{Rph})$$



$$x = \theta + \phi$$

∴ ~~no other rule for all ΔABC~~

→ Applying cosine rule

$E_{R.P.}$

$$(E_{B.P.H.})^2 = (V_{ph})^2 + (E_{R.P.H.})^2 - 2 V_{ph} E_{R.P.H.} \cos(\text{angle between } V_{ph} \text{ and } E_{R.P.H.})$$

$$(E_{B.P.H.})^2 = (V_{ph})^2 + (E_{B.P.H.})^2$$

$$- 2 V_{ph} E_{R.P.H.} \cos(\text{angle between } V_{ph} \text{ and } E_{R.P.H.})$$

$$(E_{B.P.H.})^2 = (V_{ph})^2 + (E_{B.P.H.})^2 - 2 V_{ph} E_{R.P.H.} \cos(x)$$

$$(E_{B.P.H.})^2 = (V_{ph})^2 + (E_{B.P.H.})^2 - 2 V_{ph} E_{R.P.H.} \cos(180^\circ + \phi)$$


→ Applying sine rule to ΔOAB

$$\frac{E_{B.P.H.}}{\sin x} = \frac{E_{R.P.H.}}{\sin \delta}$$

$$\sin \delta = \frac{E_{R.P.H.} \times \sin(\theta + \phi)}{E_{B.P.H.}}$$

→ 3) Critical initiation :-

$$E_{bph} \approx V_{ph}$$



$$\left[\because \phi = 0 \right]$$

→ Apply cosine rule

$$(E_{bph})^2 = (V_{ph})^2 + (E_{Rph})^2 -$$

- $2 V_{ph} E_{Rph} \cos(\text{angle b/w } E_{Rph} \text{ and } V_{ph})$

\bar{E}_p

$$(E_{bph})^2 = (V_{ph})^2 + (E_{Rph})^2 - 2 V_{ph} E_{Rph} \cos(X)$$

$$(E_{bph})^2 = (V_{ph})^2 + (E_{Rph})^2 - 2 V_{ph} E_{Rph} \cos(0)$$

→ Apply KVL

$$\frac{E_{bph}}{\sin \theta} = \frac{E_{ph}}{\sin \delta}$$

$$\sin \delta = \frac{E_{ph} \times \sin \theta}{E_{bph}}$$

→ In general

$$(E_{bph})^2 = (V_{ph})^2 + (E_{Rph})^2 - 2 V_{ph} E_{Rph} \cos(\theta \pm \phi)$$

- ↑
+ → over excitation → leading pf
- → under excitation → lagging pf

Q1) A 2300V, 3φ, star connected SM

has a resistance of 0.2Ω / ph and
a synchronous reactance of 2.2Ω / ph

The motor is operating at 0.5 pf lead

with a line current of 200A.

Determine the value of generated
emf per phase

Sohn

$$V_L = 2300 \text{ V}$$

$$R_a = 0.2 \Omega/\text{ph}$$

$$X_S = 2.2 \Omega/\text{ph}$$

$$Z_d = R_a + j X_S$$

$$= 0.2 + j 2.2$$

$$\cos\phi = 0.5 \cdot \text{real}$$

$$I_L = 200 \text{ A} = I_a$$

$$E_{ph} = ?$$

$$M_2 \quad V_{ph} = \frac{V_L}{\sqrt{3}} = \frac{2300}{\sqrt{3}} \text{ V} = 1327.90 \text{ V}$$

Die Phasenverschiebung ist gleich der Winkel ϕ zwischen I_a und I_L .

$\cos \phi = \frac{1}{\sqrt{3}} = 0.577 \approx 60^\circ$ ist der Winkel zwischen I_a und I_L .

Der Winkel ϕ zwischen E_{ph} und V_{ph} ist gleich dem Winkel zwischen I_a und I_L .

$$I_{ph} = \frac{I_a}{\sqrt{3}} = \frac{200}{\sqrt{3}} \text{ A} = 115.47 \text{ A}$$

Die Phasenverschiebung ϕ zwischen E_{ph} und V_{ph} ist gleich dem Winkel zwischen I_a und I_L .

$$Z_S = 0.2 + j 2.2 \Omega$$

$$= 2.2 \angle 84.0^\circ \Omega$$

$$|Z_S| = 2.2 \Omega$$

$$\phi = 84.0^\circ$$

$$\rightarrow \cos \phi = 0.5 \text{ note } (\phi = 60^\circ) \text{ on A (B)}$$

$$\phi = 90^\circ - 60^\circ = 30^\circ$$

Previous working

$$\text{Notes: } \phi = 60^\circ \text{ star connect}$$

$\phi = 30^\circ$

$$I_{ph} = I_u$$

$$\rightarrow \text{output Energy} = \underline{\underline{I_{ph} Z_s}}$$

$$\text{Working ph: } = 200 \times 20.2 \text{ with star point}$$

$$I_{ph} = \frac{I_u}{\sqrt{3}}$$

$$\text{to previous} = \underline{\underline{1680 \text{ volts}}}$$

$$\rightarrow (E_{ph})^2 = (V_{ph})^2 + (E_{Rph})^2 - 2 V_{ph} E_{Rph} \cos(\theta + \phi)$$

$$\rightarrow (1327.9)^2 + (1680)^2 - 2 (1327.9)(1680) \cos(184.8 + 60)$$

$$E_{ph} = \sqrt{279 + 387.77} = 2911.794.71$$

$$V_{ph} = 1680$$

$$E_{ph} = \underline{\underline{1670.74 \text{ volts}}} \quad Z_s = R + jX_s$$

$$= Z_s L$$

$$E_{ph} = \underline{\underline{1706.39 \text{ volts}}}$$

$$E_{ph} = \underline{\underline{I_{ph} Z_s}}$$

$$E_{ph} = E_{Rph} + V_{ph} - 2V_{ptb} \cos(60^\circ)$$

$$\theta =$$

$$0.86 \times \phi$$

$$0.86 \phi$$

(Q2) A 400 V, 3φ, start connected SM has an armature resistance of 0.2Ω /ph and synchronous reactance of 2.0Ω /ph, when during a certain load, it takes 25A from supply.

iii) calculate the back emf induced if the motor is working at

$$(i) 0.8 lag \rightarrow 200.5 \text{ V}$$

$$(ii) 0.9 mod \rightarrow 252.5 \text{ V}$$

$$(iii) UPF \rightarrow 231.38 \text{ V}$$

Soln $Z_s = 0.2 + j2$

$$Z_s =$$

$$Z_s = 2 L 84.28$$

$$= |Z_s| L \theta$$

$$\theta = 84.28$$

$$\rightarrow \cos \phi_1 = 0.8$$

$$\phi_1 = 36.86$$

$$\rightarrow \cos \phi_2 = 0.9$$

$$\phi_2 = 25.84$$

$$\rightarrow \phi_3 = 0$$

$$E_{Bph} = I_a Z_s$$

~~E_{Bph}~~ = ~~$I_a Z_s$~~ \rightarrow ~~$25 \text{ A} \times 2$~~ \rightarrow ~~50 V~~ \rightarrow ~~230.94~~ \leftarrow

(i) $(E_{Bph})^2 = \left(\frac{400}{\sqrt{3}}\right)^2 + (50)^2 - 2 \times \frac{400}{\sqrt{3}} \times 50 \times \cos(84.28 - 36.86)$

$$\underline{E_{Bph1} = 200.05 \text{ V}}$$

(ii) $(E_{Bph})^2 = (230.94)^2 + (50)^2 - 2 \times 230.94 \times 50 \times \cos(84.28 + 25.86)$

$$\underline{E_{Bph2} = 252.05 \text{ V}}$$

(iii) ~~$(E_{Bph})^2$~~ $(E_{Bph})^2 = (230.94)^2 + (50)^2 - 2 \times 230 \times 50 \times \cos(84.28)$

$$\underline{\underline{E_{Bph3} = 231.038 \text{ V}}}$$

26/5/2017 Hunting in synchronous motor :-

Hunting of synchronous motor :-


- Due to inertia of the motor it cannot achieve its final position instantaneously when the motor is loaded.
- There is periodic swinging of the motor on both sides of the new equilibrium position, corresponding to the load such oscillations of the motor about its new equilibrium position, due to sudden application or removal of load is called swinging or hunting in synchronous motor.

→ use of damper winding to prevent hunting :-

- when the rotor starts oscillating i.e., when hunting starts, a relative motion b/w damper winding and RMF gets created due to emf induced in the damper winding.
According to Lenz's law this emf in the damper opposes hunting thus hunting is minimised due to damper winding.

No primary current waveform
is better if ($\text{avg} < \text{rms}$)

No resonance
no higher
waveshape
waveshape



→ Synchronous condenser :-

- A synchronous motor running on no load when over excited ($E_{0ph} > V_{ph}$) is called a synchronous condenser or synchronous capacitor.

- Under such condition, the current I_A will lead the voltage (V_{ph}) by an angle almost equal to 90° : (iii) ~~110~~
- This is ^{an} ~~in~~ property due to which synchronous motor are used as power factor improvement due to phase advance.

→ Disadvantages of low power factor:-

* Single phase power

$$P = V I \cos \phi$$

for ϕ was at ~~sub~~ ~~near~~ ~~near~~ ~~NPH~~

$$I = \frac{P}{V \cos \phi}$$

- Let $P = 5 \text{ kW}$ and $V = 230V$

would

(a) (i) :-

$$\text{Power} = V \cdot I \cdot \cos \phi$$

$$P_f = 0.8$$

(a) (ii) :-

$$\cos \phi = 0.6$$

voltage
regulation
per cent
efficiency

$$(i) \text{ MVA} = \frac{5 \times 10^3}{230 \times 0.8}$$

$$= \underline{27.17 \text{ A}}$$

$$(ii) \text{ I} = \frac{5 \times 10^3}{230 \times 0.6}$$

$$= \underline{36.23 \text{ A}}$$

for any machine
PF should be high
so current drawn
by the motor
should be less

* High current due to low PF has
the following disadvantages -

* The conductor size should be more
increase which increases the
loss

* More copper losses and less
efficiency

* Large current causes large voltage drop in transmission lines and this results in poor regulation

*

$$VI \cos \phi = \text{Active power}$$

$$\cos \phi = \frac{\text{Active power}}{VI}$$


$$\Rightarrow \frac{\text{Active power}}{\text{Apparent power}}$$

$$P_f \cos \phi = \frac{Kw}{KVA}$$

If the pf is low then KVA rating of the equipment of ch high which increases the cost.

→ Use of synchronous condenser improvement -

Q.1)



as $\phi_T \downarrow \rightarrow \cos\phi_T \uparrow \rightarrow Pf \uparrow$

Explanation

(own)

Note :-


such P_f correction equipment
is connected
across the supply
with (syn condensers)

Q1) A synchronous motor developing 20 kW is connected in parallel with factory load of 200 kW at pf of 0.8 lag. If the total load connected to the supply has a pf of 0.92 lag what is the value of reactive power drawn by the motor and at what pf is it operating?

Soln

Given :-

$P_1 = \text{factory load } 200 \text{ kW}$
 $\cos \phi_1 = 0.8 \text{ lag}$



Soln

$$\cos \phi_1 = 0.8$$

$$\phi_1 = 36^\circ 86'$$

prigadebiti rotam varavimis A (1)

$$\tan \phi_1 = \frac{Q_1}{P_1} \quad \text{at} \quad \text{WY} \quad \text{je}$$

WY 006 β boat μ glesj WY

$$Q_1 = P_1 \tan \phi_1$$

$$\text{WY} \cdot \text{ft} \cdot \text{pol} \cdot 8 \cdot 0 \quad \text{for} \quad \text{P} \cdot \text{ft} \cdot \text{ft}$$

$$\text{WY} \cdot \text{ft} \rightarrow 200 \cdot 10^3 \cdot \tan 36 \cdot 8 \cdot 0$$

$$\text{Pd} \cdot \text{ft} \cdot \text{ft} \quad Q_1 = 150 \text{ kVAR} \quad (\text{real power})$$

WY β $\underline{\text{WY}}$ drawn by factory load

four synch motor


! prigadebiti β Pd WY WY

$$P_2 = 20 \text{ kW} \quad \text{for} \quad \text{load} \quad \text{to} \quad \text{WY}$$

$$\cos \phi_T = 0.92$$

$$\phi_T = 23.07^\circ$$

$$\text{Pd} \cdot \text{ft} \cdot \text{ft} = \phi \text{WY}$$



$$\therefore P_T = P_1 + P_2$$

$$= 200 + 20 \quad \text{for} \quad \phi \text{WY}$$

$$= 220 \text{ kW}$$

$$Q_T = P_T \tan \phi_T$$

$$= 220 \times 10^3 \times \tan 23.07$$

$$Q_T = 93.70 \text{ KVAR}$$

~~Factor symmet~~ \Rightarrow ~~so symmet~~

$$\therefore Q_1 + Q_2 = Q_T$$

$$Q_2 = Q_T - Q_1$$

$$= 93.7 - 150$$

$$Q_2 = -56.3 \text{ KVAR}$$

$\xrightarrow{-ve sign indicated reading power}$

The reactive power drawn by the motor is -56.3 KVAR

and -ve sign indicates SH
leading nature

$$\tan \phi_2 = \frac{Q_2}{P_2}$$

$$\phi_2 = \tan^{-1} \left(\frac{Q_2}{P_2} \right)$$

$$= \tan^{-1} \left(\frac{-56.3 \text{ kN}}{20 \text{ kN}} \right)$$

$$\phi_2 = \underline{\underline{-70.44^\circ}}$$

$$\therefore \cos \phi_2 = \cos (-70.44^\circ)$$

$$= \underline{\underline{0.33^\circ \text{ modph}}}$$

Buondel diagram

BD ~~is~~ of a SM is an extension of simple phaser of ~~synchronous~~ motor simple phaser for synchronous motor

$$P_{in} = V_{ph} I_{ph} \cos\phi$$

$$\text{Copper loss} = (I_{ph})^2 R_a$$


$$P_m = P_{in} - P_{cu}$$

$$P_w = V \cdot I \cos\phi - I_a^2 R_a$$

$$I^2 R_a - V I \cos\phi + P_m = 0$$

$$I^2 - \frac{V I \cos\phi}{R_a} + \frac{P_m}{R_a} = 0$$

① represents polar view of a circle to this, and draw a line at angle θ



The circle drawn with centre at O' and radius $O'B$ represents circle of constant power.

This is called constant power.

This is called Blondel diagram.

- if inclination is varied while the power is kept constant the work done working then point B while moving along the circle of constant power

$$\text{Punman} \rightarrow \frac{V^2}{4 \pi R_0}$$